

## Orkney Coaches: Fleetlist, 31 January 2006

1

001	SMH	<b>HRO 2Y</b>	MB O814D	WDB6703742N064877	Pn	978.5MXV4877	B31F	Aug-97	Rapson (SN)	Jun-05	R937 AMB
002	KW	<b>KKZ 5534</b>	MB 814L	6742142K124821	Buscraft		C35F	Aug-96	Rapson (SN)	Jun-05	P 65 HBG
003	SMH	<b>WIB 7085</b>	MB O814D	WDB6703742N074512	Pn	988.5MXV8386	B31F	Oct-98	Rapson (SN)	Jun-05	S533 UPV
004	KW	<b>PIL 6829</b>	MB O814D	6703732N061894	Pn	977.8MWW6418	B31F	Mar-97	Rapson (SN)	Jun-05	P698 HND
006	SMH	<b>YJ 05 XOA</b>	Oe M920	001907	Oe		B31F	May-05	Rapson (SN)	Jun-05	
013	KW	<b>YJ 05 XOH</b>	Oe M???	002032	Oe		B35F	Jun-05	Rapson (SN)	Jun-05	
014	KW	<b>YJ 05 XOK</b>	Oe M???	002033	Oe		B35F	Jun-05	Rapson (SN)	Jun-05	
015	KW	<b>YJ 05 XOM</b>	Oe M920	002034	Oe		B29F	Jun-05	Rapson (SN)	Jun-05	
016	KW	<b>YJ 05 XOL</b>	Oe M920	001824	Oe		B31F	Jun-05	Rapson (SN)	Jun-05	
036	KW	<b>K247 MOS</b>	Ta HDB30R	0002060	Co	251071	C21F	Apr-93	Rapson (SN)	Jun-05	K500 WCM
037	KW	<b>M487 WAS</b>	MB 811D	670303-2N-030662	ArB	M43.01	B33F	Apr-95	Rapson (SN)	Jun-05	
039	wdn	<b>N 11 JDP</b>	Fd Tt	BDVESY26575	Fd		M14	Aug-95	Highland Country (SN) 039	by8/05	
079	KW	<b>N108 WRC</b>	MB 811D	670303-2N-035904	Pn	958.5MLV4550	B30F	Dec-95	Rapson (SN)	Jun-05	
080	KW	<b>N101 WRC</b>	MB 811D	670303-2N-023845	Pn	958.5MLV4552	B30F	Dec-95	Rapson (SN)	Jun-05	
081	KW	<b>N102 WRC</b>	MB 811D	670303-2N-029763	Pn	958.5MLV3627	B30F	Nov-95	Rapson (SN)	Jun-05	
099	KW	<b>YN 03 UYJ</b>	Oe Alero	SAB2100000000323	Oe		C14F	May-03	Rapson (SN)	Jun-05	
140	wdn	<b>TGD 759W</b>	Vo B58-61	016516	VH	9636	C50F	Mar-81	Rapson (SN)	Jun-05	TGD 759W, WNR 536, WIB 7085
141	wdn	<b>NST 61Y</b>	Bd YNT	DT102422	Pn	8311NTP1C040	C53F	Mar-83	Rapson (SN)	Jun-05	HRO 2Y
144	SMH	<b>C663 EHU</b>	Vo B10M-61	012115	Du	8593/0039	C55F	Jul-86	Rapson (SN)	Jun-05	UFX 567, C663 EHU, PIL 6829
402	wdn	<b>HDZ 5417</b>	Vo B58-56	15599	Du	048/6071	C53F	Aug-80	Rapson (SN)	Jun-05	MPS 970W, FSU 718, MPS 970W
403	KW	<b>JAZ 9858</b>	Sca K93CRB	1814792	Pn	8912SFA1030	C57F	Sep-89	Rapson (SN)	Jun-05	G803 RNC
408	KW	<b>JAZ 9859</b>	Vo B10M-60	23626	Pn	9012VCB1625	C44FT	Feb-90	Rapson (SN)	Jun-05	G813 BPG
411	ST	<b>KPS 701T</b>	Bd YLQ	JW451717	Pn	7910QX503	C45F	Jan-79	Rapson (SN)	Jun-05	
413	KW	<b>JAZ 9856</b>	Sca K93CRB	1815111	Pn	8912SFA1027	C49FT	Jul-89	Rapson (SN)	Jun-05	F431 GWG
416	KW	<b>RXW 982</b>	Vo B10M-61	12495	Pn	8712VMH3C829	C49FT	Mar-87	Rapson (SN)	Jun-05	D783 SGB, PSU 630, D783 SGB
419	ST	<b>PVS 20W</b>	Bd YMQ	KW453771	Du	050/1560	C35F	Sep-80	Rapson (SN) 419	Jun-05	
437	ST	<b>JIL 5809</b>	Bd YMP	DT103719	Pn	8310MQP1C003	C45F	May-83	Rapson (SN)	Jun-05	XVN 501Y
439	KW	<b>JAZ 9850</b>	Vo B10M-61	7392	VH	11555	C52FT	Jun-84	Rapson (SN)	Jun-05	A639 EJS, 1983 NT, A199 PBS
442	ST	<b>A106 MAC</b>	Bd YNT	ET103969	Pn	8411NTP1C092	C53F	Jun-84	Rapson (SN)	Jun-05	
443	ST	<b>A416 SPS</b>	Bd YNT	DT100792	Pn	8311NTP1C026	C53F	Dec-83	Rapson (SN)	Jun-05	
444	KW	<b>HDZ 5427</b>	Vo B10M-61	7478	VH	11291	C50FT	Apr-84	Rapson (SN)	Jun-05	LTU 284, A128 TAS
451	ST	<b>B509 YAT</b>	Bd YNT	ET106389	Pn	8511NTP2C017	C53F	May-85	Rapson (SN)	Jun-05	
452	ST	<b>C771 FBH</b>	Bd YNV	FT700400	Du	8592/9255	C57F	Oct-85	Rapson (SN)	Jun-05	
455	ST	<b>TJI 7192</b>	Bd YNT	HT100812	Pn	8711NTP3C05N	C53F	May-87	Rapson (SN)	Jun-05	D676 FWK, 9737 VC, D523 TUJ
457	KW	<b>SJI 1631</b>	Bd YNT	GT104156	Pn	8711NTP3C005	C53F	Apr-87	Rapson (SN)	Jun-05	D125 VRM, 748 COF, D410 BDP
473	KW	<b>D451 CNR</b>	Bd YNT	HT101285	Du	8694/0379	C53F	May-87	Rapson (SN)	Jun-05	
474	KW	<b>A446 BGM</b>	Bd YNT	LW452934	Pn	8211NTS5C033	C53F	Jan-84	Rapson (SN)	Jun-05	
475	KW	<b>B460 KRM</b>	Bd YMP	FT103191	Pn	8510MQP2C001	C45F	May-85	Rapson (SN)	Jun-05	
476	KW	<b>C321 PRM</b>	Bd YNT	FT105396	Pn	8611NTP2C008	C53F	May-86	Rapson (SN)	Jun-05	
477	KW	<b>C322 PRM</b>	Bd YNT	FT104931	Pn	8611NTP2C006	C53F	May-86	Rapson (SN)	Jun-05	
478	KW	<b>E176 TWW</b>	Bd YNV	FT700611	Pn	8712NVP3C016	C57F	Jan-88	Rapson (SN)	Jun-05	
479	KW	<b>A449 HJF</b>	Bd YNT	DT701065	Pn	8411NTP1C030	C53F	Apr-84	Rapson (SN)	Jun-05	A449 HJF, GAZ 6666
480	KW	<b>B193 DVL</b>	Bd YNT	ET104484	Pn	8411NTP1C096	C53F	Jan-85	Rapson (SN)	Jun-05	B193 DVL, PAZ 9319, B193 DVL, GAZ 7227
481	KW	<b>C268 XSC</b>	Bd YNV	FT700316	Pn	8512NVP2C015	C57F	Oct-85	Rapson (SN)	Jun-05	B885 RMS, B977 NSF
482	KW	<b>535 LXB</b>	Ds Jv	11SDL2133/897	Pn	9311HZM1455	C47F	Nov-93	Rapson (SN)	Jun-05	L151 BFV
483	KW	<b>550 XBV</b>	Ds Jv	11SDL2133/912	Pn	9311HZM1460	C47F	Jan-94	Rapson (SN)	Jun-05	L156 BFV
484	KW	<b>720 RXJ</b>	Ds Jv	11SDL2133/919	Pn	9311HZM1462	C47F	Jan-94	Rapson (SN)	Jun-05	L158 BFV
485	KW	<b>520 PXR</b>	Ds Jv	11SDL2133/1068	Pn	9411HZM2828	C47F	Jan-95	Rapson (SN)	Jun-05	M107 CCD

<b>486</b>	KW	<b>700 KXL</b>	Ds Jv	11SDL2133/1053	Pn	9411HZM2821	C47F	Dec-94	Rapson (SN)	Jun-05	M951 JBO
<b>487</b>	KW	<b>JAZ 9852</b>	Ds Jv	11SDL2129/835	Pn	9311HGM0807	C47F	Oct-93	Rapson (SN)	Jun-05	L144 BFV
<b>499</b>	KW	<b>A615 KRT</b>	Bd YNT	ET103361	Pn	8411NTP1C076	C53F	Apr-84	Rapson (SN)	Jun-05	A253 SBM, 866 VNU
<b>540</b>	KW	<b>UIJ 412</b>	Ds Jv	11SDL2133/903	Pn	9311HZM1457	C47F	Dec-93	Rapson (SN)	Jun-05	L153 BFV
<b>541</b>	KW	<b>PDZ 7762</b>	Ds Jv	11SDL2129/844	Pn	9311HGM0805	C47F	Sep-93	Rapson (SN)	Jun-05	L142 BFV
<b>613</b>	KW	<b>ESK 930</b>	Vo B10M-62	40329	Pn Pe 350	9412VUP1793	C48FT	Dec-93	Rapson (SN)	Jun-05	L592 RST
<b>622</b>	KW	<b>L500 GSM</b>	Ds Jv	8.5SDA2127/761	Bf	2355	C35F	Mar-94	Rapson (SN)	Jun-05	
<b>632</b>		<b>IDZ 828</b>	Ds Jv	12SDA2159/1501	Bf	3116	C49FT	May-96	Highland Country (SN) 632	Nov-05	N866 XMO