

Scotland North – Minor Operators – Operators Included

A

A & I, Stonehaven
Aberdeen VIP Party Bus,
Aberdeen
Active Outdoor Pursuits,
Newtonmore
Aitken J, Lochboisdale
APCOA Parking, Dyce

B

Bain {RS Coaches}, Sauchen
Bain, Oldmeldrum
Bain, Sauchen
Blargoans, Thurso
Bremner, Aviemore
Brown {Allan & Black},
Aboyne
Bruce, Maud
Buchanan, Griminish
Buchanan, Linciate
Burns, Tarves

C

Cadger, Balmedie
Caledonian Coaches, Fort
William
Cameron, Brora
Campbell {South Harris
Coaches}, Strond
Care UK Learning, Drummuir
Central Taxis {Central
Coaches}, Aberdeen
Central Coaches, Aberdeen
Central Taxis {Central
Coaches}, Aberdeen
Cheyne, Daviot
Clark, Stromness
Classy Taxis {Freddies
Taxis}, Fraserburgh
Comhairle, Stornoway
Cormack {Beaully Coach
Hire}, Beaully
Cormack {Beaully Coach
Hire}, Beaully
Corsie, Dounby
Crestmount {Highland
Taxis}, Inverness

D

D & E Coaches ,Inverness
DA Travel, Kilphedar
DAB Plus, Maud
Deveron Coaches, Macduff
Dunnett {CFDA Firm},
Thurso

E

Easter Ross {George Rapson
Travel}, Tore
Edwards {GL Enterprises},
Drumnadrochit
Ewen {Fountain Executive},
Dyce

F

Falcon, Dyce
Farley {Bobbysbus},
Auchengill
Farrey {Four Seasons}, Duns
Ferguson {Aldas},
Lochmaddy
Ferguson {Traveline}, East
Whitburn
Fraser {Kintore Taxis},
Kintore
Fraser, Munloch

G

Galson Stornoway, Barvas
Glover {D&H Coaches}, Kyle
Grenitote Travel, Grenitote

H

Halcrow, Cunningsburgh
Harcuss, Pierowall
Harrold, South Keiss
Heatherlea, Nethybridge
Hill {Halyal Garage}, Lyness

I

Ingram {Turrieff Coaches &
Cabs}, Turrieff

J

Jacobite Cruises, Inverness
Jamieson, Cullivoe
Johnson, Brae

K

Keir, Glass
Kineil Coaches, Fraserburgh

L

Leask, Lerwick
Lees, Lumphanan
Lindsay, Lochboisdale
Littlejohn {Aboyne Taxis},
Aboyne
Loch Ness Monster,
Drumnadrochit

Lochs Motor Transport,
Leurbost
Logan, Lossiemouth
Lowe {W&G Taxis /
Coaches}, Cuminestown

M

MacArthur {Spa Motors},
Strathpeffer
MacAskill {Glenedin
Coaches}, Edinbane
MacDonald {Hebridean
Coaches}, Howmore
MacDonald, Balallan
MacDonald, Carloway
MacDonald, Dunvegan
MacDonald, Lochmaddy
MacDonald, Struan
MacDonald, Tolstachaolais
MacIver {Hebridean
Transport}, Stornoway
MacIver, Carloway
MacIver, Stornoway
MacKay, Dornoch
MacKay, Dunress
Mackay, Talmine
MacKenzie & MacLennan
{Westerbus}, Gairloch
MacKenzie {Coast to Coach
Travel}, Dundonnell
MacKenzie, Upper Carloway
MacKinnon {Misty Isle
Tours}, Kyle
MacLean, Dornie
MacLean, Kyle
MacLennan {Moray Academy
of Transport Training}, Elgin
MacLennan P, Laxy Lochs
MacLennan, Grosebay
MacLennan, Laxy Lochs
MacLennan, Stornoway
MacMillan, Castlebay
MacNeil, Castlebay
MacQuarrie, Lochmaddy
MacRae {Skye-ways / Clan
Taxis}, Kyle
MacRae, Glenshiel
MacRitchie {Hebridean
Minibus Service}, Ness
MacVicar {WMV}, Linciate
Marshall & Innes {J & J
Watt}, Huntly
Marshall & Innes {J&J Watt},
Huntley
Matheson {KSM Motors},
Lochinver
Maynes, Buckie
McAllister {Ashgrove
Executive Travel}, Aberdeen

McIntosh {Templeford
Garage}, Forgue
Menzies {Castle Cruises Loch
Ness}, Drumnadrochit
Milne, New Byth
Morrison {Andrew's},
Whiteness
Morrison {Escocia
Vacaciones}, Beaulieu
Morrison {Uig Bus Services},
Uig
Morrison, Uig
Mowat {Victoria}, Peterhead
Mundole, Forres

N

Nicoll, Laurencekirk
Nicolson, Cunningsburgh
Northcote {Augusta}, Fort
Augustus

O

Orkney Community
Transport, Kirkwall

P

Peace, Echt
Petrofac Training, Aberdeen
Philips Coaches, Alford
Poke {J & V Coaches},
Stromness
Portsoy Taxis, Portsoy
Premier Coaches, Kintore
Priest & Thomson {P&T
Coaches}, Baltasound

R

Ratray {Woodlands Service
Centre}, Grantown-on-Spey
Reid, Newmachar
Reid, Rhynie
Robertson, Cuminstown
Robertson, Ulsta
Robinson Transport,
Weisdale
Roe {Vale Taxis}, Banff
Rosie {Causeway Cars}, St
Margarets Hope
Ross {Lochcarron Garage},
Strathcarron
Ross, Beaulieu

S

Safedrive Taxis, Laurencekirk
Sanday Enterprises, Sanday

Sands Hotel, Burray
Scalpay Minibus Committee,
Scalpay
Seaprobe Atlantis, Upper
Breakish
Shearer, Huntly
Shetland Islands Council,
Lerwick
Shiel Buses, Acharacle
Shirran, Lumsden
Simpson, Rosehearty
Slater, Gott
Spence {Arthur's Hire},
Birsay
Stables, Newmill
Stewart {RGS Motor
Services}, Oldmeldrum
Sutherland {Great Glen
Travel}, Invergarry

T

Taxi 24/7, Nairn
The Durness Bus, Lairg
Tipper, Rousay
Tour Skye, Portree

U

Urquhart, Inverness

V

Voluntary Action Training
{The Red Bus / Third Sector
Hebrides / Staran},
Stornoway

W

Wastbus, Bixter
Watermill Coaches,
Fraserburgh
Watt {A&K Transport}, Walls
Webster {Real Scottish
Journeys}, Peinness
White, Bridge of Walls
Whytes, Newmachar

Scotland North - Minor Operators Fleet Lists, as at November 2017.

Fleet Data thanks to Tony Hunter

Operator	Area	Status / Fleet	Registration	Chassis Type and Number		Body Type and Number	Seating	Previous Registrations
A								
A & I, Stonehaven	SN		GU 08 WNN	Fd	Tt	WF0DXXTTFD8B79104	Fd	M16
A & I, Stonehaven	SN		SC 02 JUX	Fd	Tt	WF0EXXGBFE2L49724	Fd	M14
A & I, Stonehaven	SN		SV 05 MMO	Fd	Tt	WF0EXXTTTFE4T04264	Fd	M16
A & I, Stonehaven	SN		X983 SHH	MB	O814D	WDB6703742N086196	Pn	998.5MZE1996
A & I, Stonehaven	SN	(x)	SP 03 WRU	Rt	Mtr	VF1FDBNE528305510	Glen	M8L
Aberdeen VIP Party Bus, Aberdeen	SN		H 6 TCC	Ta	HDB30R	001374	Co	151212
Active Outdoor Pursuits, Newtonmore	SN		SX 64 EUA	Fd	Tt	WF0HXXTTGHEB80005	Fd	M16
Aitken J, Lochboisdale	SN		XIL 7250	MB	814D	WDB6703132N028098	WS	4787/95
Aitken J, Lochboisdale	SN		YK 05 EYW	LDV	Cy	SEYZMVSZGDN111228	LDV	M16
APCOA Parking, Dyce	SN		BF 16 XRD	MB	City 45	WDB9066572P179735	MB	B13F
APCOA Parking, Dyce	SN		BT 15 KMK	MB	City 45	WDB9066572S881328	MB	B13F
Apcoa, Dyce	SN		BT 15 KMM	MB	City 45	WDB9066572S974393	MB	B13F
B								
Bain {RS Coaches}, Sauchen	SN		A 6 PTU	Ba	FHD12-370	XL9AA18CGY8003478	Ba	C70F
Bain {RS Coaches}, Sauchen	SN		BU 05 DVL	Rt	Mtr	VF1PDMUL632885481	Rt	M16
Bain {RS Coaches}, Sauchen	SN		BU 05 DVM	Rt	Mtr	VF1PDMUL632885483	Rt	M16
Bain {RS Coaches}, Sauchen	SN		BU 05 DVN	Rt	Mtr	VF1PDMUL632885484	Rt	M16
Bain {RS Coaches}, Sauchen	SN		JK 03 JNK	Ba	FHD12-370	XL9AA18P330003853	Ba	C57F
Bain {RS Coaches}, Sauchen	SN		MT 54 TFE	MB	O814D	WDB6703742N116383	Me	4083
Bain {RS Coaches}, Sauchen	SN		PJ 12 ATY	Au	N2216/3SHDL	WAGP20Z7CT018704	Au	P20-0147
Bain {RS Coaches}, Sauchen	SN		R 14 ROB	MB	O816D	WDB6793742N148030	UNVI	-?-
Bain {RS Coaches}, Sauchen	SN		YN 11 AXH	MB	O816D	WDB6703742N140901	Pn	107.5MBJ8715
Bain {RS Coaches}, Sauchen	SN		N 18 KTL	Ba	FHD12-340	XL9AA18P230003667	Ba	C53F
Bain {RS Coaches}, Sauchen	SN		N736 FJC	Vo	B10M-62	YV31M2B19SA043082	Pn	9512VUP3673
Bain {RS Coaches}, Sauchen	SN		T 9 TAP	MB	614D	WDB6683532N076711	Onyx	315
Bain {RS Coaches}, Sauchen	SN		YP 11 XJB	MB	315CDI	WDB9067332S565884	?	M8
Bain {RS Coaches}, Sauchen	SN		YS 57 YND	Fd	Tt	WF0DXXTTFD7T50924	Fd	M16
Bain {RS Coaches}, Sauchen	SN		RIL 3691	Vo	B10M-62	YV31M2B19TA044038	Je	23922
Bain, Oldmeldrum	SN	(w)	611 LFM	Au	N122	84 99 87	Au	CH57/18CT
Bain, Oldmeldrum	SN	(w)	UIW 2135	Vo	B10M-61	013862	VH	12627
Bain, Oldmeldrum	SN		YKZ 7497	KL	XMQ6127	LA6R1HSJX8B102159	KL	C49FT
Bain, Oldmeldrum	SN		A 20 HOF	Sca	K93CRB	1819824	Pn	9112SEM0336
Bain, Oldmeldrum	SN		AE 09 DJK	MAN	14.240	WMAA66ZZ37C010251	MCV	MCV-342
Bain, Oldmeldrum	SN		BMC 2T	BMC	750	NMC750RKDRD100004	BMC	C29F
Bain, Oldmeldrum	SN		BU 05 EHB	BMC	Fn	NMC111LKFD200020	BMC	B40F
Bain, Oldmeldrum	SN		BX 14 KPF	KL	XMQ6129	LA6A1LBS6DB105434	KL	C49FT
Bain, Oldmeldrum	SN		BX 54 VNV	BMC	1100	NMC111LKFD200019	BMC	B40F
Bain, Oldmeldrum	SN		BX 56 XAE	KL	XMQ6127	LKLR1KSLX5B600226	KL	C48FT
Bain, Oldmeldrum	SN		CN 04 XCK	BMC	1100	NMC111LKFD200026	BMC	B40F
Bain, Oldmeldrum	SN		FL 55 NMV	Fd	Tt	WF0EXXTTTFE5A53776	Fd	M16
Bain, Oldmeldrum	SN	(w)	GSU 10T	AEC	Re	6U3ZR37640	Pn	7812ACM032

Bain, Oldmeldrum	SN		H 16 XEC	Vo	B10M-62	YV31MA6141A053196	Co	F013043007	C49FT	(ex Y807 LCS, WSC 471, Y807 LCS, 123 TRL, ULZ 1819, Y798 GDV, 91-D-60725)
Bain, Oldmeldrum	SN	(r)	H102 VUB	DAF	SB220LC550	XLRDE02LTOE344152	Oe	5141	DP29DL	
Bain, Oldmeldrum	SN	(w)	J627 UTW	MB	709D	WDB6690032P145746	Pn	91.7MVC0311	B23F	
Bain, Oldmeldrum	SN		JIL 2949	Sca	K93CRB	1817639	Pn	9012SFA2370	C55F	(G882VNA/WSV553/G882VNA)
Bain, Oldmeldrum	SN		JIL 7656	MAN	18.360	WMAA51ZZ14S002589	Mpo	2.05.R.OF.1143	C23FT	(PN05DZH)
Bain, Oldmeldrum	SN		K 21 OUY	Vo	B10M-60	YV31MGD10NA029764	Pn	9212VCP0694	C53F	(ex 6292 SC, K 21 OUY)
Bain, Oldmeldrum	SN		LX 58 BZO	MB	515CDI	WDB9066572S335055	Tawe		M16	
Bain, Oldmeldrum	SN	(w)	M408 OKM	De	Le SLF	11SDA3201/149	Bf	421-05	B40F	(ex B 8 YST, M408 OKM, 418 DCD, M408 OKM)
Bain, Oldmeldrum	SN		MW 10 DVR	Fd	Tt	WF0DXXTTFDAJ41802	Fd		M16	
Bain, Oldmeldrum	SN	(r)	N120 WBR	Ds	Dt	9.8SDL3054/2920	MI	C37.115	B40F	
Bain, Oldmeldrum	SN		N590 GBW	Ds	Jv	12SDA2146/1431	Co	558019	C49FT	(N590GBW/GSU483)
Bain, Oldmeldrum	SN		P 80 BMC	BMC	850	NMC850RKTRD800031	BMC		C35F	
Bain, Oldmeldrum	SN		R 4 WGT	Ba	FHD12-340	XL9AA18CGW7003393	Ba		C70F	
Bain, Oldmeldrum	SN		R 5 MCH	MB	311CDI	WDB9066325318150	Malton		M13	(YL08FZB)
Bain, Oldmeldrum	SN		R 7 LWB	Ba	FHD12-340	XL9AA18CGW7003154	Ba		C70F	(R 7LWB/A 6VUE)
Bain, Oldmeldrum	SN	(w)	R376 DJN	Oe	L1070	VN9196	Oe	9196	B35F	(R376DJN/WSV541)
Bain, Oldmeldrum	SN	(r)	S306 KNW	DAF	DE02GSSB220	XMGDE02GS0H005946	Oe	5351	B49F	
Bain, Oldmeldrum	SN		S471 HOK	Ta	BB50R	TW043BB5000001258	Co	851118	C26F	
Bain, Oldmeldrum	SN	(x)	S517 MRS	LDV	Cy	SEYZNHPHEDN037220	Me	3051	B12FL	
Bain, Oldmeldrum	SN		SH 05 YLR	Fd	Tt	WF0EXXTTFE5U48605	Fd		M14	
Bain, Oldmeldrum	SN		SM 54 ELH	Fd	Tt	WF0EXXTTFE4S65440	Fd		M14	
Bain, Oldmeldrum	SN		SV 02 JZW	LDV	Cy	SEYZNHPYGDN085580	Cu	8542	B12FL	
Bain, Oldmeldrum	SN		SV 06 ESG	BMC	1100	NMC111LKFD200024	BMC		B40F	
Bain, Oldmeldrum	SN		SV 06 ESN	BMC	1100	NMC111LKFD200023	BMC		B40F	
Bain, Oldmeldrum	SN		SV 06 GUX	BMC	900	NMC900LKKRD100002	BMC		B27F	
Bain, Oldmeldrum	SN		SV 10 CUK	BMC	1100FE	NMC111TKCRD400006	BMC		B55F	
Bain, Oldmeldrum	SN		SV 12 BVC	KL	XMQ6900J	LAGRIDSEXBB301294	KL		B27F	
Bain, Oldmeldrum	SN		SV 56 EOR	MB	614D	WDB6683222N124275	Me	4386	B20FP	
Bain, Oldmeldrum	SN		SV 57 AKK	BMC	900	NMC900LKKRD20010	BMC		B27F	
Bain, Oldmeldrum	SN	(w)	T147 AUA	Ds	Dt SLF	SFD212BR1WGW13131	Ar	9836/8	B27D	
Bain, Oldmeldrum	SN		T825 FUM	Vo	B10M-62	YV31MA614XC061246	Pn	9912VUP0551	C49FT	(T551EUB/WIJ 551)
Bain, Oldmeldrum	SN		VU 03 HRC	Vx	Mov	VF1F9CNLS27862273	O&H	-?-	M14	
Bain, Oldmeldrum	SN		WG 55 XDL	VW	LT	WV1ZZZ2DZ6H009182	?		M16	
Bain, Oldmeldrum	SN		Y147 RSS	Ta	BB50R	TW043BB5000001643	Co	F03071013	C26F	
Bain, Oldmeldrum	SN		YJ 61 GPZ	Rt	Mtr	VF1MEN4JE45847259	?		M16	
Bain, Sauchen	SN		YN 58 KSJ	Au	N2216/3SHDL	WAGP22Z238T012918	Au	-?-	C61F	(ex J300 TRU, YN 58 KSJ)
Blargoans, Thurso	SN		BL 04 OAN	Fd	Tt	WF0DXXTTFDCL36965	Fd		M16	
Blargoans, Thurso	SN		BL 06 OAN	Fd	Tt	WF0DXXTTFDCG33964	Fd		M16	(SL12CWR)
Blargoans, Thurso	SN		BL 10 ANS	Fd	Tt	WF0DXXTTFDAS10568	Fd		M16	(SP10YKC)
Bremner, Aviemore	SN		PX 07 BEY	Ba	FHD12-340	XL9AA18P632003684	Ba		C53F	(PX07BEY/7726AT)
Bremner, Aviemore	SN		S 29 BOA	MB	O816D	WDB6703742N148406	Sitcar	2986	C29F	
Bremner, Aviemore	SN		SN 15 FFC	MB	516CDI	WDB9066572S119206	EVM		C19F	
Bremner, Aviemore	SN		YN 05 HEV	Sca	K114EB4	YS2K4X20001848942	Ir	130067	C48FT	
Brown {Allan & Black}, Aboyne	SN		5397 LJ	Sca	K400EB4	YS2K4X20001884182	Lah	YK900L360DR00879	C53FT	(ex YT 13 AOG)
Brown {Allan & Black}, Aboyne	SN		?	Sca	K113CRB	YS4KC2X2B01827069	Bf	3168	C50FT	(ex CKL 1Y, P 66 MNM)
Brown {Allan & Black}, Aboyne	SN	(r)	BLZ 8582	Ka	S215H	WKK17900001045055	Ka		C53F	(PSU620/F489YSC)
Brown {Allan & Black}, Aboyne	SN		BVS 118	Au	N516SHD	WAG2051621SS31993	Au	5160629	C48FT	(YR02UOF)
Brown {Allan & Black}, Aboyne	SN		F830 NNF	Ka	S215H	WKK17900001035095	Ka		C53F	(F830NNF/515FCG/F830NNF/5950KP/VAV 15)
Brown {Allan & Black}, Aboyne	SN		FJ 57 KHU	Sca	K340EB6	YS2K6X20001857580	Co	FD73043036	C82F	
Brown {Allan & Black}, Aboyne	SN		FM 10 USF	Sca	K360EB4	YS2K4X20001867044	Lah	YK900L360?R00870	C51FT	(ex 5397 LJ, FM 10 USF, B 17 DWA, FM 10 USF, B 15 DWA, B 13 DWA)
Brown {Allan & Black}, Aboyne	SN		G369 RTO	Sca	N113DRB	1816857	Ar	RH68/489/16	H47/33F	
Brown {Allan & Black}, Aboyne	SN		K 7 SKY	Ka	S250	WKK13400001015074	Ka		C48FT	(P600TCC)

Brown {Allan & Black}, Aboyne	SN		OSA 72	Ba	FHD14-430	XL9AB36P531003862	Ba		C83F	(ex WA 54 KTT)
Brown {Allan & Black}, Aboyne	SN		P 6 KET	Ba	FHD13-380	XL9AA38P431003323	Ba		C70F	(ex UK 04 TGT, GPV 516, UK 04 TGT)
Brown {Allan & Black}, Aboyne	SN		RAX 19Y	Ka	S215HD	WKK17900001035016	Ka		C49FT	(RAX 19Y/HIL7618)
Brown {Allan & Black}, Aboyne	SN		RE 60 BKA	MB	515CDI	WDB90665725500599	EVM		M16	
Brown {Allan & Black}, Aboyne	SN		RE 66 VMA	MB	516CDI	WDB9066572P265354	EVM		M16	
Brown {Allan & Black}, Aboyne	SN	(p)	RUB 379G	Ld	PSU3A/4R	900996	Pn	693293	C53F	
Brown {Allan & Black}, Aboyne	SN		TAV 35	Ba	FHD14-430	XL9AB36P431003441	Ba		C83F	(ex WA 04 EWW)
Brown {Allan & Black}, Aboyne	SN		VAV 15	Sca	K340EB4	YS2K4X20001861577	Lah	YK900L3408R00859 5	C49FT	(YR58SNN)
Brown {Allan & Black}, Aboyne	SN		WA 08 GPK	Ba	FHD120.365	XL9AA18R733003759	Ba		C53FT	
Brown {Allan & Black}, Aboyne	SN		YN 05 UVL	MB	413CDI	WDB9046632R702698	KVC		M16	
Bruce, Maud	SN		FT 10 KUP	MB	613D	WDB6683532N137911	Onyx	905	C24F	
Bruce, Maud	SN		MD 15 WGF	Fd	Tt	WF0HXTTGHHFY06500	Fd		M16	
Bruce, Maud	SN	(x)	PX 56 YDA	Fd	Tt	WF0DXTTTFD6P40968	Fd		M8	
Bruce, Maud	SN		SG 62 DZZ	Fd	Tt	WF0DXTTTFDCR65546	Fd		M16	
Bruce, Maud	SN		T727 SFS	MB	614D	WDB6683532N076374	Onyx	362	C24F	
Bruce, Maud	SN		YK 57 MPV	Fd	Tt	WF0DXTTTFD7Y89507	Fd		M16	
Buchanan, Griminish	SN		T540 SAS	LDV	Cy	SEYZMVJEDN047138	LDV		M16	
Buchanan, Linciate	SN		W646 GBX	Rt	Mtr	VF1FDCCM521078902	Cym		M16	
Burns, Tarves	SN	(w)	B 10 MBC	Vo	B10M-60	YV31MGD12KA020317	VH	13931	C53F	(F773TMH)
Burns, Tarves	SN		BX 61 VLB	MB	516CDI	WDB90665725442640	UNVI	-?	C19F	
Burns, Tarves	SN		MK 02 GAU	MB	413CDI	WDB9046632R378552	Onyx	541	M16	
Burns, Tarves	SN		P 6 CHT	MB	310D	WDB9034632P701506	MinO		M15	(P720ESA)
Burns, Tarves	SN		P161 RWR	DAF	DE33WSSB3000	XMGDE33WS0H005633	Is	350T1CV1GB0040	C70F	
Burns, Tarves	SN		P716 RWU	DAF	DE33WSSB3000	XMGDE33WS0H005182	Is	350T1PT1GP0017	C70F	
Burns, Tarves	SN		PO 65 FMJ	MAN	19.290	WMARR8ZZ1GC021075	MOBIpeople -?		C70F	
Burns, Tarves	SN		SK 07 FZV	MB	616CDI	WDB9056132R952189	UNVI		C22F	
Burns, Tarves	SN		SN 61 CXB	MB	516CDI	WDB90665725585244	?		M16	
Burns, Tarves	SN		SW 10 UMK	MB	O816D	WDB6703742N133621	Ech	-?	C33F	(ex 10-DL-216)
Burns, Tarves	SN	(w)	V958 DSO	MB	614D	WDB6683532N085712	Onyx	374	C24F	
Burns, Tarves	SN		YCZ 4486	MB	O814D	WDB6703742N109125	Ech		C29F	
Burns, Tarves	SN		YP 14 FXR	MB	313CDI	WDB9066332S875819	?		M13	
C										
Cadger, Balmedie	SN		NH 57 PVT	Fd	Tt	WF0DXTTTFD7L67292	Fd		M16	
Caledonian Coaches, Fort William	SN		BJ 07 XCW	Fd	Tt	WF0DXTTTFD7D11779	Fd		M14	
Caledonian Coaches, Fort William	SN		WA 14 CLY	MB	516CDI	WDB90665725638730	UNVI	-?	C21F	
Cameron, Brora	SN		HSK 607	Fd	Tt	WF0DXTTTFDBK45438	Fd		M16	(ex ST 11 FWS)
Cameron, Brora	SN		HSK 631	VW	Crf	WV1ZZZ2E296008915	Onyx	907	M16	(MX59FYM)
Cameron, Brora	SN		HSK 708	MB	O816D	WDB6703742N131200	UNVI	-?	C33F	(ex SX 08 FBO, NE 51 BUS, JC 08 BUS)
Cameron, Brora	SN		HSK 805	MB	O813D	WDB6703742N124781	UNVI		C33F	(NE55BUS)
Cameron, Brora	SN		HSK 815	MB	O814D	WDB6703742N117015	ACI	1884	C31F	(OS05NES)
Cameron, Brora	SN		HSK 816	Rt	Tc	VF1JLB7BSDY509100	?		M9	(ex NX 13 XDY)
Cameron, Brora	SN		SB 11 XSD	Fd	Tt	WF0BXXBDFBAG87547	Fd		M8	
Campbell {South Harris Coaches}, Strond	SN		SY 14 KAK	Fd	Tt	WF0DXTTTFDDK81220	Fd		M16	
Campbell, Strond	SN		BP 62 ADZ	Fd	Tt	WF0DXTTTFDCL49488	Fd		M16	
Capbell, Strond	SN		SF 53 NZU	LDV	Cy	SEYZMVSZGDN099891	?		M16L	
Capbell, Strond	SN		YD 10 SVE	Fd	Tt	WF0DXTTTFD9K03477	Fd		M16	
Care UK Learning, Drummuir	SN		SD 58 TKV	Fd	Tt	WF0DXTTTFD8K32590	?		M14	
Care UK Learning, Drummuir	SN		SG 59 CFP	Fd	Tt	WF0DXTTTFD9R32759	?		M14	
Central Coaches, Aberdeen	SN		WX 06 UWG	MB	O814D	WDB6703732N123097	UVM	10921	B28FL	
Central Coaches, Aberdeen	SN		YG 10 ETF	Fd	Tt	WF0DXTTTFD9D31004	Fd		M16	

Central Taxis {Central Coaches}, Aberdeen	SN		LK 11 GFZ	Ibs	CC150E25FP	ZCFA1LJ0302511165	Vxl	-?-	B68FL	
Central Taxis {Central Coaches}, Aberdeen	SN		SG 03 ZES	Vo	B12M	YV3R9F8143A001052	Je	26448	C53F	(ex K333 RES, SG 03 ZES, 2 HAN)
Central Taxis {Central Coaches}, Aberdeen	SN		AR 63 AAA	Vo	B9R	YV3S5P723DA161938	Je	37176	C53FT	
Central Taxis {Central Coaches}, Aberdeen	SN		BJ 63 FWK	Fd	Tt	WF0DXXTTFDDB52862	Fd		M16	
Central Taxis {Central Coaches}, Aberdeen	SN		BK 11 WPV	Fd	Tt	WF0DXXTTFDBC39564	Fd		M16	
Central Taxis {Central Coaches}, Aberdeen	SN		BN 65 OTJ	Fd	To	WF03XXTTG3FD14643	Fd		M9	
Central Taxis {Central Coaches}, Aberdeen	SN		CV 02 KFX	MB	O814D	WDB6703742N087901	Cym		B31F	
Central Taxis {Central Coaches}, Aberdeen	SN		D 4 CTC	Ibs	397E.12.31	ZGA7B2N000E002382	Pn	0512EBL6140	C53F	(YN06RVR)
Central Taxis {Central Coaches}, Aberdeen	SN		D 5 CTC	Vo	B13R(T)	YV3T2P426EA164755	Pn	DE06/01	C57FT	(ex YX 14 SDY)
Central Taxis {Central Coaches}, Aberdeen	SN		D 7 CTC	MB	516CDI	WDB9066572S888061	UNVI	-?-	M16	(ex WA 14 COJ)
Central Taxis {Central Coaches}, Aberdeen	SN		D 8 CTC	Ba	XHD12-340	XL9259AM310320789	Ba		C52FT	(YJ56CEO)
Central Taxis {Central Coaches}, Aberdeen	SN		D 9 CTC	Vo	B12M	YV3R9F8164A011924	Co	F043043009	C49FT	(FJ06URK)
Central Taxis {Central Coaches}, Aberdeen	SN		D 12 CTC	MB	1223L	WDB9702582K945689	UNVI	33866	C??F	(SN05DJY)
Central Taxis {Central Coaches}, Aberdeen	SN		D 15 CTC	Vo	B13R(T)	YV3T2P428DA160611	Pn	CE08/02	C57FT	(ex YN 13 GXR)
Central Taxis {Central Coaches}, Aberdeen	SN		D 16 CTC	Vo	B13RT	YV3T2P427CA154652	Je	30198	C57FT	(ex BX 12 CUH)
Central Taxis {Central Coaches}, Aberdeen	SN		D 17 CTC	MB	O815D	WDB6703742N122464	UNVI	34138	C29F	(HEZ8265/SN06OWX)
Central Taxis {Central Coaches}, Aberdeen	SN		D 18 CTC	Vo	B12M	YV3R9L2298A126099	Pn	0812.8TXL7703	C53FT	(YN08NNA)
Central Taxis {Central Coaches}, Aberdeen	SN		D 19 CTC	Au	N122/3	WAG3012223SS34111	Au	SS34111	CH57/18CT	(DD03BUZ/5705MT/DD03BUZ)
Central Taxis {Central Coaches}, Aberdeen	SN		D 20 CTC	Vo	B13R(T)	YV3T2P422BA147270	Pn	1114SBA8826	C57F	(ex GXZ 2986, YN 11 AXU)
Central Taxis {Central Coaches}, Aberdeen	SN	(x)	HK 05 UCR	Fd	Tt	WF0TXXBDFT5B44399	Fd		M8	
Central Taxis {Central Coaches}, Aberdeen	SN	(x)	HK 05 UCX	Fd	Tt	WF0TXXBDFT5B44067	Fd		M8	
Central Taxis {Central Coaches}, Aberdeen	SN		L 22 CTC	MB	616CDI	WDB9056132R727460	UNVI		C22F	(ex YN 05 RXT, FXI 690, YN 05 RXT, MCH 85, YN 05 RXT)
Central Taxis {Central Coaches}, Aberdeen	SN		L 44 CTC	Vo	B13R(T)	YV3T2P425CA154635	Je	30197	C57FT	(ex BX 12 CUG)
Central Taxis {Central Coaches}, Aberdeen	SN		L 70 CTC	Vo	B10M-62	YV31M2B18SA043848	VH	32277	C70F	(LSK832/N509PYS/DSV707/N509PYS)
Central Taxis {Central Coaches}, Aberdeen	SN		L 77 CTC	Vo	B10M-62	YV31M2B13SA043708	VH	32265	C70F	(KSK981/N475PYS/SIL9541/N475PYS/WA Y877/N475PYS)
Central Taxis {Central Coaches}, Aberdeen	SN		L 80 CTC	Sca	K124IB4	YS4K2X20001835958	VH	33387	C49FT	(00-KK- 2352/W413SSX/2748PK/PSU611/YIL2851/ D 7CTC)
Central Taxis {Central Coaches}, Aberdeen	SN		L 88 CTC	MB	1524L	WDB9702782L314432	UNVI		C37F	(ex YN 09 HDY)
Central Taxis {Central Coaches}, Aberdeen	SN		L 99 CTC	Vo	B12B	YV3R8M9269A132796	Pn	0914TAA8212	C53FT	(ex YN 09 HRE, CC 54 AFC, D 18 CTC, YN 09 HRE, OO 09 MFC, YN 09 HRE)

Central Taxis {Central Coaches}, Aberdeen	SN		MX 55 NWB	MB	O814D	WDB6703742N118501	Me	4165	B29FL	
Central Taxis {Central Coaches}, Aberdeen	SN	(x)	OY 52 YTR	Io	50C13	ZCFC357100D153818	?		M8L	
Central Taxis {Central Coaches}, Aberdeen	SN	(x)	OY 52 YTW	Io	35C11	ZCFC357100D154056	?		M8L	
Central Taxis {Central Coaches}, Aberdeen	SN		P623 EVN	MB	711D	WDB6690632N048742	ACI	1381	C24F	
Central Taxis {Central Coaches}, Aberdeen	SN	(x)	R276 YMB	MB	512D	WDB6673522N064736	Onyx	257	C8FL	
Central Taxis {Central Coaches}, Aberdeen	SN		R301 BJA	Vo	B10M-62	YV31MA61XVA047098	Pn	9712VUP6744	C70F	(R301BJA/OYU807)
Central Taxis {Central Coaches}, Aberdeen	SN	(x)	RJ 55 HVY	VW	LT35	WV1ZZZ2DZ6H008242	?		M8L	
Central Taxis {Central Coaches}, Aberdeen	SN		SB 53 JUJ	Fd	Tt	WF0EXXGBFE3L78851	Fd		M16	
Central Taxis {Central Coaches}, Aberdeen	SN		SF 03 ZXC	MB	O815D	WDB6703742N105767	Sitcar	1392	C33F	
Central Taxis {Central Coaches}, Aberdeen	SN		SF 06 KHV	MB	O814D	WDB6703742N118674	Pn	058.5MXV6086	DP29FL	
Central Taxis {Central Coaches}, Aberdeen	SN		SF 06 OED	MB	O814D	WDB6703742N117729	Pn	058.5MXW6007	DP32FL	
Central Taxis {Central Coaches}, Aberdeen	SN		SF 58 OGW	Ba	FLD120.365	XL9AA12R833003899	Ba		C57F	
Central Taxis {Central Coaches}, Aberdeen	SN		SG 52 VFJ	MB	O814D	WDB6703742N105691	Pn	028.5MAE4869	C33F	
Central Taxis {Central Coaches}, Aberdeen	SN		SN 08 HVA	MB	O816D	WDB6703742N127443	UNVI		C33F	
Central Taxis {Central Coaches}, Aberdeen	SN		SN 51 OJA	MB	O814D	WDB6703742N098543	?		C24F	
Central Taxis {Central Coaches}, Aberdeen	SN		SN 56 FEP	MB	O814D	WDB6703732N122123	KVC		C28F	
Central Taxis {Central Coaches}, Aberdeen	SN		SN 57 EHC	MB	O813D	WDB6703732N126100	KVC		C28F	
Central Taxis {Central Coaches}, Aberdeen	SN		SV 06 VFO	Fd	Tt	WF0EXXTTFE6S22451	Fd		M11	
Central Taxis {Central Coaches}, Aberdeen	SN		SV 07 KXS	Oe	M780SE	SABDNEAB07R192820	Oe		B26F	(07-D-39306)
Central Taxis {Central Coaches}, Aberdeen	SN		SV 14 HWG	Fd	Tt	WF0DXXTTFDDK73922	Fd		M16	
Central Taxis {Central Coaches}, Aberdeen	SN		SV 14 HXW	Fd	Tt	WF0DXXTTFDDK73035	Fd		M16	
Central Taxis {Central Coaches}, Aberdeen	SN	(x)	SV 56 ZTC	Fd	Tt	WF0XXXBDFX6B46895	?		M8	
Central Taxis {Central Coaches}, Aberdeen	SN	(x)	SV 56 ZTS	Fd	Tt	WF0XXXBDFX6B46894	?		M8	
Central Taxis {Central Coaches}, Aberdeen	SN	(x)	SV 56 ZVE	Fd	Tt	WF0XXXBDFX6B46899	?		M8	
Central Taxis {Central Coaches}, Aberdeen	SN		SV 64 KRF	Fd	Tt	WF01XXTTG1EM59973	Fd		M9	
Central Taxis {Central Coaches}, Aberdeen	SN		SW 10 HBN	Fd	Tt		Fd		M16	
Central Taxis {Central Coaches}, Aberdeen	SN		SW 10 HRC	Fd	Tt	WF0DXXTTFD9E48931	Fd		M16	
Central Taxis {Central Coaches}, Aberdeen	SN		SY 05 DRX	MB	O814D	WDB6703742N117495	Pn	058.5MXW5980	DP29FL	

Central Taxis {Central Coaches}, Aberdeen	SN		T 9 MCS	Vo	B10M-55	YV31MA712XA050305	VH	33803	C49FT	(ex D 5 CTC, T 9 MCS)
Central Taxis {Central Coaches}, Aberdeen	SN		WA 14 CMU	MB	O816D	WDB6703742N149960	UNVI		C33F	
Central Taxis {Central Coaches}, Aberdeen	SN		WX 06 UWB	MB	O814D	WDB6703732N122955	UVM	10918	B28FL	
Central Taxis {Central Coaches}, Aberdeen	SN		WX 06 UWL	MB	O814D	WDB6703732N123036	UVM	10925	B28FL	
Central Taxis {Central Coaches}, Aberdeen	SN		X257 NSS	MB	O814D	WDB6703742N094804	Leinster		C24F	
Central Taxis {Central Coaches}, Aberdeen	SN		YN 06 CYJ	MB	O814D	WDB6703742N122522	Pn		C29F	
Central Taxis {Central Coaches}, Aberdeen	SN		YN 09 HRE	Au	N5218SHFL	WAGP12ZZ8B5001394	Au	P12-0347	C36FT	(ex MF 11 LUH, 152 JUP, ODR 29, MF 11 LUH)
Central Taxis {Central Coaches}, Aberdeen	SN		YX 54 ATY	MB	O814D	WDB6703742N113206	Pn	048.5MAE5403	C33F	
Cheyne, Daviot	SN		OTC 950	Vo	B10M-62	YV31MA615VC060409	VH	33021	C70F	(ex R609 CJS, OTC 950, R609 CJS)
Cheyne, Daviot	SN		CU 03 LXH	Fd	Tt	WF0EXXGBFE3L77653	Fd		M16	
Cheyne, Daviot	SN		FV 13 DLJ	Fd	Tt	WF0DXXTTFDCS01348	Fd		M16	
Cheyne, Daviot	SN		FV 63 AOK	Fd	Tt	WF0DXXTTFDDK73122	Fd		M16	
Clark, Stromness	SN		YN 06 CFM	MB	O814D	WDB6703732N121327	KVC		C28F	
Classy Taxis {Freddies Taxis}, Fraserburgh	SN		CE 52 TNK	Rt	Mtr	VF1FDCMM527157711	?		M16	
Classy Taxis {Freddies Taxis}, Fraserburgh	SN	(x)	EO 02 OAM	Rt	Mtr	VF1FDCGJ525244052	?		M8	
Classy Taxis {Freddies Taxis}, Fraserburgh	SN	(x)	EU 03 BVB	Rt	Mtr	VF1FDCUL528207847	?		M8L	
Classy Taxis {Freddies Taxis}, Fraserburgh	SN		EU 08 KPY	Rt	Mtr	VF1FDC2LH38934724	Wnr		M16L	
Classy Taxis {Freddies Taxis}, Fraserburgh	SN		HX 05 HGK	Rt	Mtr	VF1PDMVL532221539	?		M8L	
Classy Taxis {Freddies Taxis}, Fraserburgh	SN		LX 08 GRU	Rt	Mtr	VF1NDD1L640137390	Rt		M15	
Classy Taxis {Freddies Taxis}, Fraserburgh	SN	(r)	S956 LFT	Rt	Mtr	VF1FDCLE519399048	St		M13	
Classy Taxis {Freddies Taxis}, Fraserburgh	SN		SF 05 GCV	VW	LT46	WV1ZZZ2DZ5H021773	Drv		M6L	
Classy Taxis {Freddies Taxis}, Fraserburgh	SN		SF 05 GCY	VW	LT46	WV1ZZZ2DZ5H021930	Drv		M6L	
Classy Taxis {Freddies Taxis}, Fraserburgh	SN		T 10 CTL	Rt	Mtr	VF1MEN5JE47709561	Rt		M16	(ex SF 62 JXS)
Classy Taxis {Freddies Taxis}, Fraserburgh	SN		T 20 CTL	Rt	Mtr	VF1MEN4JE45922681	Rt		M16	(ex YJ 61 GYX)
Classy Taxis {Freddies Taxis}, Fraserburgh	SN		T 30 CTL	Rt	Mtr	VF1MEN4JE45922680	Rt		M16	(ex YJ 61 GYW)
Classy Taxis {Freddies Taxis}, Fraserburgh	SN	(x)	X675 AAY	Rt	Mtr	VF1FDCCL522718362	?		M8	
Classy Taxis {Freddies Taxis}, Fraserburgh	SN	(x)	YH 51 KWD	Rt	Mtr	VF1FDCCL525046466	?		M8	
Classy Taxis {Freddies Taxis}, Fraserburgh	SN		YK 04 EYG	Rt	Mtr	VF1PDMVL530248806	Me	11596	M16	
Classy Taxis {Freddies Taxis}, Fraserburgh	SN		YK 58 WKB	Rt	Mtr	VF1NDD1L640550123	Rt		M15	
Comhairle, Stornaway	SN		BU 05 EHG	BMC	1100FE	NMC111TKCRD200081	BMC		B55FL	(BU05EHG/05-D-68772)
Comhairle, Stornaway	SN		BX 06 OCZ	BMC	1100FE	NMC111TKCRD200103	BMC		B55FL	
Comhairle, Stornaway	SN	(x)	SC 05 ZWG	Fd	Tt	WF0EXXTTFE5B17153	Fd		M16	
Comhairle, Stornaway	SN	(x)	SG 04 FHH	Fd	Tt	WF0EXXGBFE3M55428	Fd		M16	

Comhairle, Stornaway	SN	(x)	SH 56 HUY	Fd	Tt	WF0DXXTTFD6B55554	Fd		M16L	
Comhairle, Stornaway	SN	(x)	SH 56 HVF	Fd	Tt	WF0DXXTTFD6B56410	?		M??L	
Comhairle, Stornaway	SN	(x)	SH 56 LVF	Fd	Tt	WF0DXXTTFD6B56412	?		M??L	
Comhairle, Stornaway	SN	(x) Z405	SX 53 EJV	VW	LT35	WV1ZZZ2DZ4H015667	?		M8	
Comhairle, Stornaway	SN	(x) Z406	SX 53 EJV	VW	LT35	WV1ZZZ2DZ4H015588	?		M8	
Comhairle, Stornaway	SN	(x)	SX 53 FGK	VW	LT35	WV1ZZZ2DZ4H016062	?		M??L	
Comhairle, Stornaway	SN	(x)	SX 53 FGM	VW	LT35	WV1ZZZ2DZ4H016210	?		M??L	
Comhairle, Stornaway	SN	(x) Z407	SX 53 HCF	VW	LT35	WV1ZZZ2DZ4H016154	?		M8	
Comhairle, Stornaway	SN	(x)	SX 53 HCG	VW	LT35	WV1ZZZ2DZ4H016088	?		M??L	
Comhairle, Stornaway	SN	(x)	SX 53 HCH	VW	LT35	WV1ZZZ2DZ4H016211	?		M??L	
Comhairle, Stornaway	SN	(x)	SX 53 HCJ	VW	LT35	WV1ZZZ2DZ4H019674	?		M??L	
Comhairle, Stornaway	SN	(x)	SY 55 SYU	Fd	Tt	WF0LXXTTFL5B04449	?		M??L	
Comhairle, Stornaway	SN		YJ 05 KOW	BMC	1100FE	NMC111TKCRD200053	BMC		B55FL	(YJ05KOW/05-D-85090)
Comhairle, Stornaway	SN		YJ 05 PUX	BMC	1100FE	NMC111TKCRD200054	BMC		B55FL	
Comhairle, Stornaway	SN		YJ 14 BDU	Oe	M9600SR	SABTW4AF0ES290897	Oe		B34F	
Comhairle, Stornaway	SN		YJ 14 BDV	Oe	M9600SR	SABTW4AF0ES290898	Oe		B34F	
Comhairle, Stornaway	SN		YJ 14 BDX	Oe	M9600SR	SABTW4AF0ES290899	Oe		B34F	
Comhairle, Stornaway	SN		YJ 14 BDY	Oe	M9600SR	SABTW4AF0ES290900	Oe		B34F	
Comhairle, Stornaway	SN		YJ 14 BDZ	Oe	M9600SR	SABTW4AF0ES290901	Oe		B34F	
Comhairle, Stornaway	SN		YK 05 BAU	BMC	1100	NMC111TKCRD200069	BMC		B55FL	
Comhairle, Stornaway	SN		YN 07 KGU	VDL	SB200	XMGDE02CS0H014166	Pn	0611.9LBA6405	B42F	
Comhairle, Stornaway	SN	(x)	BX 65 KLM	Rt	Mtr	VF1MAF4RC53530284	MinO		M8L	
Comhairle, Stornaway	SN		MK 63 XAA	AD	E20D	SFD7E1AR6CGY13430	AD	C250/4	B39F	
Cormack {Beaulay Coach Hire}, Beaulay	SN		MX 05 LKO	Io	50C13	ZCFC5090005511321	MinO		M16L	
Cormack {Beaulay Coach Hire}, Beaulay	SN		SF 53 KUT	MB	O814D	WDB6703742N110552	Tbs		DP33F	(SF53KUT/K 90SBL)
Corsie, Dounby	SN		SV 04 COH	Fd	Tt	WF0EXXTTFF4567303				
Corsie, Dounby	SN		SY 10 BGU	Fd	Tt	WF0DXXTTFD9D24493	Fd		M16	
Crestmount {Highland Taxis}, Inverness	SN		W895 WHS	VW	LT46	WV1ZZZ2DZYH023960	?		M16	
Crestmount {Highland Taxis}, Inverness	SN	(x)	WK 52 DLE	VW	LT35	WV1ZZZ2DZ3H014961	?		M8	
Crestmount {Highland Taxis}, Inverness	SN		Y116 TSU	VW	LT35	WV1ZZZ2DZ1H010750	?		M16	
D										
D & E Coaches ,Inverness	SN		YJ 17 DDA	Tmsa	MD9	NLTAPLJ6R01000038	Tmsa	-?-	C35F	
D & E Coaches, Inverness	SN		B 1 YST	Vo	B10M-62	041689	VH	31887	C46FT	(M662KVU)
D & E Coaches, Inverness	SN		B 2 YST	Ba	FHD12-340	XL9AA18P230003799	Ba		C49FT	(SF03AUH)]
D & E Coaches, Inverness	SN		B 3 YST	MB	515CDI	WDB9066552S177542	KVC		M16	(SN08GFA/BU53DEC/S 3YST)
D & E Coaches, Inverness	SN		B 5 YST	Ba	FHD12-340	XL9AA18CGX7003592	Ba		C51FT	(T 2LEC/916VBH/T 2LEC)
D & E Coaches, Inverness	SN		B 6 YST	Ba	FHD12-370	XL9AA18CGY8003138	Ba		C53F	(V 11BUS/V435EHH/M 99BUS)
D & E Coaches, Inverness	SN		B 7 YST	MB	1223L	WDB9702472L134511	UNVI		C33F	(YN57DVVW)
D & E Coaches, Inverness	SN		B 8 YST	Vo	B10M-55	YV31MA515TA045807	Ar	9606/21	B49F	(P821FVU)
D & E Coaches, Inverness	SN		B 9 YST	Vo	B10M-62	YV31M2B19TC060096	Pn	9612VUP4745	C53F	(ex N224 HWX, OAS 578, N224 HWX) (ex Y658 HWY, KFO 809, Y658 HWY, XAT 11X, Y658 HWY)
D & E Coaches, Inverness	SN		B 10 YST	Ba	FHD12-270	XL9AA18CG18003968	Ba		C75F	(R208WYD/PUI3786)
D & E Coaches, Inverness	SN		B 13 YST	Ba	FHD12-333	XL9AA18JGW7003244	Ba		C75F	(SY08NTM/BU52DEC/S 1YST)
D & E Coaches, Inverness	SN	(x)	B 14 YST	VW	Tr	WV2ZZZ7HZ8H096417	?		M8	(WJ02KDF)
D & E Coaches, Inverness	SN		B 15 YST	Ba	FHD12-340	XL9AA18P230003271	Ba		C49FT	(T 87JBA)
D & E Coaches, Inverness	SN		B 17 YST	MB	O814D	WDB6703472N079566	Pn	998.5MXV0664	B31F	(N 3CLA/N347WPT/WSV572/N347WPT)
D & E Coaches, Inverness	SN		B 20 YST	Vo	B10M-62	YV31M2P10TA044834	VH	32552	C49FT	
D & E Coaches, Inverness	SN		BU 56 DEC	MB	O814D	WDB6703742N123665	Pn		B31F	
D & E Coaches, Inverness	SN		BU 58 DEC	MB	O813D	WDB6703742N135180	Pn		B27FL	
D & E Coaches, Inverness	SN		DK 55 BOH	MB	413CDI	WDB9046632R815869	Cpt		M16	(DK55BOH/A 17BNG)

D & E Coaches, Inverness	SN		FJ 05 XYN	MB	O814D	WDB6703742N116872	Pn	058.5MXW5989	B32FL	
D & E Coaches, Inverness	SN		FJ 05 XYT	MB	O814D	WDB6793742N116851	Pn	058.5MXW5987	B32FL	
D & E Coaches, Inverness	SN		J782 KHD	DAF	MB230LT615	XLACE02LT00313930	VH	30552	C51FT	(ex B 12 YST, J782 KHD)
D & E Coaches, Inverness	SN		M 5 YST	Ba	FHD12-333	XL9AA18JGV6003884	Ba		C75F	(P928KYC/PUI3788/P928KYC)
D & E Coaches, Inverness	SN		M 6 YST	Vo	B10M-55	YV31MA51XVC060357	Ar	9417/20	B49F	(P855GND)
D & E Coaches, Inverness	SN		M 7 YST	Vo	B10M-55	YV31MA516VC060355	Ar	9417/18	B49F	(P853GND)
D & E Coaches, Inverness	SN		M 8 YST	Ba	FHD12-340	XL9AA18CGW7003357	Ba		C75F	(R 2AVC)
D & E Coaches, Inverness	SN		M 9 YST	Vo	B10M-55	YV31MA518VA047330	Ar	9633/29	B49F	(P559ESA)
D & E Coaches, Inverness	SN		M 14 YST	Vo	B10M-55	YV31MA51XVA047331	Ar	9633/30	B49F	(P660ESO)
D & E Coaches, Inverness	SN		OU 62 CVF	MB	516CDI	WDB9066572S645356	?		M16	
D & E Coaches, Inverness	SN		P 2 YST	Vo	OLY-50	YV3YNA413VC028394	ArB	D25.12	H47/25D	(97-D-378/R340LHK)
D & E Coaches, Inverness	SN		P 3 YST	Vo	OLY	YV3YNA413VC027908	ArB	D23.16	H47/31F	(97-D-361/R342LHK)
D & E Coaches, Inverness	SN		P 4 YST	Vo	OLY	YV3YNA419VC028299	ArB	D24.20	H47/31F	(97-D-365/R358LHK)
D & E Coaches, Inverness	SN		P 5 YST	Vo	OLY	YV3YNA41XVC027906	ArB	D23.15	H47/31F	(97-D-360/R363LHK)
D & E Coaches, Inverness	SN		P 6 YST	Vo	OLY	028355	ArB	D25.12	H47/31F	(97-D-377/R364LHK)
D & E Coaches, Inverness	SN		P 7 YST	Vo	OLY-50	YV3YNA416VC028339	ArB	D25.07	H47/31F	(97-D-372/R367LHK)
D & E Coaches, Inverness	SN		P 8 YST	Vo	OLY-50	YV3YNA413VC028332	ArB	D25.04	H47/25D	(97-D-389/R393LHK)
D & E Coaches, Inverness	SN		P 9 YST	Vo	B7TL	YV3S2G5121A001631	Ar	0108/29	H49/27F	(ex LW 51 ZGU, 01-D-10214)
D & E Coaches, Inverness	SN		P 10 YST	Vo	B7TL	YV3S2G5172A001707	Ar	0108/37	H49/27F	(ex LW 51 ZWM, 01-D-10222)
D & E Coaches, Inverness	SN		P 12 YST	Vo	B7TL	YV3S2C618YA001070	Ar	0006/15	H49/25F	(ex X189 H CJ, 00-D-40056)
D & E Coaches, Inverness	SN		P 15 YST	Vo	B7TL	YV3S2C6181A001141	Ar	0029/44	H49/25F	(ex X122 HKY, 00-D-40071)
D & E Coaches, Inverness	SN		P 16 YST	Vo	B7TL	YV3S2G5152A002113	Ar	0197/27	H49/27F	(ex SJ 02 AJA, 02-D-10256)
D & E Coaches, Inverness	SN		P 17 YST	Vo	B7TL	YV3S2G5192A002115	Ar	0197/29	H49/27F	(ex SJ 02 AAT, 02-D-10258)
D & E Coaches, Inverness	SN		P125 XCN	Vo	B10M-55	YV31MA51XVC060388	Ar	9417/50	B49F	
D & E Coaches, Inverness	SN		P543 MSF	MB	711D	WDB6693032N046400	UVG	5516/94	B22FL	
D & E Coaches, Inverness	SN		P786 SWC	Vo	YN2RV18V3	YV3YNA413VC027617	ArB	D23.14	H47/31F	(97-D-344)
D & E Coaches, Inverness	SN		P823 FVU	Vo	B10M-55	YV31MA519TA045809	Ar	9606/23	B49F	
D & E Coaches, Inverness	SN		P858 GND	Vo	B10M-55	YV31MA51XVC060360	Ar	9417/23	B49F	
D & E Coaches, Inverness	SN		PUI 3786	VW	Tr	WV1ZZZ7HZ6H022487	?		M?	(PV55JBE)
D & E Coaches, Inverness	SN		R236 KRG	Vo	B10BLE	YV3R4AS10VA003101	Ar	9629/1	B44F	(ex M 20 YST, R236 KRG)
D & E Coaches, Inverness	SN		R374 LHK	Vo	OLY	YV3YNA419VC028402	ArB	D25.17	H47/31F	(ex 97-D-382)
D & E Coaches, Inverness	SN		R649 YCR	MB	O810D	WDB6703732N066973	UVG	5727/97	DP23FL	
D & E Coaches, Inverness	SN		RJ 60 UNX	Fd	Tt	WF0DXTTFFDAA82055	Fd		M16	
D & E Coaches, Inverness	SN		RX 05 EOS	MB	413CDI	WDB9046632R758838	Eurm	13441/6 05	M14	
D & E Coaches, Inverness	SN		S 1 YST	VDL	SB4000	XMGDE40PS0H010185	VH	37213	C53F	(YJ10DJK)
D & E Coaches, Inverness	SN		S 3 YST	Vo	B12B	YV3R8M9298A124285	Pn	0712TML7425	C53F	(ex OO 08 SOU, SN 58 JAU)
D & E Coaches, Inverness	SN		S 5 YST	Vo	B12M	YV3R8G1206A112391	Pn	0612TKT6511	C53F	(SM06SOU)
D & E Coaches, Inverness	SN		S 9 YST	Vo	B11R	YV3T2S820CA154863	Co		C49FT	(12-D-25433/BP12ZBD)
D & E Coaches, Inverness	SN		S 10 YST	Ba	FHD12-340	XL9AA18P230003188	Ba		C49FT	(WA51JYN/PG51GAR/S 1YST)
D & E Coaches, Inverness	SN		S 11 YST	Vo	B10M-55	YV31MA7101A053310	VH	33840	C49FT	(Y288RSO/HSV725/Y288RSO)
D & E Coaches, Inverness	SN		S 12 YST	VDL	SB4000	XMGDE40PS0H016142	VH	37189	C49FT	(AY08DXF)
D & E Coaches, Inverness	SN		S 14 YST	VDL	SB4000	XMGDE40XS0H014623	VH	37135	C49FT	(YJ07JFY)
D & E Coaches, Inverness	SN		S 15 YST	VDL	SB4000	XMGDE40PS0H010186	VH	37214	C53F	(ex YJ 10 DJO)
D & E Coaches, Inverness	SN		S 22 YST	VDL	SB4000	XMGDE40PS0H015760	VH	31785	C53F	(ex DF 08 XUC, L 2 HCR, VR 08 HCR)
D & E Coaches, Inverness	SN		S 33 YST	DAF	DE40XSSB4000	XMGDE40XS010992	VH	37079	C49FT	(ex B 12 FWS, YJ 04 BYF)
D & E Coaches, Inverness	SN		S 50 YST	Vo	B7RLE	YV3R6K6278A123120	Pn	0712TGA7335	B46F	(ex FD 57 VYA)
D & E Coaches, Inverness	SN		S 60 YST	Vo	B7RLE	YV3R6K6208A122990	Pn	0712TGA7331	B46F	(ex FD 57 VYC)
D & E Coaches, Inverness	SN		S 66 YST	Oe	M9600SR	SABFW3AF0AL290051	Oe		B22F	(ex YJ 10 MGE)
D & E Coaches, Inverness	SN		S 70 YST	Vo	B7RLE	YV3R6K6218A123078	Pn	0712TGA7334	B46F	(ex FD 57 VYE)
D & E Coaches, Inverness	SN		S 77 YST	Oe	M9600SR	SABFW3AF0AL290050	Oe		B22F	(ex YJ 10 MGO)
D & E Coaches, Inverness	SN		S 88 YST	DAF	SB120	XMGDE12BS0H010219	Wt	F509	B39F	(ex YG 52 CEN)
D & E Coaches, Inverness	SN		S 99 YST	DAF	SB120	XMGDE12CS0H010214	Wt	F504	B39F	(ex YG 52 CDZ)
D & E Coaches, Inverness	SN		SJ 16 ZZT	Vo	B11R	YV3T2U827GA175839	Je	-?	C53FT	
D & E Coaches, Inverness	SN		SJ 16 ZZU	Vo	B11R	YV3T2U82XGA175835	Je	-?	C53FT	
D & E Coaches, Inverness	SN		SK 03 AXF	Sca	K124IB4	1843618	VH	36121	C49FT	(ex 318 DHR, SK 03 AXF, PSU 614, SK 03 AXF, 03-KK-1870)
D & E Coaches, Inverness	SN		SK 17 HHG	Wt	StLt WF	SA9DSRXXX16141260	Wt	AM136	B37F	

D & E Coaches, Inverness	SN		SK 17 HHJ	Wt	StLt WF	SA9DSRXXX16141266	Wt	-?-	B37F	
D & E Coaches, Inverness	SN		SN 54 FHA	MB	O814D	WDB6703732N114041	KVC		C24F	(ex W 6AMY, SN 54 FHA, V 11 HFT, SN 54 FHA)
D & E Coaches, Inverness	SN		SN 56 OLH	Fd	Tt	WF0DXXTTFD6B69037	Fd		M16	
D & E Coaches, Inverness	SN		SY 62 CVL	Wt	StLt WF	SA9DSRXXX12141149	Wt	AH001	B33F	
D & E Coaches, Inverness	SN		V984 DNB	MB	O814D	WDB6703742N085430	Pn	998.5MXW1525	DP32FL	
D & E Coaches, Inverness	SN		Y404 BVV	MB	O814D	WDB6703742N096649	ACI	1779	C32F	(ex KFO 809, Y404 BVV)
D & E Coaches, Inverness	SN		YA 10 CFX	MB	515CDI	WDB90665725419896	?		M16	
D & E Coaches, Inverness	SN		YJ 10 DVA	Tmsa	Safari HD	NLTRJTA7R01010006	Tmsa		C47FT	(ex B 9 YST, YJ 10 DVA)
D & E Coaches, Inverness	SN		YJ 10 DVC	Tmsa	Safari HD	NLTRJTA7R01010008	Tmsa	OA04820	C47FT	(ex B 10 YST, YJ 10 DVC, 10-D-121770, YJ 10 DVC)
D & E Coaches, Inverness	SN		YJ 16 EHM	Tmsa	MD9	NLTAPLJ6R01000011	Tmsa	-?-	C34FT	
D & E Coaches, Inverness	SN		YJ 16 EHN	Tmsa	MD9	NLTAPLJ6R01000012	Tmsa	-?-	C34FT	
D & E Coaches, Inverness	SN		YJ 17 DDN	Tmsa	MD9	NLTAPLJ6R01000041	Tmsa	-?-	C35F	
D & E Coaches, Inverness	SN		YJ 62 JWF	VDL	SB180	XMGDE18FS0H021270	MCV	MCV-550	B34F	
D & E Coaches, Inverness	SN		YJ 62 NHL	VDL	FHD2-129.355	XNL501E100D001584	VDL		C51FT	(ex SC 07 BUS, YJ 62 NHL)
D & E Coaches, Inverness	SN		YN 04 WTV	Vo	B12B	YV3R8F8164A014776	Pn	0412TKL5541	C49FT	(ex BSK 789, YN 04 WTV)
D & E Coaches, Inverness	SN		YN 12 BKU	MB	O816D	WDB6703742N145544	Pn	CC 02	C29F	
D & E Coaches, Inverness	SN		YR 52 MDN	MB	O814D	WDB6703742N105927	Pn	028.5MAE4882	C33F	
D & E Coaches, Inverness	SN		YX 63 ZVJ	AD	E20D	SFD7E1AR6DGY13820	AD	D226/02	B37F	
D & E Coaches, Inverness	SN		YX 63 ZVN	AD	E20D	SFD7E1AR6DGY13824	AD	D226/06	B37F	
DA Travel, Kilphedar	SN		EX 52 TWA	Sca	K114EB	YS4K4X20001840502	VH	36071	C53F	
DA Travel, Kilphedar	SN		L926 UGA	MB	814D	WDB6703132N004137	Do		C33F	
DA Travel, Kilphedar	SN	(r)	P175 ANR	Ds	Jv	12SDA2155/1443	Co	667001	C57F	
DA Travel, Kilphedar	SN		R 68 GNW	DAF	DE33WSSB3000	XMGDE33W50H005664	VH	32845	C51F	(R 68GNW/HIL7613)
DA Travel, Kilphedar	SN		S 9 BJT	Ds	Jv	SFD731BR3WGJE2167	Pn	9812GHM9474	C53F	
DA Travel, Kilphedar	SN		SF 09 GWD	MB	O813D	WDB6703742N129235	Pn	078.5MXV7352	DP31FL	
DA Travel, Kilphedar	SN		SF 57 EUE	MB	O814D	WDB6703742N129466	Pn		DP30FL	
DA Travel, Kilphedar	SN		SX 02 PZO	Ds	Jv	SFD721BR41GJ22414	Pn	0212GFM4693	C55F	(ex VU 02 CZK)
DA Travel, Kilphedar	SN		VU 02 CZK	Ds	Jv	-?-	Pn	-?-	C53F	(?)
DA Travel, Kilphedar	SN		Y878 CGN	LDV	Cy	SEYZMVSHEDN073691	LDV		M16	
DA Travel, Kilphedar	SN		YD 15 JHJ	Fd	Tt	WF0HXXTTGHHER01959	Fd		M16	
DA Travel, Kilphedar	SN		YK 16 UFL	Fd	Tt	WF0HXXTTGHFP34094	Fd		M16	
DA Travel, Kilphedar	SN		YK 16 UFN	Fd	Tt	WF0HXXTTGHFP34093	Fd		M16	
DAB Plus, Maud	SN	(x)	BX 56 YLP	Rt	Mtr	VF1FDCVL536013729	MinO		M15L	
DAB Plus, Maud	SN		FJ 12 CNO	Ft	Do	ZFA25000002079992	MinO		M15L	
DAB Plus, Maud	SN		FJ 13 GFG	Ft	Do	ZFA25000002281367	MinO		M16L	
DAB Plus, Maud	SN		LV 52 KCF	VW	LT46	WV1ZZZ2DZ2H032110	?		M15	
DAB Plus, Maud	SN		MT 64 ACJ	VW	CrF	WV1ZZZ2ZE6036236	MinO		M15L	
DAB Plus, Maud	SN	(x)	MX 04 FLN	Fd	Tt	WF0LXXGBFL3P61191	?		M7L	
DAB Plus, Maud	SN		MX 08 KLP	VW	CrF	WV1ZZZ2EZ86007882	?		M15L	
DAB Plus, Maud	SN	(x)	MX 54 GBE	VW	LT35	WV1ZZZ2DZ5H005441	?		M10L	
DAB Plus, Maud	SN	(x)	MX 54 GCF	VW	LT35	WV1ZZZ2DZ5H009933	?		M10L	
DAB Plus, Maud	SN		MX 58 AUP	VW	CrF	WV1ZZZ2EZ96005502	?		M16	
DAB Plus, Maud	SN	(x)	NX 04 FLN	Fd	Tt	WF0LXXGBFL3P61191	?		M8L	
DAB Plus, Maud	SN	(x)	X198 DBT	VW	LT46	WV1ZZZ2DZ1H013168	?		M12L	
Deveron Coaches, Macduff	SN		699 NAE	MB	O814D	WDB6703742N113652	ACI	1866	C33F	(YN54BGZ)
Deveron Coaches, Macduff	SN		AF 07 MWG	Fd	Tt	WF0DXXTTFD6B69034	Fd		M16	
Deveron Coaches, Macduff	SN		BX 14 KOD	KL	XMQ6129	LA6A1LBS8DB105435	KL		C53FT	
Deveron Coaches, Macduff	SN		CV 06 DXS	Fd	Tt	WF0EXXTTFE5C79235	Fd		M16	
Deveron Coaches, Macduff	SN		GT 03 MMM	Vo	B12M	YV3R9F8163A001019	Je	26535	C51FT	
Deveron Coaches, Macduff	SN		GT 03 PPP	Vo	B12M	YV3R9F8163A001036	Je	26536	C46FT	
Deveron Coaches, Macduff	SN		GT 03 SSS	Vo	B12M	YV3R9F8183A001037	Je	26537	C46FT	
Deveron Coaches, Macduff	SN		GT 03 TTT	Vo	B12M	YV3R9F81X3A001038	Je	26538	C46FT	
Deveron Coaches, Macduff	SN		GT 03 VVV	Vo	B12M	YV3R9F8193A001046	Je	26539	C46FT	
Deveron Coaches, Macduff	SN		GT 03 WWW	Vo	B12M	YV3R9F8113A001283	Tbs	0312JT5033	C46FT	
Deveron Coaches, Macduff	SN		HT 53 HJN	Fd	Tt	WF0EXXGBFE3E48623	Fd		M16	

Deveron Coaches, Macduff	SN		M321 RAW	Vo	B10M-62	YV31M2B17SA042318	Pn	9512VUP3420	C53F	(M321RAW/3408NT)
Deveron Coaches, Macduff	SN		MW 52 PYP	Oe	M850	SAB19000000000901	Oe		B26F	
Deveron Coaches, Macduff	SN		MX 03 AEA	Vo	B12M	YV3R9F8123A000904	Je	26427	C48FT	
Deveron Coaches, Macduff	SN		MX 05 OTE	Oe	M880	SAB19000000001764	Oe		B26F	
Deveron Coaches, Macduff	SN		MX 06 ABV	Oe	M850	SAB19000000001800	Oe		B30F	
Deveron Coaches, Macduff	SN		MX 10 DWO	Io	45C15	ZCFC45A200D384995	Onyx	916	C19F	
Deveron Coaches, Macduff	SN		MX 16 BGK	KL	XMQ6127	LA6R1KSS7GB401015	KL		C49FT	
Deveron Coaches, Macduff	SN		MX 16 BGO	KL	XMQ6900	LA6R1DSEXDB105357	KL		C35F	
Deveron Coaches, Macduff	SN		MX 53 ZWE	MB	O814D	WDB6703732N108131	Onyx	634	C24F	
Deveron Coaches, Macduff	SN		N993 THO	Vo	B10M-62	YV31M2B1XTA044680	Pn	9612VUS4682	C49FT	(A 2XEL)
Deveron Coaches, Macduff	SN		NC 04 NHG	Fd	Tt	WF0EXXGBFE3M55374	Fd		M16	
Deveron Coaches, Macduff	SN		NK 02 EXB	Fd	Tt	WF0EXXGBFE1C15535	Fd		M14	
Deveron Coaches, Macduff	SN		NV 56 WVH	Fd	Tt	WF0DXXTTFD6B69462	Fd		M14	
Deveron Coaches, Macduff	SN		P314 CVE	Vo	B10M-62	YV31M2B18TA044080	Pn	9512VUP4475	C52F	
Deveron Coaches, Macduff	SN		P364 JJU	Vo	B10M-62	YV31MA619VA046458	Pn	9612VUP6281	C53F	(97-D-7825)
Deveron Coaches, Macduff	SN		P413 TNG	Vo	B10M-62	YV31MA615TC060178	Je	24198	C53F	
Deveron Coaches, Macduff	SN		R901 WEC	Vo	B10M-62	YV31MA612WA048652	Pn	9812VUP7810	C70F	
Deveron Coaches, Macduff	SN		S588 ACT	MB	O814D	WDB6703742N075825	ACI	1568	C33F	(S588ACT/WLT982)
Deveron Coaches, Macduff	SN		SF 09 GWL	MB	O816D	WDB6703742N135358	Pn	088.5MBJ8044	C33F	
Deveron Coaches, Macduff	SN		SF 12 GXH	MB	O816D	WDB6703742N145018	Pn	BC03/01	C29F	
Deveron Coaches, Macduff	SN		SF 17 EDR	VDL	FHD2-122	XNL501E100D006751	VDL		C53F	
Deveron Coaches, Macduff	SN		SF 53 KUR	Tbs	Dt SLF	SFD6BACR32GW16633	Tbs	2013/6	B29F	
Deveron Coaches, Macduff	SN		SJ 52 XLC	Fd	Tt	WF0EXXGBFE2L68082	Fd		M16	
Deveron Coaches, Macduff	SN		SK 05 RRU	Fd	Tt	WF0EXXTTFE5U37893	Fd		M16	
Deveron Coaches, Macduff	SN		SN 03 JWG	MB	817L	WDB6764642K292070	Leinster		C33F	
Deveron Coaches, Macduff	SN		SN 09 LSE	MB	O816D	WDB6703742N135470	Pn	088.5MBJ8123	C29F	(B 12DWA/SN09LSE/MIL6696)
Deveron Coaches, Macduff	SN		ST 15 JFE	Fd	Tt	WF0HXXTTGHEM47980	Fd		M16	
Deveron Coaches, Macduff	SN		SV 05 VHE	Fd	Tt	WF0EXXTTFE5M71786	Fd		M16	
Deveron Coaches, Macduff	SN		T802 FRU	Vo	B10M-62	YV31MA617XC061094	Pn	9912VUP0212	C49FT	(A 18XEL)
Deveron Coaches, Macduff	SN		V350 EKY	MB	O814D	WDB6703742N077692	Pn	988.5MZE9732	C33F	
Deveron Coaches, Macduff	SN		VIB 9485	Sca	K113CRB	1826448	VH	32176	C51FT	(N921DWJ)
Deveron Coaches, Macduff	SN		WA 03 CWF	LDV	Cy	SEYZMVXZGDN094997	LDV		M16	
Deveron Coaches, Macduff	SN		X223 HCD	MB	O814D	WDB6703742N097080	Pn	008.5MZE3412	C25F	(X223HCD/S10BUS)
Deveron Coaches, Macduff	SN		Y200 BCC	Au	N316SHD	WAG2031621BD32025	Au	33160830	C49FT	
Deveron Coaches, Macduff	SN		Y302 KBN	Vo	B10M-62	YV31MA6121A052774	VH	33602	C53F	
Deveron Coaches, Macduff	SN	(z)	Y313 KDP	Vo	B6BLE	YV3R3A9131A010356	EL	32112	B26F	
Deveron Coaches, Macduff	SN		Y342 AUT	Vo	B10M-62	YV31MA7111A053221	Bf	4361	C51FT	
Deveron Coaches, Macduff	SN		Y463 RSO	MB	O814D	WDB6703742N090085	Pn	008.5MZE3155	C27F	(Y106XKR/?)
Deveron Coaches, Macduff	SN		Y546 CDS	MB	O815D	WDB6703742N094473	Sitcar	1644	C27F	(Y546CDS/MIL7525/TIW8406)
Deveron Coaches, Macduff	SN		Y701 HWT	Vo	B10M-62	YV31MA6101A053325	Je	25919	C48FT	(Y701HWT/7243WA)
Deveron Coaches, Macduff	SN		Y702 HWT	Vo	B10M-62	YV31MA6121A053326	Je	25920	C48FT	(Y702HWT/3333WA)
Deveron Coaches, Macduff	SN		Y703 HWT	Vo	B10M-62	YV31MA6141A053327	Je	25921	C48FT	(Y703HWT/7820WA)
Deveron Coaches, Macduff	SN		Y704 HWT	Vo	B10M-62	YV31MA6121A053357	Je	25922	C48FT	(Y704HWT/8665WA)
Deveron Coaches, Macduff	SN		Y707 HWT	Vo	B10M-62	YV31MA6141A053408	Je	25925	C48FT	
Deveron Coaches, Macduff	SN		Y708 HWT	Vo	B10M-62	YV31MA6161A053409	Je	25926	C48FT	
Deveron Coaches, Macduff	SN		Y718 HWT	Vo	B10M-62	YV31MA6151A053496	Je	25935	C48FT	
Deveron Coaches, Macduff	SN		Y724 HWT	Vo	B10M-62	YM31MA6151A053546	Je	25940	C68F	
Deveron Coaches, Macduff	SN		Y726 HWT	Vo	B10M-62	YV31MA6171A053547	Je	25941	C48FT	
Deveron Coaches, Macduff	SN		Y797 HPG	Vo	B10M-62	YV31MA7171A053143	Bf	4354	C51FT	
Deveron Coaches, Macduff	SN		Y832 HHE	MB	O814D	WDB6703742N098121	Pn	018.5MZE3884	C24F	
Deveron Coaches, Macduff	SN		YC 02 DFJ	Vo	B12M	YV3R9F812A000339	Je	26138	C48FT	
Deveron Coaches, Macduff	SN		YC 02 DFK	Vo	B12M	YV3R9F8162A000340	Je	26169	C48FT	
Deveron Coaches, Macduff	SN		YC 02 DFL	Vo	B12M	YV3R9F8182A000341	Je	26170	C48FT	
Deveron Coaches, Macduff	SN		YC 02 DJK	Vo	B12M	YV3R9F8122A000481	Je	26191	C48FT	
Deveron Coaches, Macduff	SN		YJ 15 APV	Oe	M900SR	SABLD82A3F5291106	Oe		B30F	
Deveron Coaches, Macduff	SN		YJ 62 FCE	Oe	M890SR	SABSWYSCHCS290435	Oe		B30F	
Deveron Coaches, Macduff	SN		YJ 62 FEF	Oe	M890SR	SABSWYSCHCS290443	Oe		B30F	

Deveron Coaches, Macduff	SN		YK 04 KWM	Oe	M850	SAB1900000001487	Oe		B27F	
Deveron Coaches, Macduff	SN		YN 04 LXJ	Oe	Alero	SAB2100000000386	Oe		B14F	
Deveron Coaches, Macduff	SN		YN 05 HVJ	MB	O814D	WDB6703742N115526	Pn	048.5MAE5774	C29F	(YN05HVJ/BU51DEC/YN05HVJ/A 20BNG)
Deveron Coaches, Macduff	SN		YN 53 VBL	MB	O814D	WDB6703742N110586	Tbs	038.5MAE5290	C29F	
Deveron Coaches, Macduff	SN		YR 52 XPA	MB	311CDI	WDB9036622R391752	MB		M14	
Deveron Coaches, Macduff	SN		YX 60 DXZ	MB	O814D	WDB6703742N136327	Pn	108.5MBJ9013	C33F	
Dunnett {CFDA Firm}, Thurso	SN		D 14 CFD	Fd	Tt	WF0DXXTTFD7C65928	Fd		M16	
Dunnett {CFDA Firm}, Thurso	SN		D 15 CFD	Fd	Tt	WF0DXXTTFD7C65930	Fd		M16	
Dunnett {CFDA Firm}, Thurso	SN		D 16 CFD	Fd	Tt	WF0DXXTTFD7C66372	Fd		M16	
Dunnett {CFDA Firm}, Thurso	SN		D 17 CFD	Fd	Tt	WF0DXXTTFD7C66374	Fd		M16	
Dunnett {CFDA Firm}, Thurso	SN		D 18 CFD	Fd	Tt	WF0DXXTTFD7C66376	Fd		M16	
Dunnett {CFDA Firm}, Thurso	SN		D 19 CFD	MB	1523L	WDB9702782K978443	Unvi	34003	C41F	(YN06CFE/R444THO/YN06CFE)
Dunnett {CFDA Firm}, Thurso	SN		D 20 CFD	Fd	Tt	WF0DXXTTFD7C66376	Fd		M16	(SY62OYD)
Dunnett {CFDA Firm}, Thurso	SN		D 22 CFD	Fd	Tt	WF0DXXTTFD7C66376	Fd		M16	(ex SY 12 OMS)
Dunnett {CFDA Firm}, Thurso	SN		SN 61 CXD	MB	516CDI	WDB90665725594172	UNVI	-?-	C22F	
Dunnett {CFDA Firm}, Thurso	SN		SN 61 CXE	MB	516CDI	WDB90665725603479	UNVI	-?-	C22F	
Dunnett {CFDA Firm}, Thurso	SN		SY 12 OMT	Fd	Tt	WF0XXBBDFFCB27102	Fd		M8	
Dunnett {CFDA Firm}, Thurso	SN		SY 12 OMU	Fd	Tt	WF0XXBBDFFCB27103	Fd		M8	
Dunnett {CFDA Firm}, Thurso	SN		SY 12 OMX	Fd	Tt	WF0DXXTTFD7C66376	Fd		M16	
Dunnett {CFDA Firm}, Thurso	SN		SY 58 PHU	Fd	Tt	WF0DXXTTFD8K42063	Fd		M16	
E										
Easter Ross {George Rapson Travel}, Tore	SN		K200 RAP	MB	1018L	WDB9702472K965369	UNVI	-?-	C33F	(ex YN 55 KWJ, KFX 863, YN 55 KWJ)
Easter Ross {George Rapson Travel}, Tore	SN		L309 YDU	MB	709D	WDB6690032N021400	ArB	M24120594	B23F	
Easter Ross {George Rapson Travel}, Tore	SN	(r)	LPT 707T	BI	LH6L	LH-1541	ECW	23643	B43F	
Easter Ross {George Rapson Travel}, Tore	SN		M754 LAX	Vo	B10M-55	YV31M2F19SA043304	Ar	29PS/9412/37	B60F	
Easter Ross {George Rapson Travel}, Tore	SN	(w)	MRJ 265W	Ld	PSU5D/4R	8030654	Pn	8012LC038	C55F	
Easter Ross {George Rapson Travel}, Tore	SN		N200 RAP	MB	O1223L	WDB9702582K881670	UNVI		C37F	(SN04NWS)
Easter Ross {George Rapson Travel}, Tore	SN		N400 RAP	Ka	S415HD	WKK62941123000027	Ka		C49FT	(ex L300 RAP, PG 04 HOF, A 18 EFA, PG 04 HOF, TDL 856, PG 04 HOF)
Easter Ross {George Rapson Travel}, Tore	SN		NK 05 HTO	MB	O814D	WDB6703732N113475	Nuk	-?-	B16FL	
Easter Ross {George Rapson Travel}, Tore	SN		SY 56 ZMX	Fd	Tt	WF0DXXTTFD6G34892	Fd		M14	
Easter Ross {George Rapson Travel}, Tore	SN		V 73 DBB	MB	614D	WDB6683532N074329	Onyx	357	C24F	
Easter Ross {George Rapson Travel}, Tore	SN		WX 55 OHF	MB	413CDI	WDB9046122R816487	UVM	10707	B16FL	
Easter Ross {George Rapson Travel}, Tore	SN		WK 56 PEN	Oe	M950	SABFWJAE06L192259	Oe		B33F	(ex MX 56 NLT)
Edwards {GL Enterprises}, Drumnadrochit	SN		YJ 07 RCO	LDV	Max	SEYL6RXH20N216712	LDV		M16	
Ewen {Fountain Executive}, Dyce	SN		FXI 214	Sca	K114EB4	YS2K4X20001851101	Ir	130368	C49FT	(SN05JWZ)
Ewen {Fountain Executive}, Dyce	SN		FXI 249	MB	616CDI	WDB9056132R758075	UNVI		C19F	(SN55FPU)
Ewen {Fountain Executive}, Dyce	SN		FXI 253	MB	616CDI	WDB9056132R758077	UNVI		C19F	(SN55SPE)
Ewen {Fountain Executive}, Dyce	SN		FXI 688	Sca	K124EB6	YS2K6X20001849463	Ir	102212	C35FT	(YN05HFX/V 11PKF)

Ewen {Fountain Executive}, Dyce	SN		FXI 690	Sca	K124EB6	YS2K6X20001846968	Ir	101454	C34FT	(ex V 5 PKF, YN 54 PKF)
Ewen {Fountain Executive}, Dyce	SN		FXI 724	Sca	K114EB4	1853089	Ir	102279	C49FT	(YN06JXE)
Ewen {Fountain Executive}, Dyce	SN		FXI 782	Sca	K114EB4	YS2K4X20001851194	Ir	130369	C49FT	(SN05JXA)
Ewen {Fountain Executive}, Dyce	SN	(x)	ME 10 EXE	MB	515CDI	WDB9066572S311163	EVM		M8	
Ewen {Fountain Executive}, Dyce	SN	(x)	ME 10 FXE	MB	515CDI	WDB9066572S311162	EVM		M8	
Ewen {Fountain Executive}, Dyce	SN		S559 EKN	Sca	K124IB6	1833157	Ir	91824	C34FT	(ex FXI 690, S559 EKN, 5167 HP, S559 EKN, H 2 KFC, S559 EKN)
Ewen {Fountain Executive}, Dyce	SN		SN 64 BGO	MB	1523L	WDB9670272L841524	UNVI	-?-	C30F	
Ewen {Fountain Executive}, Dyce	SN		SN 65 ABX	MB	1527L	WDB9670272L950223	UNVI	2675	C30F	
F										
Falcon, Dyce	SN	(x)	BK 55 FXZ	Fd	Tt	WF0EXXTTFE5R40073	Fd		M8	
Falcon, Dyce	SN		FJ 02 EZH	Fd	Tt	WF0EXXGBFE2L56997	Fd		M16	
Falcon, Dyce	SN	(x)	GF 52 PZK	Vx	Mov	VN1F9CNL527507575	?		M8L	
Falcon, Dyce	SN		GV 06 RTO	Vx	Mov	VN1F9CVL535533866	?		M11L	
Falcon, Dyce	SN		S981 KST	Rt	Mtr	VF1FDCEL518801297	St		M13	
Falcon, Dyce	SN	(x)	SB 05 GHZ	Fd	Tt	WF0EXXTTFE5M70564	Fd		M8	
Falcon, Dyce	SN	(x)	SC 03 BHY	Fd	Tt	WF0EXXGBFE3K85445	Fd		M8	
Falcon, Dyce	SN		SF 04 HHU	VW	LT35	WV1ZZZ2DZ4H024021	?		M12L	
Falcon, Dyce	SN		SF 53 LUO	VW	LT46	WV1ZZZ2DZ4H003136	FGy	-?-	M14L	
Falcon, Dyce	SN	(x)	SG 05 DUY	VW	LT35	WV1ZZZ2DZ5H018815	Verve		M8	
Falcon, Dyce	SN		SG 52 WXE	VW	LT46	WV1ZZZ2DZ3H003058	O&H	9927	M14L	
Falcon, Dyce	SN		SG 52 WYM	VW	LT46	WV1ZZZ2DZ2H001106	FGy	8507	M14L	
Falcon, Dyce	SN		SJ 54 CCF	Vx	Mov	VN1F9CVL532085164	?		M12L	
Falcon, Dyce	SN	(x)	SO 53 MXD	Fd	Tt	WF0EXXGBFE3M47107	Fd		M8	
Falcon, Dyce	SN	(x)	SP 06 XBW	Fd	Tt	WF0VXXTTFV5M52657	?		M8L	
Falcon, Dyce	SN	(x)	SY 06 WRL	Fd	Tt	WF0EXXTTFE5G66755	Fd		M8	
Falcon, Dyce	SN		WA 56 NCD	Rt	Mtr	VF1FDCWL636661904	?		M12L	
Falcon, Dyce	SN		X173 UFS	VW	LT35	WV1ZZZ2DZ1H012307	Wre	-?-	M12L	
Farley {Bobbysbus}, Auchengill	SN		YF 63 NYP	Fd	Tt	WF0DXXTTFDDC55609	Fd		M16	
Farley {Bobbysbus}, Auchengill	SN		YK 66 VWA	Fd	Tt	WF0HXTTGHFP34096	Fd		M16	
Farrey {Four Seasons}, Duns	SN		W 4 FST	Ka	S431DT	WKK41000213119880	Ka		C17CT	
Ferguson {Aldas}, Lochmaddy	SN	(w)	P381 RBX	Rt	Mtr	VF1FB30AK15159509	Rt		M16	
Ferguson {Traveline}, East Whitburn	SN		SM 16 HBH	MB	513CDI	WDB9066572P157660	?		M16	
Fraser {Kintore Taxis}, Kintore	SN		DJZ 1727	Fd	Tt	WF0EXXGBFE1C24585	Fd		M16	
Fraser, Munloch	SN		A746 ERM	Bd	YNT	ET101647	Du	8320/0264	C53F	
Fraser, Munloch	SN	(w)	BAB 888W	Vo	B58-61	16451	Pn	8012VC114	C57F	(BAB888W/LIB8921)
Fraser, Munloch	SN		CEZ 8152	Vo	B10M-62	YV31MA614WA048944	Co	858512	C49FT	(R100STL/PSU611/R100STL)
Fraser, Munloch	SN		CEZ 8153	Vo	B10M-62	YV31MA613VA046987	VH	33034	C46FT	(P301VWR/YCZ8703/P301VWR/OSU638/P301VWR)
Fraser, Munloch	SN		EX 09 YDY	Fd	Tt	WF0DXXTTFD9U69664	Fd		M14	(ex P555 RJF, EX 09 YDY)
Fraser, Munloch	SN		G454 TST	Vo	B10M-60	020484	VH	14032	C55F	
Fraser, Munloch	SN		G818 GSX	Ld	ON2R56C13Z4	ON11542	Ar	RH75/3089/19	H51/33F	
Fraser, Munloch	SN		J239 NNC	Vo	B10M-60	YV31MGD1XNA028170	VH	30929	C49FT	(J239NNC/CEZ8153)
Fraser, Munloch	SN		JIL 5623	Ld	TRCTL11/3R	8200538	Pn	8312LTP1C020	C57F	(FNM860Y)
Fraser, Munloch	SN	(w)	JIL 8256	Vo	B10M-61	008168	VH	11742	C53F	(C301JNS/7173WW/C180USS)
Fraser, Munloch	SN	(w)	L 4 PHF	MB	814D	WDB6703132N005922	Do	52586 635 93	C33F	
Fraser, Munloch	SN	(w)	L148 XDS	MB	609D	WDB6680632N012272	Onyx		C24F	

Fraser, Munloch	SN		LIB 8921	Vo	B10M-60	023439	VH	30416	C49FT	(G701XFB/SIL4860/G391XST/B3YST/G391XST)
Fraser, Munloch	SN		MK 02 GZU	MB	413CDI	WDB9046632R349851	Onyx	530	M16	
Fraser, Munloch	SN	(x)	P821 GLS	Fd	Tt	SFALXXBDVLM45924	?		M8	
Fraser, Munloch	SN		R349 HYS	Fd	Tt	WFOEXXBDVEWJ43767	Fd		M12	
Fraser, Munloch	SN	(w)	RJI 8720	Vo	B10M-61	000904	VH	10470	C49FT	(STT614X/383DVF/972FGD)
Fraser, Munloch	SN		S592 ACT	MB	O814D	WDB6703742N076316	ACI	1580	C33F	(S592ACT/HSK805)
Fraser, Munloch	SN		SF 04 SXX	Vo	B12M	YV3R9G1194A011755	Je	26799	C53F	(SF04SXX/7921AT/SF04SXX/HSV782)
Fraser, Munloch	SN		SG 03 ZEW	Vo	B12M	YV3R9F8123A001051	Je	26447	C53F	(15RWM/SG03ZEW/B15GOO/DSV246)
Fraser, Munloch	SN	(x)	SX 03 BEJ	Fd	Tt	WFOXXBDFFP3C73196	Fd		M8	
Fraser, Munloch	SN	(x)	T555 RJF	Fd	Tt	WFOBXXBDFBBS14884	Blbd		M16	(HY61NVK)
Fraser, Munloch	SN	(w)	TPC 723X	Vo	B10M-61	YV3B10M6000002699	VH	10475	C49FT	(TPC723X/WLT909)
Fraser, Munloch	SN	(w)	VNU 328	Vo	B10M-61	007591	Je	19410	C51FT	
Fraser, Munloch	SN		YN 57 DVM	MB	O816D	WDB6703742N127058	Ind		C33F	
Fraser, Munloch	SN		YR 02 ZLX	MB	O814D	WDB6703742N089305	Pn	998.5MZE2408	C33F	
Fraser, Munloch	SN		SN 04 MJS	Fd	Tt	WFOEXXGBFE4B86560	Fd		M14	
Fraser, Munloch	SN		SN 57 EXD	MB	515CDI	WDB90665725168395	KVC		M16	
G										
Galson Stornoway, Barvas	SN		FJ 58 LSK	Vo	B12B	YV3R8L2278A124676	Je	28535	C53F	(FJ58LSK/T66MOS)
Galson Stornoway, Barvas	SN		GA 15 ONS	Fd	Tt	WFOHXXTTGHFK09650	Fd		M16	
Galson Stornoway, Barvas	SN		KM 03 GSM	Vo	B12B	YV3R8F8142A000405	VH	33851	C53F	(ex 1528 RU, KM 03 GSM)
Galson Stornoway, Barvas	SN	(w)	L345 ERU	Vo	B10M-62	YV31M2B17RA041115	Pn	9412VUM2159	C49FT	(XEL31/L345ERU/213ONU)
Galson Stornoway, Barvas	SN		NE 52 STY	Vo	B12B	YV3R8F8193A002006	VH	33858	C57F	(SF03AWC, TIW5725, SF03AWC)
Galson Stornoway, Barvas	SN		SC 58 OHB	MB	O813D	WDB6703742N132365	Pn	08.5MXV7815	B31F	(09-CN-937)
Galson Stornoway, Barvas	SN		SG 59 XGS	Fd	Tt	WFODXXTTFD9A40838	Fd		M16	
Galson Stornoway, Barvas	SN		SJ 05 ACX	Vo	B12B	YV3R8G1225A104730	VH	33947	C49FT	(SJ05ACX/KSK934)
Galson Stornoway, Barvas	SN		SK 05 SOU	Vo	B12B	YV3R8G1245A104650	VH	33941	C51F	
Galson Stornoway, Barvas	SN	GS68	V 58 KWO	Vo	B10M-62	YV31MA619XC061324	Pn	9912VUM1245	C53F	
Galson Stornoway, Barvas	SN		WA 54 HXV	Vo	B12M	YV3R9F8114A011989	VH	33781	C54FT	
Galson Stornoway, Barvas	SN		WA 54 HXW	Vo	B12M	YV3R9F8184A011990	VH	33782	C54FT	
Galson Stornoway, Barvas	SN	(w)	XCC 95V	Ld	PSU3E/4R	7930035	Pn	8011LX573	C53F	(UFM267V/794YKM)
Galson Stornoway, Barvas	SN		YJ 03 VMR	Vo	B12M	YV3R9F8183A001121	Tbs	0312TJT5005	C48FT	
Galson Stornoway, Barvas	SN		YJ 10 OAD	Oe	M880SL	SABEN3AF0AL193706	Oe		B27F	
Glover {D&H Coaches}, Kyle	SN		T200 DAH	MB	313CDI	WDB90663525442562	?		M16	(WV10WLF)
Glover {D&H Coaches}, Kyle	SN		T300 DAH	Fd	Tt	WFOHXXTTGHER03534	Fd		M17	(SY64XUZ)
Grenitote Travel, Grenitote	SN		CN 09 DMO	Rt	Mtr	VF1FDC1M639521862	Tawe		M16	
Grenitote Travel, Grenitote	SN	(w)	DX 04 WKW	Rt	Mtr	VF1FDBNH527747012	Tawe		M9	
Grenitote Travel, Grenitote	SN	(r)	G775 FJC	VW	LT55	KH006979	Oe	656	DP25FL	
Grenitote Travel, Grenitote	SN		SD 04 WKW	Fd	Tt	WFOEXXGBFE4B86626	Fd		M16	
Grenitote Travel, Grenitote	SN		SF 55 GOE	Rt	Mtr	VF1PDMUL632787431	?		M16	
Grenitote Travel, Grenitote	SN		SY 08 VYC	Rt	Mtr	VF1PDM1L638165092	Rt		M16	
Grenitote Travel, Grenitote	SN		SY 12 AZT	Rt	Mtr	VF1MEN4JE45894570	?		M16	
Grenitote Travel, Grenitote	SN		SY 12 AZU	Rt	Mtr	VF1MEN4JE46130823	Rt		M16	
Grenitote Travel, Grenitote	SN		SY 14 HPO	Rt	Mtr	VF1MEN4UE5055448	Rt		M16	
Grenitote Travel, Grenitote	SN		YD 15 JWF	Fd	Tt	WFOHXXTTGHFE51396	Fd		M16	
Grenitote Travel, Grenitote	SN		YD 15 JWJ	Fd	Tt	WFOHXXTTGHFE51397	Fd		M16	
Grenitote Travel, Grenitote	SN		YK 16 UFN	Fd	Tt	WFOHXXTTGHFP34093	Fd		M16	
H										
Halcrow, Cunningsburgh	SN		CV 53 HTN	Fd	Tt	WFOXXBDFP3L00292	Fd		M11	
Halcrow, Cunningsburgh	SN		MV 02 UMH	Vo	B12M	YV3R9H4181A000226	VH	33674	C46FT	(MV02UMH/TOT987)
Halcrow, Cunningsburgh	SN		N978 NMW	MB	814D	WDB6703132N028061	Pn	958.5MMY3842	C33F	(N30ARJ)
Halcrow, Cunningsburgh	SN		SN 06 BSV	AD	Env	SFD211AR15GG10219	AD	5304/2	B57F	
Halcrow, Cunningsburgh	SN		SY 14 GNK	AD	E20D	SFD7F3BR6EGY24181	AD	D266/1	B39F	(J200JFJ)

Halcrow, Cunningsburgh	SN		W201 EAG	Vo	B10M-62	YV31MA61XYA051995	Pn	0012VUL2361	C53F	
Harcuss, Pierowall	SN		SP 10 DXY	Io	35C13	ZCFC359400D422970	Allied		M11	
Harcuss, Pierowall	SN		SV 57 FJK	Io	50C15	ZCFC50A2005687448	?		M16	
Harcuss, Pierowall	SN		YN 58 KVD	MB	311CDI	WDB9067332S349308	MB		M8	
Harrold, South Keiss	SN		A179 MKE	Ld	TRCTL11/3R	8300554	Du	435/5563	C57F	(ex 869 SVX, A179 MKE)
Harrold, South Keiss	SN		AVK 139V	Ld	AN68A/2R	7901100	Ar	AL79/1979/6	H49/37F	
Harrold, South Keiss	SN		B417 CVH	DAF	SB2300DHTD585	246557	Pn	8512DMP2C006	C57F	
Harrold, South Keiss	SN		B851 KRY	Bd	YNT	ET105194	Pn	8411NTP1C040	C53F	
Harrold, South Keiss	SN		D 21 EFS	Vo	B10M-61	012556	Pn	8712VMH3C760	C53F	(D 21EFS/HIL5346)
Harrold, South Keiss	SN	(w)	D438 TMB	Bd	YNV	FT700350	Du	8692/0341	C57F	
Harrold, South Keiss	SN		E235 WMB	MB	609D	WDB66806320787197	PMT	787	C26F	
Harrold, South Keiss	SN		F990 HGE	Vo	B10M-60	021379	Pn	8912VCB1304	C53F	
Harrold, South Keiss	SN		G932 TVO	Vo	B10M-60	024578	VH	30654	C49FT	(G879VNA/XTW359/G792YND/B 6WER/G316OKW/A 9EBT/ACZ 103)
Harrold, South Keiss	SN		JIL 2566	Vo	B10M-61	009189	Pn	8512VZH2C779	C53F	(B705WUA)
Harrold, South Keiss	SN	(r)	NOC 598R	Ld	FE30AGR	7602375	PR	61938	H43/33F	
Harrold, South Keiss	SN	(w)	OIL 2946	Vo	B10M-60	026018	Pn	9112VCS0268	C53F	(J418HDS)
Harrold, South Keiss	SN		R599 GFS	MB	814D	WDB6703742N065133	Pn	978.5MZD7389	C33F	
Harrold, South Keiss	SN		R967 MGB	MB	O814D	WDB6703742N064466	Me	02764	C33F	
Harrold, South Keiss	SN	(r)	VNB 133L	Ld	AN68/1R	7203690	PR	B59796	H--/--F	
Heatherlea, Nethybridge	SN		KN 10 HHZ	Fd	Tt	WF0DXXTTFD9E31962	Fd		M14	
Hill {Halyal Garage}, Lyness	SN		P993 TGB	MB	609D	WDB6680632N046651	Adn	AC609004	C24F	
I										
Ingram {Turriff Coaches & Cabs}, Turriff	SN		PL 03 WCF	Fd	Tt	WF0EXXGBFE3Y07132	Fd		M16	
Ingram {Turriff Coaches & Cabs}, Turriff	SN		MJ 15 WHD	Fd	Tt	WF0HXXTTGHFD24513	Fd		M16	
J										
Jacobite Cruises, Inverness	SN		1983 NT	Ds	Tt	SFD33GBR73GX43192	Tbs	3073/4	PO47/??F	(ex LX 53 JZM)
Jacobite Cruises, Inverness	SN		2080 NT	Ds	Tt	SFD33GBR73GX43189	Tbs	3038/32	PO47/??F	(ex LX 53 JZH)
Jacobite Cruises, Inverness	SN		NE 55 BUS	MB	O816D	WDB6703742N139099	Pn	108.5MBJ8534	C33F	(ex LN 10 BUS)
Jacobite Cruises, Inverness	SN		SF 16 KUW	MAN	19.360	WMARRZZXGCO21346	Bs	-?-	C48F	
Jamieson, Cullivoe	SN	(z)	HPS 28P	Bd	YLQ	FW452929	Du	616/2224	C45F	
Jamieson, Cullivoe	SN		JJ 13 RGJ	KL	XMQ6900EU	LA6R1DSE3DB105958	KL		C33FL	
Jamieson, Cullivoe	SN		NK 62 EWP	Fd	Tt	WF0DXXTTFDCL36530	Fd		M8	
Jamieson, Cullivoe	SN		SW 13 KCU	Fd	Tt	WF0DXXTTFDPP46815	Fd		M16	
Jamieson, Cullivoe	SN		T 22 RGJ	Fd	Tt	WF0HXXTTGHFL60197	Fd		M16	(ex SW 15 FNX)
Jamieson, Cullivoe	SN		V 22 RGJ	MAN	19.360	WMARRZZZ0FC020480	Barbi	-?-	C43F	
Jamieson, Cullivoe	SN		W 22 RGJ	Vo	B12B	YV3R8F8114A014782	Pn	0412TKT5553	C53F	(B 12CCT/BU54WYA/JIG4301)
Jamieson, Cullivoe	SN		X 22 RGJ	Vo	B9R	YV3S5P725EA163188	Pn	DU06/01	C53F	
Jamieson, Cullivoe	SN		Y 22 RGJ	Vo	B8R	YV3T7U528HA182919	Pn	GL12/01	C53F	
Jamieson, Cullivoe	SN		YE 11 BUS	MB	516CDI	WDB9066572P275693	?		C22F	
Jamieson, Cullivoe	SN		YE 11 RGJ	MB	O816D	WDB6703742N142112	Pn	118.5MBJ8781	C33F	
Johnson, Brae	SN		G953 KJX	DAF	SB2305DHTD585	318913	Pn	9012DFA2082	C57F	
Johnson, Brae	SN		J 16 JFJ	MB	516CDI	WDB9066572S703710	?		M16	
Johnson, Brae	SN		J 20 JFJ	MB	516CDI	WDB9066572S910611	EVM		C19F	
Johnson, Brae	SN		J 33 JFJ	MB	O816D	WDB6703742N141454	Pn		C33F	
Johnson, Brae	SN		J 40 JFJ	MB	516CDI	WDB9066572S795792	?		C19F	
Johnson, Brae	SN		J 44 JFJ	MB	516CDI	WDB906572S795792	EVM		C19F	
Johnson, Brae	SN		J 50 JFJ	Fd	Tt	WF0HXXTTGHFE37818	Fd		M16	(ex SE 65 NCX)
Johnson, Brae	SN		J 70 JFJ	Vo	B7R	YV3R6R626BA143410	Pn	1012TTX8734	C55F	
Johnson, Brae	SN		J 77 JFJ	MB	516CDI	WDB9066572S997551	EVM		M16	
Johnson, Brae	SN		J 80 JFJ	MB	921L	WDB9670232L917228	Erduman	-?-	C33F	

Johnson, Brae	SN		J200 JFJ	Vo	B8R	YV3T7U529EA165672	Pn	-?-	C57F	
Johnson, Brae	SN		J300 JFJ	Vo	B7R	YV3R6R62XBA143412	Pn	1012TTX8736	C57F	(YN61E00)
Johnson, Brae	SN		SD 07 TXC	Fd	Tt	WF0DXXTTFD7D24936	Fd		M15	
Johnson, Brae	SN		SV 52 KGF	Fd	Tt	WF0EXXGBFE2B35658				
Johnson, Brae	SN		YK 63 EKN	Fd	Tt	WF0DXXTTFDDB68824	Fd		M16	
Johnson, Brae	SN		YN 63 EKN	Fd	Tt	-?-	Fd		M16	
Johnson, Brae	SN		J 90 JFJ	MB	516CDI	WDB9066572P302457	?		M16	
K										
Keir, Glass	SN		J721 KBC	Ds	Jv	SFD741BR54GJ22513	Pn	0412GRX5675	C57F	
Keir, Glass	SN		SV 06 DDO	MB	O815D	WDB6703742N117711	Sitcar	2120	C33F	
Keir, Glass	SN		SV 54 CFA	MB	O814D	WDB6703742N115343	Pn	048.5MAE5715	C33F	
Keir, Glass	SN		W500 SOU	Vo	B10M-62	YV31MA618YA052045	Pn	0012VUP2172	C57F	
Kineil Coaches, Fraserburgh	SN		671 YWC	Vo	B10M-62	YV31M2B14RA041704	VH	31861	C70F	(LSK503/M831HN/M 5 END/M831HNS/HJI 565/M831HNS)
Kineil Coaches, Fraserburgh	SN		953 HBU	Vo	B10M-62	YV31M2B15SA042494	VH	32219	C70F	(M760GGE/XRY278/M760GGE)
Kineil Coaches, Fraserburgh	SN		A717 OSJ	Vo	B10M-61	007439	VH	11288	C50FT	(NVY148)
Kineil Coaches, Fraserburgh	SN	(r)	C261 FGG	Ld	TRCLXC/2R	8401211	Ar	21TE/1384/4	C49F	(C261FGG/HSK792)
Kineil Coaches, Fraserburgh	SN		F782 UJS	Vo	B10M-60	YV31MGD12KA020088	VH	14011	C70F	(ex JSU 384, F782 UJS)
Kineil Coaches, Fraserburgh	SN		F812 XSG	Vo	B10M-60	YV31MGD16KA020370	VH	14030	C55F	(ex RIB 7742, F812 XSG)
Kineil Coaches, Fraserburgh	SN		GJI 926	Vo	B10M-62	YV31M2B19RA040323	VH	31802	C70F	(LSK835/L633AYS/CAZ1577/L633AYS)
Kineil Coaches, Fraserburgh	SN		HRP 1N	Vo	B10M-62	YV31MA6181A053394	VH	33648	C49FT	(WA51JYE)
Kineil Coaches, Fraserburgh	SN		JSU 384	Ba	FHD12-340	XL9AA18P532003426	Ba		C49FT	(ex SV 06 CEO)
Kineil Coaches, Fraserburgh	SN		JSV 362	Vo	B10M-60	YV31M2B12PA032271	VH	31749	C70F	(L971KDT)
Kineil Coaches, Fraserburgh	SN		K 5 SKY	Vo	B10M-62	YV31MA610XA051146	VH	33547	C49FT	(ex V540 DYA)
Kineil Coaches, Fraserburgh	SN		M 12 BUS	Vo	B10M-62	YV31M2B15SA042091	VH	32097	C53F	
Kineil Coaches, Fraserburgh	SN	(w)	PDL 252X	Bd	YNT	LW452606	Pn	8111tc050	C53F	
Kineil Coaches, Fraserburgh	SN		PDX 782	Ba	FHD12-340	XL9AA18P632003495	Ba		C49FT	(ex SF 06 LKU)
Kineil Coaches, Fraserburgh	SN		PSU 755	Ba	FHD12-340	XL9AA18P532003422	Ba		C49FT	(ex SV 06 CEK)
Kineil Coaches, Fraserburgh	SN		SD 63 HNV	VDL	FHD2.122	XNL501E100D002412	VDL		C53F	
Kineil Coaches, Fraserburgh	SN		SF 16 KUX	VDL	FHD2-129.365	XNL501E100D004583	VDL		C57F	
Kineil Coaches, Fraserburgh	SN		SF 16 MVL	Io	70C17	ZCFC270C905015148	Sit	3187	C25F	
Kineil Coaches, Fraserburgh	SN		SF 16 MVM	Io	70C17	ZCFC270C505016748	Sit	3190	C25F	
Kineil Coaches, Fraserburgh	SN		SF 58 JFV	MB	O813D	WDB6703732N128902	Onyx	826	C24F	
Kineil Coaches, Fraserburgh	SN		SF 65 CZO	Sca	K410EB4	YS2K4X20001893943	VH	-?-	C49FT	
Kineil Coaches, Fraserburgh	SN		SF 65 CZP	VDL	FHD2 129.365	XNL501E100D004468	VDL		C57F	
Kineil Coaches, Fraserburgh	SN		SM 02 GSM	Sca	K124IB4	1838159	VH	36029	C49FT	
Kineil Coaches, Fraserburgh	SN		SN 03 JZK	MB	O815D	WDB6703742N106181	Sitcar	1838	C33F	
Kineil Coaches, Fraserburgh	SN		SN 04 GFE	MB	O814D	WDB6703742N110498	Pn	038.5MAE5286	C33F	
Kineil Coaches, Fraserburgh	SN		SN 06 ABO	MB	413CDI	WDB9046632R853096	KVC		M16	
Kineil Coaches, Fraserburgh	SN		SN 10 AZT	MB	O816D	WDB6703742N135372	Sitcar	2496	C29F	
Kineil Coaches, Fraserburgh	SN		SN 12 EBF	MB	513CDI	WDB9066572S628729	EVM		M16	
Kineil Coaches, Fraserburgh	SN		SN 12 EBG	MB	516CDI	WDB9066572S637767	UNVI	-?-	C22F	
Kineil Coaches, Fraserburgh	SN	(r)	SN 53 DYA	MB	614D	WDB6683532N108971	Onyx	625	C24F	
Kineil Coaches, Fraserburgh	SN		SN 62 AZX	MB	516CDI	WDB9066572S715598	UNVI	-?-	C22F	
Kineil Coaches, Fraserburgh	SN		SN 62 AZZ	MB	516CDI	WDB9066572S721217	UNVI	-?-	C22F	
Kineil Coaches, Fraserburgh	SN		SV 12 BZP	MB	O816D	WDB6703742N145700	Pn	BC04	C29F	
Kineil Coaches, Fraserburgh	SN		TIW 7700	Vo	B10M-61	007647	VH	11507	C50FT	(WAC828/A221XTL/5670SC/A722YOX)
Kineil Coaches, Fraserburgh	SN		V326 XDO	MB	412D	WDB9044632P861169	ACI	1676	M16	
Kineil Coaches, Fraserburgh	SN		VIA 488	Vo	B10M-62	YV31MA616WA049237	VH	33472	C49FT	(S750XYA)
Kineil Coaches, Fraserburgh	SN		VIA 508	Vo	B10M-62	YV31M2B19RA041696	VH	31857	C53F	(LSK499/M827HNS)
Kineil Coaches, Fraserburgh	SN		X974 NRS	MB	614D	WDB6703742N092557	Onyx	427	C24F	
Kineil Coaches, Fraserburgh	SN		YJ 10 OAB	Oe	M880SL	SABEN3AF0AL193704	Oe		B27F	
Kineil Coaches, Fraserburgh	SN		YJ 15 EUA	VH	TX15	YE2X15SH249D55572	VH	55572	C49F	
Kineil Coaches, Fraserburgh	SN		YJ 15 EUB	VH	TX15	YE2X15SH249D55573	VH	55573	C49F	
Kineil Coaches, Fraserburgh	SN		YN 09 DXS	MB	O814D	WDB6703742N135359	Pn	088.5MBJ8121	C33F	

Kineil Coaches, Fraserburgh	SN		YN 54 WVX	MB	O814D	WDB6703742N116264	Pn		C33F	
Kineil Coaches, Fraserburgh	SN		YN 57 MEU	MB	O816D	WDB6703742N130790	Pn		C33F	
Kineil Coaches, Fraserburgh	SN		YN 57 MFK	MB	O816D	WDB6703742N129209	Pn	078.5MBJ7365	C33F	
Kineil Coaches, Fraserburgh	SN		YN 59 BMV	AD	Jv	SFD755BR69GJ22638	Pn	0912JAX8286	C57F	
Kineil Coaches, Fraserburgh	SN		YN 61 EOM	Vo	B7R	YV3R6R628BA143411	Pn	1012TTX8735	C57F	
Kineil Coaches, Fraserburgh	SN		YX 14 EFN	MB	O816D	WDB6703742N150333	Pn	DC30/01	C29F	
Kineil Coaches, Fraserburgh	SN		VIA 963	Vo	B10M-62	YV31MA6101A056292	VH	33617	C49FT	(ex Y226 NYA)
L										
Leask, Lerwick	SN	(w)	K106 TCP	DAF	MB230LT615	XLVCE02LT0H002903	VH	31449	C51FT	(ex K600 JLS, K106 TCP)
Leask, Lerwick	SN		K600 JLS	Vo	B9R	YV3S5P721DA160044	Pn	CP32/01	C57F	(ex SW 62 OJN, J 90 JFJ)
Leask, Lerwick	SN		N 20 JLS	MB	O816D	WDB6703742N141455	Pn	118.5MBJ8758	C33F	
Leask, Lerwick	SN		R 20 JLS	AD	E20D	SFD7F3BR6EGY24278	AD	E206/1	B39F	
Leask, Lerwick	SN		S 20 JLS	MB	O814D	WDB6703742N127842	Pn	078.5MBJ7163	C33F	
Leask, Lerwick	SN		T 20 JLS	AD	E20D	SFD7E1AR6EGY14180	AD	D265/4	B37F	
Leask, Lerwick	SN		T 30 JLS	VDL	SB200	XMGDE02F50H020665	Wt	AF558	B44F	(ex YJ 12 CLX)
Leask, Lerwick	SN		T 40 JLS	Vo	B7RLE	YV3R6R629EA164269	MCV	MCV-581	B44F	
Leask, Lerwick	SN		T 50 JLS	Vo	B7RLE	YV3R6R623DA161592	MCV	MCV-551	B44F	
Leask, Lerwick	SN		T 70 JLS	AD	E20D	SFD7E1AR6EGY14172	AD	C265/3	B37F	
Leask, Lerwick	SN		V 40 JLS	AD	E300	SFD113AR13GG10131	AD	3040/5	B43F	
Leask, Lerwick	SN		V 90 JLS	Tmsa	Safari	NLTRHT87R01050008	Tmsa	OA02187	C57F	(YJ57BSX)
Leask, Lerwick	SN		V258 DPS	Vo	B10BLE	YV3R4A517XA005477	Wt	B417	B47F	
Leask, Lerwick	SN		W 20 JLS	MB	614D	WDB6683532N117993	Excel	594	C16F	(YN05CUY)
Leask, Lerwick	SN		W 30 JLS	MB	516CDI	WDB90665725823998	EVM	C10233	C19F	
Leask, Lerwick	SN		W 40 JLS	Tmsa	Safari HD	NLTRJTA7R01010005	Tmsa		C53FT	(YJ10DUY)
Leask, Lerwick	SN		W 60 JLS	Wt	StLt DF	SA9DSRXXX12141180	Wt	AH227	B40F	
Leask, Lerwick	SN		W 90 JLS	Tmsa	Safari	NLTRHT97R01010020	Tmsa	OA03935	C57F	
Leask, Lerwick	SN		Y800 JLS	Vo	B12B	YV3R8G1216A110052	VH	33961	C49FT	(ex YJ 06 GLY, JL 06 RSL, YJ 06 GLY)
Leask, Lerwick	SN		YD 02 RDY	DAF	DE02CSSB200	XMGDE02CS0H009633	Wt	E66	B44F	
Lees, Lumphanan	SN		CXZ 9425	Vo	B12B	YV3R8G1247A116364	VH	38053	C51F	(ex WA 07 WCX, 07-C-12519)
Lees, Lumphanan	SN		A 6 NPT	Io	45C15	ZCFC45A2005663365	Elite		M16	(FJ57NAC)
Lees, Lumphanan	SN		AJ 59 XZH	Fd	Tt	WF0DXXTTFD9D28093	Fd		M16	
Lees, Lumphanan	SN		CN 58 ZTM	Fd	Tt	WF0DXXTTFD8K47793	Fd		M16	
Lees, Lumphanan	SN		KM 12 GSM	Au	N2216SHD	WAGP21ZZ9BT017378	Au	P21-1251	C49FT	
Lees, Lumphanan	SN		NA 06 BWP	Fd	Tt	WF0EXXTTFE6Y05495	Fd		M16	
Lees, Lumphanan	SN		P503 VUS	Vo	B10M-62	YV31MA612VC060402	VH	33014	C51F	(P503VUS/NLZ 708/P503VUS/XSV893)
Lees, Lumphanan	SN		SN 06 AEF	Vo	B12B	YV3R8G1265A105203	Bf	5038	C53F	(SN06AEF/570PRR)
Lees, Lumphanan	SN		SN 62 AYF	MB	O816D	WDB6703742N146168	UNVI	-?-	C29F	
Lees, Lumphanan	SN		SW 05 CNN	MB	311CDI	WDB9036632R725304	?		M16	
Lees, Lumphanan	SN		SW 05 DKO	Fd	Tt	WF0EXXTTFE5B12347	Fd		M16	
Lees, Lumphanan	SN		WA 03 EYJ	Vo	B12M	YV3R9F8163A000971	VH	33726	C46FT	
Lees, Lumphanan	SN		YK 10 WDJ	Fd	Tt	WF0DXXTTFD9D30380	Fd		M16	
Lindsay, Lochboisdale	SN		AE 54 JTV	LDV	Cy	SEYZMVSZGDN106099	LDV		M16	
Lindsay, Lochboisdale	SN	(w)	F705 ENE	Ld	TRCL10/3ARZM	TR00508	Pn	8912LCA0794	C53F	(F705ENE/665EYL/TXY978)
Lindsay, Lochboisdale	SN		H341 GRY	Ds	Jv	11SDL1921/523	Du	8978/1158	C55F	
Lindsay, Lochboisdale	SN	(w)	K 17 CJT	Vo	B10M-60	YV31MGD15LA024069	Pn	9012VCAP1730	C57F	(K301MFB/3138DP)
Lindsay, Lochboisdale	SN		M 6 SEL	Ds	Jv	12SDA2131/988	Pn	9412HKM1996	C53F	
Lindsay, Lochboisdale	SN		N320 RSK	Ds	Jv	10SDA2156/1467	WS		C41F	(?)
Lindsay, Lochboisdale	SN		N576 DAS	Ds	Jv	10SDA2156/1467	UVG		C41F	(?)
Lindsay, Lochboisdale	SN		P705 PWC	MB	O810D	WDB6703732N063258	Pn	977.8MWW6979	C33F	
Lindsay, Lochboisdale	SN		SN 54 KND	LDV	Cy	SEYZMVSYDN109259	LDV		M16	
Littlejohn {Aboyne Taxis}, Aboyne	SN		SW 12 HRL	Fd	Tt	WF0DXXTTFD8414	Fd		M16	
Loch Ness Monster, Drumnadrochit	SN		YX 56 CGF	LDV	Cy	SEYZMVFZGDN086315	?		M16L	(YX56CGF/TX11788)

Lochs Motor Transport, Leurbost	SN		SD 15 UWL	Vo	B11R	YV3T2U821FA171008	Je	37302	C53F	
Lochs Motor Transport, Leurbost	SN		SY 61 AUL	Vo	B9R	YV3S5P727AA141087	Pn	1012SAR8576	C53FL	
Lochs Motor Transport, Leurbost	SN		YN 12 BXL	Vo	B9R	YV3S5P727CA154053	Pn	BP10/01	C55F	
Lochs Motor Transport, Leurbost	SN		YX 17 NRL	AD	E20D	SFD6U3BR6HG Y26199	AD	H212/1	B41F	
Lochs Motor Transport, Leurbost	SN		YX 66 WMZ	Vo	B8R	YV3T7U521HA181031	Pn	GL11/01	C57F	
Lochs Motor Transport, Leurbost	SN		YY 14 NLK	Vo	B11R	YV3S5P723EA167790	Pn	EP03/01	C53F	
Lochs Motor Transport, Leurbost	SN		SF 17 VMR	Vo	B11R	YV3T2U829HA182342	Je	37674	C53FT	
Logan, Lossiemouth	SN		SC 04 LUB	Fd	Tt	WF0EXXGBFE3U15080	Fd		M16	(ex X 11 ECK, SC 04 LUB)
Logan, Lossiemouth	SN		SC 51 BDV	Fd	Tt	WF0EXXGBFE1P16818	Fd		M14	(KC51BUS/SC51BDV/X 11ECK)
Logan, Lossiemouth	SN		SP 10 KBE	Fd	Tt	WF0DXXTTFDAS85652	Fd		M14	(ex -?-)
Logan, Lossiemouth	SN		YK 07 YLP	Fd	Tt	WF0DXXTTFD7K78530	Fd		M16	
Lowe {W&G Taxis / Coaches}, Cuminstown	SN		BJ 12 XLM	Fd	Tt	WF0DXXTTFDCA07286	Fd		M16	
Lowe {W&G Taxis / Coaches}, Cuminstown	SN	(x)	FD 10 ABK	Fd	Tt	WF0SXXBDFSAJ70393	Fd		M8	
Lowe {W&G Taxis / Coaches}, Cuminstown	SN		HV 12 KTK	Fd	Tt	WF0DXXTTFDCA02114	Fd		M16	
Lowe {W&G Taxis / Coaches}, Cuminstown	SN		MJ 63 HNU	Fd	Tt	WF0DXXTTFDDG30747	Fd		M16	
Lowe {W&G Taxis / Coaches}, Cuminstown	SN		MV 63 SBX	Fd	Tt	WF0DXXTTFDDG30724	Fd		M16	
Lowe {W&G Taxis / Coaches}, Cuminstown	SN		ND 60 WDV	MB	311CDI	WDB9067332S534973	MB		M8	(ex P 9 WGC, ND 60 WDV)
Lowe {W&G Taxis / Coaches}, Cuminstown	SN		P 9 WGC	MB	1021L	WDB9670242L913452	UNVI	-?-	C35F	(ex CC 15 WGC)
Lowe {W&G Taxis / Coaches}, Cuminstown	SN		R 9 WGC	MB	O816D	WDB6703742N136460	UNVI		C33F	(ex SW 60 LHK, SC 60 WGC)
Lowe {W&G Taxis / Coaches}, Cuminstown	SN		S591 ACT	MB	410D	WDB9044632P844042	ACI	1579	M16	(C 9 WGC, S591 ACT)
Lowe {W&G Taxis / Coaches}, Cuminstown	SN		SN 64 AAO	MB	516CDI	WDB9066572S341879	Paramount		C19F	(ex SN 64 AAO)
Lowe {W&G Taxis / Coaches}, Cuminstown	SN	(x)	SW 10 HFO	Fd	Tt	WF0SXXBDFSAJ70684	Fd		M8	
Lowe {W&G Taxis / Coaches}, Cuminstown	SN		SW 10 HHD	Fd	Tt	WF0DXXTTFDAS11013	Fd		M16	
M										
MacArthur {Spa Motors}, Strathpeffer	SN	(w)	BX 04 VJD	MB	413CDI	WDB9046632R417595	?		M16	
MacArthur {Spa Motors}, Strathpeffer	SN		D605 MVR	Vo	B10M-61	YV31MGD16HA013976	VH	12653	C53F	
MacArthur {Spa Motors}, Strathpeffer	SN	(w)	E 40 OMS	MB	709D	WDB66906320826858	Ar	AM45/2887/1	DP25F	
MacArthur {Spa Motors}, Strathpeffer	SN		G862 RNC	Vo	B10M-60	023063	VH	30077	C57F	(G862RNC/BAZ7912)
MacArthur {Spa Motors}, Strathpeffer	SN		K295 ESF	MB	811D	WDB6703032N004868	Do		C29F	
MacArthur {Spa Motors}, Strathpeffer	SN	(w)	K481 VVR	Vo	B10M-60	YV31MGD13NA030505	VH	30968	C70F	(K481VVR/GSU382)

MacArthur {Spa Motors}, Strathpeffer	SN		KN 07 SPA	Vo	B12B	YV3R8G12X7A117003	VH	38015	C53FT	
MacArthur {Spa Motors}, Strathpeffer	SN		P550 MSF	MB	814D	WDB6703132N044189	Pn	968.5MMY5744	C33F	
MacArthur {Spa Motors}, Strathpeffer	SN		P974 WOS	Vo	B10M-62	YV31MA613VA046410	VH	33002	C53F	(97-C-8212)
MacArthur {Spa Motors}, Strathpeffer	SN		PAZ 2535	Vo	B10M-60	YV31M2B17RA032382	VH	31807	C48FT	(L906NWW)
MacArthur {Spa Motors}, Strathpeffer	SN		S 21 SPA	Vo	B10M-62	YV31MA614WC060922	Pn	9812VUM8787	C57F	
MacArthur {Spa Motors}, Strathpeffer	SN		S 22 SPA	Ta	BB50R	TW1FG518905500548	Co	F043071062	C21F	(ex BX 05 AJV)
MacArthur {Spa Motors}, Strathpeffer	SN		S 33 SPA	Vo	B12B	YV3R8G1164A014695	VH	33896	C49FT	(SY54CXF)
MacArthur {Spa Motors}, Strathpeffer	SN		SN 03 AXM	MB	614D	WDB6683532N108023	Onyx	597	C24F	
MacArthur {Spa Motors}, Strathpeffer	SN		SN 03 NLK	MB	O814D	WDB6703742N108631	Pn	038.5MAE4981	C33F	
MacArthur {Spa Motors}, Strathpeffer	SN		SY 02 XUN	MB	O814D	WDB6703742N105122	Pn	028.5MAE4706	C31F	(S 33SPA)
MacArthur {Spa Motors}, Strathpeffer	SN		T642 BSS	Vo	B10M-55	YV31MA710XA050433	VH	33808	C49FT	
MacArthur {Spa Motors}, Strathpeffer	SN		W251 GSE	Vo	B10M-55	YV31MA710YA051776	VH	33823	C49FT	
MacArthur {Spa Motors}, Strathpeffer	SN	(z)	XIB 9829	Vo	B10M-61	000622	Je	17758	C49FT	(BTU771W)
MacArthur {Spa Motors}, Strathpeffer	SN		Y 5 SPA	Vo	B10M-62	YV31MA7151A053318	VH	33643	C53F	
MacArthur {Spa Motors}, Strathpeffer	SN		Y 6 SPA	Vo	B10M-55	YV31MA7111A053350	VH	33841	C49FT	(Y291RSO)
MacAskill {Glenedin Coaches}, Edinbane	SN		K 8 JNM	Rt	Mtr	VF1FDCEL521654600	?		M14	(X488ADB)
MacAskill {Glenedin Coaches}, Edinbane	SN	(x)	NX 54 BUV	Io	29L12	ZCFC2980005516072	Io		M8	
MacAskill {Glenedin Coaches}, Edinbane	SN		PVS 20W	Bd	YLO	YMQ2DZ0KW453771	Du	050/1560	C53F	
MacAskill {Glenedin Coaches}, Edinbane	SN	(w)	X173 APY	Io	50C13	ZCFC5070005241991	Me	10967	M16L	
MacAskill {Glenedin Coaches}, Edinbane	SN	(w)	YX 06 CUO	VW	Tr	WV3ZZZ7JZ5X024760	Blbd	-?-	B15F	
MacDonald {Hebridean Coaches}, Howmore	SN		AIG 6222	Fd	Tt	WF0DXTTFD7K02983	Fd		M16	(ex SL 07 RZG)
MacDonald {Hebridean Coaches}, Howmore	SN		AF 02 RZT	LDV	Cy	SEYZMVSYGDN082716	LDV		M16	
MacDonald {Hebridean Coaches}, Howmore	SN		CST 703N	Fd	R1114	BC04PT62571	Ar	48/AYS/973/4	B53F	
MacDonald {Hebridean Coaches}, Howmore	SN	(w)	G278 BEL	Ds	Jv	11SDA1906/455	Du	8979/1086	C53F	
MacDonald {Hebridean Coaches}, Howmore	SN	(w)	G911 KWF	Ft	49-10	11992	RB	17375	B25F	
MacDonald {Hebridean Coaches}, Howmore	SN		HIG 2461	Ds	Jv	12SDA2155/1281	Pn	9512HBM4343	C57F	(P512MBD)
MacDonald {Hebridean Coaches}, Howmore	SN		JIL 6316	Ds	Jv	12SDA2131/852	Pn	9312HKM1393	C57F	(L837LRM)
MacDonald {Hebridean Coaches}, Howmore	SN	(w)	NA 04 ZJU	Fd	Tt	WF0EXXGBFE3M48018	Fd		M16	

MacDonald {Hebridean Coaches}, Howmore	SN		NUI 5272	Ds	Jv	12SDA2138/965	Pn	9412HKM1870	C53F	(L234BUT)
MacDonald {Hebridean Coaches}, Howmore	SN		OUI 3813	MB	814D	WDB6703132N026199	WS	4779/??	C29F	(02-RN-59)
MacDonald {Hebridean Coaches}, Howmore	SN		R128 XWF	Ds	Jv	SFD731BR3VGJ92016	Pn	9712HPP6748	C53F	
MacDonald {Hebridean Coaches}, Howmore	SN		RDZ 4275	Ds	Jv	SFD731BR3VGJ41955	Pn	9712HMP6496	C53F	(P222TCC)
MacDonald {Hebridean Coaches}, Howmore	SN		SD 57 HZH	Fd	Tt	WF0DXXTTFD7S25896	Fd		M14	
MacDonald {Hebridean Coaches}, Howmore	SN		UCZ 3032	Fd	Tt	WF0EXXGBFE3Y10631	Fd		M16	
MacDonald, Balallan	SN		SG 62 EFZ	Fd	Tt	WF0DXXTTFDCY57007	Fd		M16	
MacDonald, Balallan	SN		SJ 15 PVA	Vo	B11R	YV3T2U823FA170488	Je	37296	C53F	
MacDonald, Balallan	SN		SM 63 GOH	Fd	Tt	WF0DXXTTFDDA21602	Fd		M16	
MacDonald, Balallan	SN		WA 04 YZR	Vo	B12B	YV3R8G1114A014880	Je	26855	C53F	(04-G-5405/WA04YZR/B 16WCS)
MacDonald, Balallan	SN		Y504 TGJ	Vo	B10M-62	YV31MA617YA051808	Pn	0012VUT2137	C53F	(ex K400 RES, Y504 TGJ)
MacDonald, Carloway	SN		BK 07 HXH	Fd	Tt	WF0DXXTTFD7D15196	Fd		M16	
MacDonald, Dunvegan	SN		SF 54 CFO	MB	O814D	WDB6703742N114562	Pn	048.5MXV5476	DP33F	
MacDonald, Dunvegan	SN		YJ 10 MHL	Oe	M880	SABEN5AFEAB193679	Oe		B27F	
MacDonald, Dunvegan	SN		YJ 59 NNO	Oe	M880	SABEW3AF09L193570	Oe		B27F	
MacDonald, Lochmaddy	SN		SY 12 AWZ	Rt	Mtr	VF6MKN4JE47219022	?		M16	
MacDonald, Struan	SN		AE 61 FZZ	Io	50C17	ZCFC50C0005869292	?		M16	
MacDonald, Struan	SN		SY 03 FHB	MB	O814D	WDB6703732N108933	Onyx	615	C24F	
MacDonald, Tolstaclaolais	SN	(x)	SB 13 OET	Fd	Tt	WF0SXXBDFSDP61268	Fd		M8	
MacIver {Hebridean Transport}, Stornaway	SN		CX 65 PKU	Fd	Tt	WF0HXXTTGHFT35219	Fd		M16	
MacIver {Hebridean Transport}, Stornaway	SN		HC 04 AAA	Vo	B7R	YV3R6G81X4A010161	Pn	0412TLX5649	C57F	
MacIver {Hebridean Transport}, Stornaway	SN		MV 64 ZVY	Fd	Tt	WF0HXXTTGHEU33742	Fd		M16	
MacIver {Hebridean Transport}, Stornaway	SN		MV 64 ZWA	Fd	Tt	WF0HXXTTGHEU32658	Fd		M17	
MacIver {Hebridean Transport}, Stornaway	SN		MV 64 ZWA	Fd	Tt	WF0HXXTTGHEU32658	Fd		M16	
MacIver {Hebridean Transport}, Stornaway	SN		N409 SPC	Ds	Jv	12SDA2159/1477	Pn	9612HCM4704	C53F	
MacIver {Hebridean Transport}, Stornaway	SN		SG 58 EFC	Fd	Tt	WF0DXXTTFD8G82167	Fd		M16	
MacIver {Hebridean Transport}, Stornaway	SN		W209 EAG	Vo	B10M-62	YV31MA619YA052118	Pn	0012VUL2367	C53F	(ex 5093 PO, W209 EAG)
MacIver {Hebridean Transport}, Stornaway	SN		WM 03 BYD	Vo	B7R	YV3R6G7173A006374	Pn	0312THX5120	C53F	
MacIver {Hebridean Transport}, Stornaway	SN		YN 07 EXS	Sca	K340EB4	YS2K4X20001855561	Ir	130886	C49FL	(ex OIJ 883, YN 07 EXS)
MacIver {Hebridean Transport}, Stornaway	SN		HB 12 HEB	Sca	K360EB4	YS2K4X20001876062	Ir	-?-	C53FL	(ex YT 12 YUA)
MacIver {Hebridean Transport}, Stornaway	SN		MV 64 ZWB	Fd	Tt	WF0HXXTTGHEU40175	Fd		M16	
MacIver {Hebridean Transport}, Stornaway	SN		SW 59 MLE	Vo	B7R	YV3R6M3209A135238	Pn	0912TWS8383	C53FL	(ex J600 JFJ)
MacIver, Carloway	SN		WF 60 EXX	Fd	Tt	WF0DXXTTFD9E49319	Fd		M16	
MacIver, Carloway	SN		WJ 14 HYT	Fd	Tt	WF0DXXTTFDD06846	Fd		M16	
MacIver, Stornaway	SN		YS 65 WWM	Fd	Tt	WF0HXXTTGHFM16578	Fd		M11	
MacKay, Dornoch	SN		CN 57 HSF	MB	515CDI	WDB9061552N317934	UVM	-?-	B11FL	
MacKay, Dornoch	SN		LIL 8615	MB	811D	WDB67030320934567	Ar	AM60/288/13	C33F	(F196XFS/JHC 4/F196XFS)
MacKay, Dornoch	SN	(w)	LUI 1520	MB	811D	WDB6703032P012633	Ce	C16-086	B30F	(H727LOL)

MacKay, Dornoch	SN		ML 02 NYC	Io	65C15	ZCFC65A0005361732	FGy	8758	B20FL	
MacKay, Dornoch	SN		MX 59 HZN	MB	515CDI	WDB90665725274843	Onyx	852	M16	(ex MM 55 BUS, MX 59 HZN)
MacKay, Dornoch	SN		SY 53 BWV	VW	LT46	WV1ZZZ2DZ4H009742	?		M??	
MacKay, Dornoch	SN		X 2 PCC	MB	O814D	WDB6703742N088044	Pn	008.5MXV2323	DP33F	
MacKay, Dunress	SN		AF 02 ZNV	LDV	Cy	SEYZMVSYGDN087350	LDV		M16	
MacKay, Dunress	SN		M281 FEG	MB	308D	WDB6023672P399461	DC	558M	M15	
MacKay, Dunress	SN		N235 WDO	MB	410D	WDB6114682P404648	ACI	1269	M16	
MacKay, Dunress	SN		PX 03 HBA	LDV	Cy	SEYZMVSYGDN097049	LDV		M16	
Mackay, Talmine	SN		SG 11 MBO	Fd	Tt	WF0DXXTTFDAA83169	Fd		M16	
MacKenzie & MacLennan {Westerbus}, Gairloch	SN		MIL 8024	Vo	B12M	YV3R9H4141A000224	VH	33672	C46FT	(MV02UMF)
MacKenzie & MacLennan {Westerbus}, Gairloch	SN	(z)	MIL 9310	Vo	B10M-61	YV3N10M6100006861	Je	18918	C51FT	(A120XNH/IIL5317)
MacKenzie & MacLennan {Westerbus}, Gairloch	SN		MKZ 585	Sca	K400EB4	YS2K4X20001869948	Lah	YK900L360AR00812	C51FT	(ex YP 10 VZG, C 10 HCD, YP 10 VZG)
MacKenzie & MacLennan {Westerbus}, Gairloch	SN		SIL 8761	Vo	B12M	YV3R9F8183A000776	VH	33735	C46FT	(MX03ABF)
MacKenzie & MacLennan {Westerbus}, Gairloch	SN		TLZ 2656	Ba	FHD10-340	XL9AA16CGX7003739	Ba		C45F	(T759JYB)
MacKenzie & MacLennan {Westerbus}, Gairloch	SN		XIL 5755	MAN	11.190HOCL	WMA4691241G081812	Co	359004	C35F	(971OHT/J888BST)
MacKenzie & MacLennan {Westerbus}, Gairloch	SN		EU 04 BXX	MB	O814D	WDB6703742N112520	Pn	048.5MAE5377	C33F	(ex MKZ 3553, EU 04 BXX)
MacKenzie & MacLennan {Westerbus}, Gairloch	SN		FV 11 JGX	Fd	Tt	WF0DXXTTFDBC35124	Fd		M16	
MacKenzie {Coast to Coach Travel}, Dundonnell	SN		T527 CDM	MB	412D	WDB9044632P908464	Crest	M432	M16	
MacKenzie {Coast to Coach Travel}, Dundonnell	SN		Y297 OCT	MB	1223L	WDB9702582K525648	Fer	14049	C39F	
MacKenzie {DMK Motors}, Loch Carron	SN		NC 57 BSX	Fd	Tt	WF0DXXTTFD7E41626	?		M16	
MacKenzie {DMK Motors}, Loch Carron	SN		SK 53 TTZ	Fd	Tt	WF0EXXGBFE3S44732	?		M14	
MacKenzie {DMK Motors}, Loch Carron	SN		SY 05 LFM	Fd	Tt	WF0EXXTTFE5U31942	Fd		M16	
MacKenzie {DMK Motors}, Loch Carron	SN		SY 54 BZW	Rt	Mtr	VF1FDCVH532409281	?		M11	
MacKenzie {DMK Motors}, Loch Carron	SN		YP 60 UHR	Fd	Tt	WF0DXXTTFDAR46482	Fd		M16	
MacKenzie, Upper Carloway	SN		EN 55 WZF	Fd	Tt	WF0EXXTTFE5R28734	Fd		M16	
MacKenzie, Upper Carloway	SN		SJ 07 WNX	Fd	Tt	WF0DXXTTFD7E45947	Fd		M16	
MacKinnon {Misty Isle Tours}, Kyle	SN		M888 MMT	MB	413CDI	WDB9046632R925649	Onyx	789	M16	(ex PX 06 ABF)
MacLean, Dornie	SN		BP 60 XBR	Vo	B12B	YV3R8L22571120348	Vo	P070912	C53FT	(ex 11-D-6237)
MacLean, Dornie	SN	(x)	T 5 HGV	VW	Tr	WV2ZZZ7HZ6X032907	VW		M8	(ex KR 06 TVF)
MacLean, Kyle	SN		E171 ATU	MB	609D	WDB66806320849709	PMT	9028	C24F	
MacLean, Kyle	SN		H511 SWE	MB	609D	WDB6680632P031584	Wh		B24F	
MacLean, Kyle	SN		HSK 841	MB	515CDI	WDB9061552N343894	Fer		C16F	(ex FX 58 ZNU)
MacLean, Kyle	SN		HST 83X	Vo	B10M-48	YV31MA511VA047119	VH	33073	C40F	(R974EHS/JIL3961/R974EHS)
MacLean, Kyle	SN		K654 VNF	MB	609D	WDB6680632P218041	MM		C24F	
MacLean, Kyle	SN		SJ 66 LME	Vo	B8R	YV3T7U520GA179074	Ssd	B-6840	C70F	
MacLean, Kyle	SN		T108 JBA	Vo	B10M-62	YV31MA612XC061049	VH	33510	C46FT	
MacLennan {Moray Academy of Transport Training}, Elgin	SN		SX 04 GGA	Fd	Tt	WF0EXXGBFE4B86554	Fd		M16	
MacLennan P, Laxy Lochs	SN		DY 66 WXE	Vx	Mov	W0LMVT60XGB113916	?		M16	
MacLennan P, Laxy Lochs	SN		X 24 LXV	MB	516CDI	WDB9066572P204598	Prmt	-?-	C19F	
MacLennan, Grosebay	SN		819 XUP	Vo	B10M-62	YV31M2B19SA042269	Je	23568	C49FT	(M625FNS/SIL4712)

MacLennan, Grosebay	SN		A 3 EXR	MB	O814D	WDB6703732N105443	Onyx	551	C24F	(ML02ONH/P100BUS/ML02ONH)
MacLennan, Grosebay	SN		A 5 EXR	Vo	B10M-60	YV31MGD11LA024070	Pn	9012VCB2103	C51FT	(H172EJU/8399RU/H282NRF/ 99KMH/H282NRF)
MacLennan, Grosebay	SN		A 9 EXR	VW	LT46	WV1ZZZ2DZYH031915	Glen		M8L	(W143PLS)
MacLennan, Grosebay	SN		A 10 EXR	MB	O814D	WDB6703742N086116	Pn	998.5MZE1994	C33F	(W 15HCT)
MacLennan, Grosebay	SN		A 20 EXR	LDV	Cy	SEYZMVSZGDN099837	?		M16L	(SY53AWM)
MacLennan, Grosebay	SN	(z)	F298 RMH	Vo	B10M-46	YV31MGC10JA018355	Pn	889.5VNP3C010	C43F	
MacLennan, Grosebay	SN	(w)	F962 FCY	Ld	TRCTL11/3ARZ	TR00513	Pn	8912LFA1468	C53F	(F778GNA/NIL7042/F778GNA/940HFJ/F77 8GNA/MJI2050)
MacLennan, Grosebay	SN		HX 61 AUM	Rt	Mtr	VF1MEN4JE45894541	Rt		M16	
MacLennan, Grosebay	SN	(w)	JIL 3713	Vo	B10M-61	YV31MGD11JA017679	Pn	8812VMP3C036	C53F	(E3140MG)
MacLennan, Grosebay	SN		R893 WLG	MB	308D	WDB9033632P687905	Cpt		M14L	
MacLennan, Grosebay	SN	(r)	S170 MRB	LDV	Cy	DN036274	LDV		M16	
MacLennan, Grosebay	SN		S577 KCS	LDV	Cy	SEYZMYSHEDN036728	LDV		M16	
MacLennan, Grosebay	SN		SY 55 CVM	MB	411CDI	WDB9046632R560950	?		M16	
MacLennan, Grosebay	SN		T738 JHE	Sca	L94IB	YS4L4X20001834506	Ir	92404	C49FT	(T738JHE/991FOT)
MacLennan, Grosebay	SN		VX 12 FDL	Rt	Mtr	VF1MEN4JE46130818	Rt		M16	
MacLennan, Grosebay	SN		W131 PNL	Sca	K124IB4	YS4K4X20001836362	Ir	92822	C49FT	(W131PNL/ALZ9219)
MacLennan, Grosebay	SN		W901 WHS	VW	LT46	WV1ZZZ2DZYH024261	AVB		M16L	
MacLennan, Grosebay	SN		YS 63 VPC	Fd	Tt	WF0DXXTTFDDA28360	Fd		M16	
MacLennan, Laxy Lochs	SN		RK 63 ULE	Fd	Tt	WF0DXXTTFDDC51537	Fd		M16	
MacLennan, Laxy Lochs	SN	(x)	RX 63 VNM	Fd	Tt	WF0SXXBDFSDR64561	Fd		M8	
MacLennan, Laxy Lochs	SN		YS 63 VPC	Fd	Tt	WF0DXXTTFDDA28360	Fd		M16	
MacLennan, Laxy Lochs	SN		YS 63 VPF	Fd	Tt	WF0DXXTTFDDA28254	Fd		M16	
MacLennan, Stornaway	SN		AL 03 ASH	Tbs	Jv	SFD745BR53GJ22437	Tbs	0312GRX4776	C53F	
MacLennan, Stornaway	SN		FCZ 707	Vo	B12M	YV3R9G1124A011855	Je	26548	C53F	(FN04JZH)
MacLennan, Stornaway	SN		M259 OKN	Ds	Jv	12SDA2131/935	Pn	9412HKM1926	C53F	
MacLennan, Stornaway	SN		MJZ 3685	Vo	B12M	YV3R9G1104A011756	Je	26800	C53F	(SF04SSZ/LSK500/SF04SSZ)
MacLennan, Stornaway	SN		SG 52 UJP	Fd	Tt	WF0EXXGBFE2T59930	Fd		M14	(SG52UJP/T 110UR)
MacLennan, Stornaway	SN		SK 54 BPY	Sca	K114EB	1848717	Ir		C48FT	(B 17DWA/SK54BPY/G 13BSO)
MacLennan, Stornaway	SN		SX 04 XAC	Sca	K114IB4	YS2K4X20001846355	VH	36129	C49FT	(04-D-35350)
MacLennan, Stornaway	SN		T 3 APT	Vo	B10M-62	YV31MA610XA050367	VH	33525	C48FT	
MacLennan, Stornaway	SN		YM 03 EOU	Ds	Jv	SFD741BR53GJ22442	Pn	0312GRX5092	C57F	(YM03EOU/B 14PCH)
MacLennan, Stornaway	SN		YN 59 BMZ	MB	O816D	WDB6703742N135692	Pn	098.5MBJ8052	C33F	
MacLennan, Stornaway	SN		PN 08 KWX	Vo	B12M	YV3R9L2218A124248	Je	28582	C55F	(ex 4 ORX, PN 08 KWX)
MacLennan, Stornaway	SN		YP 12 NUJ	Sca	K360IB4	YS2K4X20001878687	Ir	140596	C53F	
MacMillan, Castlebay	SN	(w)	D279 FAS	Ld	TRCTL11/3R	8600439	Ar	28TE/2186/4	C53F	
MacMillan, Castlebay	SN	(w)	EFR 107W	Ld	PSU5D/5R	8030316	Du	035/5437	C53F	
MacMillan, Castlebay	SN	(r)	GST 500F	Bd	VAS5	7T457698	Wk	CF1577/80882	B27F	
MacMillan, Castlebay	SN	(w)	L309 AUT	MB	709D	WDB6690032N019396	ArB	M18090194	B25F	
MacMillan, Castlebay	SN	(w)	M 64 WKA	MB	709D	WDB6690032N021877	Ar	AM117/794/12	B25F	
MacMillan, Castlebay	SN		N208 GCS	MB	709D	WDB6690032N034994	WS	5107/95	B28FL	
MacMillan, Castlebay	SN	(w)	R972 MGB	MB	O814D	WDB6703742N068090	Me	02850	B33F	
MacMillan, Castlebay	SN		SN 53 KZG	MB	O814D	WDB6703742N111978	Pn	038.5MXW5344	B32FL	
MacMillan, Castlebay	SN		SN 53 KZL	MB	O814D	WDB6703742N111956	Pn	038.5MXW5342	B32FL	
MacMillan, Castlebay	SN		VX 56 LCE	MB	O813D	WDB6703732N125904	FGy		B16FL	
MacMillan, Castlebay	SN	(w)	W368 PSF	Io	59E12	ZCFC5980105196735	Me	3284	B24FL	
MacMillan, Castlebay	SN		W369 PSF	Io	59E12	ZCFC5980105196791	Me	3285	B24FL	
MacMillan, Castlebay	SN	(w)	W372 PSF	Io	59E12	ZCFC5980105196813	Me	3287	B24FL	
MacMillan, Castlebay	SN		WX 06 UWM	MB	O814D	WDB6703732N123117	UVM	10926	B28FL	
MacNeil, Castlebay	SN	(w)	H715 LOL	Ft	49-10	2013168	Ce		C25F	
MacNeil, Castlebay	SN		MV 04 GNZ	LDV	Cy	SEYZNVFZGDN100529	Cpt		M16	
MacNeil, Castlebay	SN	(w)	N398 FFS	MB	711D	WDB6693032N031193	Me	02304	C25F	
MacNeil, Castlebay	SN		P844 LVT	MB	814D	WDB6703132N044469	Me	02390	C33F	
MacNeil, Castlebay	SN		S717 KNV	MB	O814D	WDB6703742N077903	MI	MST-031	B31F	
MacNeil, Castlebay	SN		SF 04 EKT	MB	O814D	WDB6703742N114363	Pn	048.5MXV5454	B31F	
MacNeil, Castlebay	SN	(w)	SLZ 2617	MB	O814D	WDB6703742N090102	ACI	1717	DP31F	(W631SYC)

MacNeil, Castlebay	SN		SN 14 KXJ	Fd	Tt	WF0DXXTTFDDA21510	Fd		M16	
MacNeil, Castlebay	SN		Y546 HWE	MB	614D	WDB6703532N100116	Excel	0215	C24F	
MacQuarrie, Lochmaddy	SN		CN 06 DJF	Rt	Mtr	VF1PDMVL535116803	?		M16	
MacRae {Skye-ways / Clan Taxis}, Kyle	SN		12 EWO	Vo	B10M-62	044634	VH	32533	C49F	(N554OGE/L200NGS)
MacRae {Skye-ways / Clan Taxis}, Kyle	SN		A 1 SKY	Vo	B10M-62	YV31MA7111A053266	VH	33627	C51FT	(Y444GSM)
MacRae {Skye-ways / Clan Taxis}, Kyle	SN		E 9 SKY	Vo	B10M-55	YV31MA717YA051936	VH	33834	C49FT	(X576BYD/BHZ 122/X576BYD)
MacRae {Skye-ways / Clan Taxis}, Kyle	SN		G 1 SKY	Vo	B10M-62	YV31MA6191A053422	VH	33654	C49FT	(WJ02KDO/WIB1444)
MacRae {Skye-ways / Clan Taxis}, Kyle	SN	(x)	SY 07 YTA	MB	111CDI	WDF63970523336324	MB		M8	
MacRae {Skye-ways / Clan Taxis}, Kyle	SN	(x)	SY 51 RZR	MB	110CDI	VSA63819423428342	MB		M7	
MacRae {Skye-ways / Clan Taxis}, Kyle	SN		SY 54 AWJ	MB	313CDI	WDB9036632R679111	?		M16	
MacRae, Glenshiel	SN		EF 63 LWU	Fd	Tt	WF0DXXTTFDCS06207	Fd		M16	
MacRae, Glenshiel	SN		FG 12 MJJ	Fd	Tt	WF0DXXTTFDCA06638	Fd		M16	
MacRae, Glenshiel	SN		SY 09 RLX	Fd	Tt	WF0DXXTTFD8546019	Fd		M16	
MacRitchie {Hebridean Minibus Service}, Ness	SN		FV 10 VJJ	MB	316CDI	WDB9066352S460623	Excel	-?-	M16	
MacRitchie {Hebridean Minibus Service}, Ness	SN		LX 53 EXO	MB	413CDI	WDB9046122R507393	UVM		B16FL	
MacRitchie {Hebridean Minibus Service}, Ness	SN		RJ 59 XML	MB	313CDI	WDB9066352S414695	Elite		M16	(RJ59XML/MCH999)
MacVicar {WMV}, Linciate	SN	(w)	A 12 WMV	Fd	Tt	SFADXXBDVDNK30146	Do	203/5228392	C16F	(K901PGE)
MacVicar {WMV}, Linciate	SN		AE 53 KZF	LDV	Cy	SEYZMVSZGDN098817	LDV		M16	
MacVicar {WMV}, Linciate	SN		AF 14 YKJ	Fd	Tt	WF0HXXTTGHES73433	Fd		M16	
MacVicar {WMV}, Linciate	SN		DS 13 RXC	Fd	Tt	WF0DXXTTFDDJ44691	Fd		M16	
MacVicar {WMV}, Linciate	SN		FB 53 LCT	Tbs	Jv	SFD741BR53GJ22472	Tbs	0312GRX5202	C53F	(ex NJ 53 EPN)
MacVicar {WMV}, Linciate	SN		SB 63 TKA	Fd	Tt	WF0DXXTTFDDB66484	Fd		M16	
MacVicar {WMV}, Linciate	SN		SD 07 OKO	Fd	Tt	WF0DXXTTFD7E46410	Fd		M16	
MacVicar {WMV}, Linciate	SN		W357 GSE	Ds	Jv	SFD721BR3XGJE2277	Pn	9912GHM1090	C57F	(W357GSE/W999WCS)
MacVicar {WMV}, Linciate	SN		Y139 YSO	Ds	Jv	SFD721BR4YGJ22322	Pn	0012GFM2907	C57F	(ex Y124 PLT)
MacVicar {WMV}, Linciate	SN		YD 62 OHU	Fd	Tt	WF0DXXTTFDCC17825	Fd		M16	
Marshall & Innes {J & J Watt}, Huntly	SN		SY 17 YWZ	Fd	Tt	WF0HXXTTGHP29574	Fd		M16	
Marshall & Innes {J & J Watt}, Huntly	SN		SY 64 VMD	Fd	Tt	WF0HXXTTGHEP61774	Fd		M16	
Matheson {KSM Motors}, Lochinver	SN		V138 EAO	MB	O814D	WDB6703742N076478	Pn	998.5MZE9654	C29F	
Matheson {KSM Motors}, Lochinver	SN		DX 57 UAK	MB	813D	WDB6703532N129537	Excel	-?-	C24F	(ex BU 57 JON)
Maynes, Buckie	SN		7 MCB	MB	O816D	WDB6703742N150316	Pn	-?-	C25F	
Maynes, Buckie	SN		YSU 990	MB	519CDI	WDB9061552N667043	EVM		C19F	
Maynes, Buckie	SN		CM 05 GSM	MAN	18.310	WMAA5122845002590	Mpo		C70F	
Maynes, Buckie	SN		DM 14 YNE	MB	O816D	WDB6703742N150335	Pn	DC34/01	C25F	
Maynes, Buckie	SN		GM 14 YNE	MB	316CDI	WDB9066332S708476	EVM		M8	
Maynes, Buckie	SN		K 60 GSM	VDL	FHD2.129	XNL501E100D004318	VDL		C57F	
Maynes, Buckie	SN		KKN 752	Bd	OB	76964	Du	44272	C29F	(KKN752/KSU362)
Maynes, Buckie	SN		KM 14 YNE	VH	TX15	YE2X15SH249D55213	VH	55213	C49FT	
Maynes, Buckie	SN	11	M 17 YNE	MB	Tourismo M	WEB63241523000814	MB		C??F	
Maynes, Buckie	SN		N 22 GSM	VH	TX15	YE2X15SH249D55214	VH	55214	C49FT	
Maynes, Buckie	SN		N 33 GSM	VH	TX15	YE2X15SH249D55215	VH	55215	C49FT	
Maynes, Buckie	SN		N 40 GSM	BMC	750	NMC750RKDRD100026	BMC		C27F	
Maynes, Buckie	SN		N 40 YNE	BMC	?	-?-	BMC		C27F	

Maynes, Buckie	SN		N 44 GSM	VH	TX15	YE2X15SH249D55212	VH	55212	C49FT	
Maynes, Buckie	SN		N 60 GSM	Au	N2216SHD	WAGP21ZZ2CT017756	Au	-?-	C53FT	
Maynes, Buckie	SN		N 70 GSM	Au	N2216SHD	WAGP21ZZXCT017813	Au	-?-	C53FT	
Maynes, Buckie	SN	12	N 80 GSM	MB	Tourismo M	WEB63241523000816	MB		C??F	
Maynes, Buckie	SN		N 88 GSM	KL	XMQ6120C	LA6R1HSM6DB105449	KL		C68F	
Maynes, Buckie	SN	14	N 90 GSM	MB	Tourismo M	WEB63241523000823	MB		C??F	
Maynes, Buckie	SN		N 99 GSM	KL	XMQ6900	LA6R1DSE1DB105330	KL		C31FT	
Maynes, Buckie	SN	40	P 33 GSM	MB	Tourismo	WEB63241523000386	MB		C55F	
Maynes, Buckie	SN		P 44 GSM	Au	N2216SHD	WAGP21ZZ6FT021460	Au	P21-1996	C49FT	
Maynes, Buckie	SN		P 60 GSM	MAN	18.350	WMAA91ZZ89C012915	Mpo	02.09.OF.1663	C57F	(SV09AOA)
Maynes, Buckie	SN		P 70 GSM	MAN	18.350	WMAA91ZZ58C010392	Mpo	02.09.OF.1664	C57F	(SV09AOB)
Maynes, Buckie	SN	34	P 80 GSM	Ibs	397E.12.33	ZGA782N100E000664	HC	-?-	C57F	(PO11HWM)
Maynes, Buckie	SN	(p)	PUF 249M	Fd	R1114	BC04P561836	Du	423/4426	C49F	
Maynes, Buckie	SN	8	R 80 GSM	VDL	FHD2 122.365	XNL501E100D004456	VDL		C49FT	
Maynes, Buckie	SN	42	R 88 GSM	MB	Tourismo	WEB63241523000417	MB		C49FT	
Maynes, Buckie	SN	9	R 90 GSM	VDL	FHD2 122.365	XNL501E100D004461	VDL		C49FT	
Maynes, Buckie	SN	41	R 99 GSM	MB	Tourismo	WEB63241523000503	MB		C55F	
Maynes, Buckie	SN	3	T 70 GSM	VH	TX16	YE2X16SH249D55512	VH	55512	C53FT	
Maynes, Buckie	SN	7	T 80 GSM	VH	TX16	YE2X16SH249D55513	VH	55513	C53FT	
Maynes, Buckie	SN		X 1 GSM	MB	316CDI	WDB9066332575989	EVM		C9F	
Maynes, Buckie	SN		YSU 989	MB	O816D	WDB6703742N141125	Pn	108.5MBJ8719	C33F	
McAllister {Ashgrove Executive Travel}, Aberdeen	SN		SD 07 TKX	Fd	Tt	WF0DXXTTFD6B56406	Fd		M16	
McIntosh {Templeford Garage}, Forgue	SN		R848 WRM	Io	49E10	5156529	Me	02878	M16L	
Menzies {Castle Cruises Loch Ness}, Drumnadrochit	SN		NG 05 RWX	Fd	Tt	WF0EXXTTFE4S83716	Fd		M14	
Milne, New Byth	SN		MIL 2076	MB	516CDI	WDB9066572S679514	?		M16	(ex SN 62 AAX, CA 11 WSC, SN 62 AAX)
Milne, New Byth	SN		MIL 2430	Vo	B12B	YV3R8F8152A000428	VH	33853	C53F	(GM03GSM)
Milne, New Byth	SN		MIL 3667	MB	1023L	WDB9670242L960611	UNVI	-?-	C34F	
Milne, New Byth	SN		MIL 4852	MB	516CDI	WDB9066572P152240	UNVI	-?-	C22F	
Milne, New Byth	SN		MIL 4896	MB	1527L	WDB9670272L841523	UNVI	2338	C37F	
Milne, New Byth	SN		MIL 5169	MB	516CDI	WDB9066572S946753	Onyx	-?-	C19F	(ex PO 65 CUX)
Milne, New Byth	SN		MIL 5582	MB	516CDI	WDB9066572P152239	UNVI	-?-	C22F	
Milne, New Byth	SN		MIL 5714	Vo	B12B	YV3R8L22391131027	Vo	P086487	C49FT	(ex HXZ 2974, EXZ 9171, SN 60 CNX)
Milne, New Byth	SN		MIL 6695	Fd	Tt	WF0HXXTTTGHEU40182	Fd		M16	
Milne, New Byth	SN		MIL 6695	Fd	Tt	WF0HXXTTTGHEU40182	Fd		M16	(ex NA 64 WGO)
Milne, New Byth	SN		MIL 6696	MB	516CDI	WDB9066572S941880	Premier		C22F	
Milne, New Byth	SN		MIL 7525	MB	515CDI	WDB90665725224923	Onyx	834	M16	(MX60FOT)
Milne, New Byth	SN		NUI 2420	Ds	Jv	12SDA2155/1391	Pn	9612HBM4757	C53F	(N883JRE)
Morrison {Andrew's}, Whiteness	SN		FSU 330	Vo	B11R	YV3T2U823F1172399	Vo	P152202	C51FT	
Morrison {Andrew's}, Whiteness	SN		MIL 3724	Vo	B10M-62	YV31MA613WC060961	VH	33498	C53F	(ex T589 DGD, VIL 1532, T589 DGD, TFO 532, T589 DGD, 15 RWM)
Morrison {Andrew's}, Whiteness	SN		NUI 4223	DAF	SB3000	XMGDE33WS0H004425	VH	32817	C51FT	(ex N 87 FWU, 3 RED, N 87 FWU)
Morrison {Andrew's}, Whiteness	SN		TNZ 4461	MB	O814D	WDB6703742N087929	Pn	008.5MXW2325	DP32FL	(ex J 20 JFJ)
Morrison {Andrew's}, Whiteness	SN		XIW 1182	Vo	B10M-60	YV31MGD1XMA027597	VH	30904	C49FT	(ex J209 NNC)
Morrison {Andrew's}, Whiteness	SN		AR 03 AAA	Ba	FHD12-340	XL9AA18P33003715	Ba		C53F	(ex WA 03 EYP)
Morrison {Andrew's}, Whiteness	SN	(w)	C163 TLF	Vo	B10M-46	YV31MEC13FA010729	Pn	859.5VNP1C002	C43F	(C163TLF/HIL8280)
Morrison {Andrew's}, Whiteness	SN		CX 05 ARZ	Vo	B12M	YV3R9G1225A103347	VH	33790	C51FT	

Morrison {Andrew's}, Whiteness	SN		DK 04 LWN	MB	413CDI	WDB9046632R586652	Excel		M16	
Morrison {Andrew's}, Whiteness	SN		F980 HGE	Vo	B10M-60	YV31MGD10KA020879	Pn	8912VCB1286	C53F	(F980HGE/GUK146/F980HGE/NIW8290)
Morrison {Andrew's}, Whiteness	SN		FB 05 JTZ	Vo	B12M	YV3R8G1215A104900	Je	27153	C51FT	(ex VIL 9998, FB 05 JTZ, 05-G-504)
Morrison {Andrew's}, Whiteness	SN		FJ 04 ETV	Vo	B12B	YV3R8F8153A001449	Pn	0212TKL4724	C49FT	(FJ04ETV/YIL1710/FJ04ETV/447UXM/FJ04ETV/A 6ESS)
Morrison {Andrew's}, Whiteness	SN		FJ 04 ETX	Vo	B12B	YV3R8F8133A001451	Pn	0212TKL4725	C49FT	(FJ04ETX/YIL1720/FJ04ETX/449UXM/FJ04ETX/A 7ESS)
Morrison {Andrew's}, Whiteness	SN	(w)	FJ 05 HXY	Ta	BB50R	TW1FG518105500480	Co	F043071050	C22F	
Morrison {Andrew's}, Whiteness	SN		FM 15 KTC	MB	1218L	WDB9670252L913121	Pn	-?-	C35F	
Morrison {Andrew's}, Whiteness	SN		FM 15 KTD	MB	1218L	WDB9670252L931248	Pn	-?-	C35F	
Morrison {Andrew's}, Whiteness	SN		FM 15 KTE	MB	1218L	WDB9670252L930555	Pn	-?-	C35F	
Morrison {Andrew's}, Whiteness	SN	(r)	G870 MAH	Vo	B10M-60	YV31MGD15KA022756	Pn	9012VCB1761	C53F	(G870MAH/BIG4297)
Morrison {Andrew's}, Whiteness	SN		HIL 8028	MB	614D	WDB6683532N084401	Crossbow		C22FL	(T902VPP)
Morrison {Andrew's}, Whiteness	SN		HIL 8280	MB	O814D	WDB6703742N092069	Pn		C29F	(Y151XAE)
Morrison {Andrew's}, Whiteness	SN	(r)	J185 LGE	MB	811D	WDB6703032N001284	Ar	AM93/2491/9	C33F	(J259WFS/IIB1618)
Morrison {Andrew's}, Whiteness	SN		NH 04 BCH	Vo	B12M	YV3R9F8184A011794	Tbs	0412TJL5525	C55F	(GT04AGT)
Morrison {Andrew's}, Whiteness	SN		NH 04 CCH	Vo	B12M	YV3R9F81X4A011800	Tbs	0412TJL5526	C55F	(GT04BGT)
Morrison {Andrew's}, Whiteness	SN		NH 04 DCH	Vo	B12M	YV3R9F8114A011801	Tbs	0412TJL5527	C55F	(GT04CGT)
Morrison {Andrew's}, Whiteness	SN		NIW 7838	Vo	B10M-46	YV31MGC15HA014733	Co	758020	C35F	(E537FDU/CIL312)
Morrison {Andrew's}, Whiteness	SN		OU 65 RGY	Au	N2216SHD	WAGP20ZZ3ET021182	Au	-?-	C56FT	
Morrison {Andrew's}, Whiteness	SN		OU 65 RGZ	Au	N2216SHD	WAGP20ZZ2FT021451	Au	P21-00214	C56FT	
Morrison {Andrew's}, Whiteness	SN		PN 06 KJV	Vo	B12B	YV3R8G1296A110395	Pn	0612TKT6359	C53F	
Morrison {Andrew's}, Whiteness	SN		PN 06 KJX	Vo	B12B	YV3R8G1256A110667	Pn	0612TKT6360	C53F	
Morrison {Andrew's}, Whiteness	SN		RX 16 XHL	MB	516CDI	WDB9066572P216724	EVM		M16	
Morrison {Andrew's}, Whiteness	SN		SF 07 ZHP	Oe	M950	SABFWMAE06R192562	Oe		B30F	(ex 07-D-42887)
Morrison {Andrew's}, Whiteness	SN		SJ 16 CUA	Vo	B11R	YV3T2U829GA174806	Je	-?-	C53FT	
Morrison {Andrew's}, Whiteness	SN		SJ 16 CVA	Vo	B11R	YV3T2U822GA174839	Je	-?-	C53FT	
Morrison {Andrew's}, Whiteness	SN		SK 57 BEY	MB	O813D	WDB6703732N126055	KVC		C24F	
Morrison {Andrew's}, Whiteness	SN		T734 JGB	Vo	B10M-55	YV31MA711XA50554	VH	33813	C49FT	(ex T333 BUS, T734 JGB, XUF 456, T734 JGB)
Morrison {Andrew's}, Whiteness	SN		YJ 03 VMT	Vo	B12M	YV3R9F8173A001157	Tbs	0312TJT5006	C48FT	

N										
Nicholson, Cunnisburgh	SN	(w)	E958 CGA	Vo	B10M-61	016013	VH	13212	C57F	(E639UNE/L5K832/E95BCGA/HJI 565/E958CGA/OIW5800)
Nicholson, Cunnisburgh	SN		RX 64 FTO	MB	516CDI	WDB9066572S936079	evm		c16f	
Nicholson, Cunnisburgh	SN		SN 16 BSY	MB	1527L	WDB9670272L950225	UNVI	-?-	C41F	
Nicholson, Cunnisburgh	SN		VU 06 KDX	MB	O814D	WDB6703742N120722	Pn	058.5MXC6453	C33F	
Nicholson, Cunnisburgh	SN		YJ 03 VMU	Vo	B12M	YV3R9F8193A001158	Tbs	0312TJT5007	C53F	(YJ03VMU/KCT638)
Nicholson, Cunnisburgh	SN		YN 08 UXE	Vo	B12M	YV3R9L2248A126768	Pn	0812TVT7768	C57F	(08-DL-3355)
Nicholson, Cunnisburgh	SN		YX 11 CUJ	MB	O813D	WDB6703742N142263	Pn		B33F	
Nicoll, Laurencekirk	SN		RKZ 8284	MB	O815D	WDB6703742N123080	UNVI	34201	C29F	(ex A 17 MWN, RKZ 8284)
Nicoll, Laurencekirk	SN		A 4 MWN	MB	413CDI	WDB9046632R442498	KVC		M16	
Nicoll, Laurencekirk	SN		A 12 MWN	Vo	B10M-62	YV31MA616YA053328	Bf	4366	C51FT	(ex GM 02 GSM, S 12 YST, GM 02 GSM, B 5 YST, GM 02 GSM)
Nicoll, Laurencekirk	SN		A 15 MWN	Vo	B10M-62	YV31MA61XXC061025	Bf	3775	C51FT	(ex T687 BWN, XIL 930, T687 BWN)
Nicoll, Laurencekirk	SN		A 19 MWN	Vo	B10M-62	YV31MA61XXC061364	Pn	9912VUP1774	C53F	(LSK497/V 86LYS)
Nicoll, Laurencekirk	SN		A 20 MWN	Vo	B10M-62	YV31MA611WC060988	Bf	3882	C49FT	(ex T335 AFX, XIL 711, T335 AFX, 39 EYD, T335 AFX)
Nicoll, Laurencekirk	SN		FJ 03 NNM	MB	O814D	WDB6703742N103793	Me	3784	B28FL	
Nicoll, Laurencekirk	SN		HX 51 LPE	Ds	Dt SLF	SFD322BR11GW15829	SCC	4207/01	B37F	
Nicoll, Laurencekirk	SN		IIG 7764	Vo	B10M-62	YV31MA6111A053107	Pn	0012VUS3514	C49FT	(ex X437 BTT, GXI 53, X437 BTT, 01-D-8077)
Nicoll, Laurencekirk	SN		KFO 809	Ba	FHD13-340	XL9AA38P431003014	Ba		C80F	(ex YK 04 FVV, YSV 695, YK 04 FVV)
Nicoll, Laurencekirk	SN		MX 56 OHO	VW	LT46	WV1ZZZDZ26H023446	MinO		M12L	
Nicoll, Laurencekirk	SN		N 2 CLL	Ba	FHD127-365	XL9AA38R633003010	Ba		C49FT	(T 80VA/SP07KZA)
Nicoll, Laurencekirk	SN		N 3 CLL	Vo	B10M-62	YV31MA618WA048316	VH	33411	C53F	(R788WSB)
Nicoll, Laurencekirk	SN		N 4 CLL	MB	O814D	WDB6703742N124113	Pn	068.5MAE6332	C33F	(ex YN 56 NGV)
Nicoll, Laurencekirk	SN		N 10 CLL	MB	616CDI	WDB9056132R907398	UNVI	34186	C23F	(ex SK 06 BKN, H 18 XEC, SK 06 BKN)
Nicoll, Laurencekirk	SN		N 22 CLL	MB	413CDI	WDB9046632R601360	KVC		M16	(N 2CLL)
Nicoll, Laurencekirk	SN		P127 FRS	Ta	HZB50R	9000391	Co	551082	C21F	(N 3CLL)
Nicoll, Laurencekirk	SN		S137 JSO	MB	O810D	WDB6703732N074521	Pn	987.8MWW8751	C25F	
Nicoll, Laurencekirk	SN	(r)	S237 EWU	Oe	M850	VN6072	Oe	6072	B26F	
Nicoll, Laurencekirk	SN		SF 58 FTV	MB	O813D	WDB6703742N129673	Pn	078.5MXV7355	DP31FL	
Nicoll, Laurencekirk	SN		SK 02 VCG	MB	O814D	WDB6703732N102952	KVC		C24FL	
Nicoll, Laurencekirk	SN		SL 52 AFZ	MB	413CDI	WDB9046632R386397	KVC		M16	
Nicoll, Laurencekirk	SN		SL 52 AKN	MB	413CDI		KVC		M16	
Nicoll, Laurencekirk	SN	(r)	SM 04 GSM	Ba	FHD12-340	XL9AA18P4310003305	Ba		C49FT	
Nicoll, Laurencekirk	SN		SN 02 VCL	MB	O814D		KVC		C24FL	
Nicoll, Laurencekirk	SN		SN 51 WYC	MB	614D	WDB6683532N102172	Onyx	516	C24F	
Nicoll, Laurencekirk	SN		V501 FSF	MB	614D	WDB6683532N087359	Onyx		C24F	
Nicoll, Laurencekirk	SN		VX 07 GZA	MB	O814D	WDB6703742N127325	Me	4468	C33F	
Nicoll, Laurencekirk	SN		VX 08 HZU	MB	O816D	WDB6703742N127344	Me	4464	C29F	
Nicoll, Laurencekirk	SN		W343 GSS	Fd	Tt	WFOEXXBDVEXP67686	Fd		M14	
Nicoll, Laurencekirk	SN		W462 RSX	MB	413CDI	WDB9046632R132728	Onyx	428	M16	
Nicoll, Laurencekirk	SN		W464 RSX	MB	614D	WDB6683532N092541	Onyx	436	C24F	
Nicoll, Laurencekirk	SN		W962 GSS	Fd	Tt	WFOEXXBDVEXM61283	Fd		M14	
Nicoll, Laurencekirk	SN		YJ 05 WCT	Oe	M850	SAB1900000002027	Oe		B34F	
Nicoll, Laurencekirk	SN		YJ 62 FYX	Oe	M920SR	SABTW3AF0CS290481	Oe		B33F	
Nicoll, Laurencekirk	SN		YK 51 NVV	MB	413CDI	WDB9046122R311348	UVG	8957	DP16FL	
Nicoll, Laurencekirk	SN		YL 02 FKZ	Oe	M920	SAB1900000000856	Oe		B29F	
Nicoll, Laurencekirk	SN		YX 12 FPY	AD	E20D	SFD1D1AR6CGY13027	AD	-?-	B29F	
Nicoll, Laurencekirk	SN		YX 12 FPZ	AD	E20D	SFD7E1AR6CGY13029	AD	-?-	B39F	
Nicoll, Laurencekirk	SN		N 1 CLL	Ba	FHD12-340	XL9AA18P431003764	Ba		C49FT	(ex YJ 05 FXA, UAP 969, YJL 693, M 2 DNT, K888 SCL, YJ 05 FXA)
Nicoll, Laurencekirk	SN		NLZ 1692	Vo	B10M-62	YV31MA618VA046323	Pn	9612VUS6041	C49FL	(ex S246 WAT)
Northcote {Augusta}, Fort Augustus	SN		BG 02 XBZ	Fd	Tt	WFOEXXGBFE2T63877	?		M7	

O										
Orkney Community Transport, Kirkwall	SN		ESU 913	Vo	B10M-62	YV31MA615VA047011	VH	33038	C46FT	(ex P305 VWR, 7243 WA, P305 VWR)
Orkney Community Transport, Kirkwall	SN		AE 55 EHP	MAN	14.220	WMAA66Z85C005835	MCV	MCV-068	B40F	(AE55EHR)
Orkney Community Transport, Kirkwall	SN		DK 11 BWF	MB	516CDI	WDB9066572S532208	MinO		M15L	
Orkney Community Transport, Kirkwall	SN		DX 64 BCY	MB	516CDI	WDB9066572S936072	MinO		M15L	
Orkney Community Transport, Kirkwall	SN		FJ 56 SXT	MB	614D	WDB6683222N125857	Me	4416	B15FL	
Orkney Community Transport, Kirkwall	SN		FX 56 WFD	Vx	Mov	VN1N9DUL635804202	Vx		M16	
Orkney Community Transport, Kirkwall	SN		GN 09 KHO	Io	65C18	ZCFC65D0005780959	Me	4824	B16FL	
Orkney Community Transport, Kirkwall	SN		GR 54 EVF	MB	Touro	WEB63420323000118	MB		C53F	(M400TWC)
Orkney Community Transport, Kirkwall	SN		YC 51 HAU	Oe	M850	SAB19000000000713	Oe		B26F	
Orkney Community Transport, Kirkwall	SN		YN 03 WPV	Sca	K114IB4	YS2K4X20001843175	Ir	95377	C53F	(ex USV 605, YN 03 WPV)
Orkney Community Transport, Kirkwall	SN		YN 55 PXP	Sca	K114EB4	YS2K4X20001851528	Ir	130371	C49FT	
P										
Peace, Echt	SN		EU 60 PZZ	Vo	B9R	YV3S5P72XBA144793	Pn	1012SAZ8751	C61F	(B 20DWA)
Peace, Echt	SN		FJ 04 PXX	Ba	FHD12-340	XL9AA18P431003247	Ba		C70F	
Peace, Echt	SN	(x)	PE 10 ZRX	Rt	Tc	VF1JLAHA6AV371131	?		M8	
Peace, Echt	SN		PO 11 KTC	MB	516CDI	WDB9066572S368619	UNVI	-?-	C22F	
Peace, Echt	SN		PP 11 BUS	Ba	FHD127.365	XL9AA38RB34003619	Ba		C53F	
Peace, Echt	SN		PX 60 NCU	Vo	B9R	YV3S5P725BA145026	Pn	1012SAZ8752	C61F	(B 19DWA)
Peace, Echt	SN		SF 16 KUS	VDL	FHD2-129.370	XNL501E100D005062	VDL		C57F	
Peace, Echt	SN		SF 16 KUT	VDL	FHD2-129.370	XNL501E100D005063	VDL		C57F	
Peace, Echt	SN		SF 17 EDP	VDL	FHD2-122.360	XNL501E100D006385	VDL		C53FLT	
Peace, Echt	SN		SF 52 EBD	Fd	Tt	WF0EXXGBFE2L68056	Fd		M8	
Peace, Echt	SN		SK 06 BZN	MB	413CDI	WDB9046632R838749	KVC		M16	
Peace, Echt	SN		SN 06 AVT	MB	O814D	WDB6703732N120662	KVC		C24F	
Peace, Echt	SN		SN 13 AOP	Ba	FHD127.365	XL9AA18RC35003252	Ba		C49FLT	
Peace, Echt	SN		SN 16 BRF	MB	516CDI	WDB9061552N610746	UNVI -?-		C19F	
Peace, Echt	SN		SN 60 BFF	MB	O816D	WDB6703742N140855	UNVI	-?-	C29F	
Peace, Echt	SN		SN 62 AYE	MB	516CDI	WDB9066572S712477	UNVI		M16	
Peace, Echt	SN		SN 66 AVV	Io	70C17	ZCFC270C505117305	UNVI	-?-	C25F	
Peace, Echt	SN	(x)	SP 06 LPV	Fd	Tt	WF0TXXBDFT5K74250	Fd		M8	
Peace, Echt	SN	(x)	ST 08 HLA	Fd	Tt	WF0XXXTTFX8G69634	Fd		M8L	
Peace, Echt	SN		SV 02 KNZ	Fd	Tt	WF0EXXGBFE1G65558	Fd		M8	(JLZ9510)
Peace, Echt	SN		WA 08 AOY	Ba	FHD120.365	XL9AA18R733003705	Ba		C53F	
Peace, Echt	SN		Y768 TSJ	Ba	FHD12-370	8003575	Ba		C49FT	
Peace, Echt	SN	(x)	YE 10 XXA	Rt	Tc	VF1JLBHB6AV384433	?		M8	
Petrofac Training, Aberdeen	SN		SV 59 LVR	Fd	Tt	WF0DXXTTFD9A43408	Fd		M16	
Phillips Coaches, Alford	SN		AJZ 8753	LDV	Cy	SEYZMVSJEDN071855	LDV		M16	
Poke {J & V Coaches}, Stromness	SN		VUN 421	Vo	B12M	YV3R9G1225A101372	VH	33786	C51FT	(ex WK 06 AEC, 536 FN, WK 06 AEC)
Poke {J & V Coaches}, Stromness	SN		CH 04 COM	Ba	FHD13-340	XL9AA38P331003014	Ba		C53FT	(WA04MHX)

Poke {J & V Coaches}, Stromness	SN		FE 02 FBN	Vo	B10M-62	YV31MA7141A053567	Pn	0112VUL3957	C53F	(FE02FBN/MNZ9302/FE02FBN/A 16HNS)
Poke {J & V Coaches}, Stromness	SN		FJ 58 LSE	Vo	B12B	YV3R8L2278A126346	Je	28550	C49FT	(ex GSU 390, FJ 58 LSE)
Poke {J & V Coaches}, Stromness	SN		J 60 JXR	Vo	B10M-62	YV3R9F8122A000514	Ssd	B-2254	C49FT	(ex SF 02 NCM, 9396 WW)
Poke {J & V Coaches}, Stromness	SN		LX 03 HEJ	MB	O530G	WEB62824323102617	MB		AB49T	
Poke {J & V Coaches}, Stromness	SN		LX 03 HEU	MB	O530G	WEB62824323192625	MB		AB49T	
Poke {J & V Coaches}, Stromness	SN		P245 AUT	Vo	B10M-62	YV31MA610VA046848	Je	24454	C55F	(P245AUT/HIL4376/P245AUT/VUN421)
Poke {J & V Coaches}, Stromness	SN		PO 54 NAA	MAN	18.360	WMAA51ZZZ3S001532	Mpo	952	C49FT	(PO54NAA/VUN421)
Poke {J & V Coaches}, Stromness	SN		R309 JAF	Vo	B10M-62	YV31MA610WC060898	Pn	9812VUP8792	C44FT	
Poke {J & V Coaches}, Stromness	SN		SF 05 NRY	Ba	FHD12-340	XL9AA18P531003905	Ba		C49FT	(SF05NRY/7921AT)
Poke {J & V Coaches}, Stromness	SN		SJ 51 LPA	Sca	L94UA	1840178	Wt	E274	AB58D	(ex JIB 2987, SJ 51 LPA)
Poke {J & V Coaches}, Stromness	SN		SN 12 EAP	MB	516CDI	WDB90665725547093	UNVI		C16F	
Poke {J & V Coaches}, Stromness	SN		SN 54 FNE	MB	1018	WDB9702472K889390	UNVI	33829	C33F	(SN54FNE/UGE471)
Poke {J & V Coaches}, Stromness	SN		SX 57 LBP	Vo	B7R	YV3R6K6267A120255	Ssd	B-4300	C53F	(ex 08-C-208)
Poke {J & V Coaches}, Stromness	SN		SX 57 LBU	Vo	B7R	YV3R6K6287A120256	Ssd	B-4301	C53F	(ex 08-C-308)
Poke {J & V Coaches}, Stromness	SN		SY 59 CBF	Fd	Tt	WF0DXXTTFD9K09967	Fd		M16	
Poke {J & V Coaches}, Stromness	SN		SY 59 CBO	Fd	Tt	WF0DXXTTFD9K09987	Fd		M16	
Poke {J & V Coaches}, Stromness	SN		T 4 APT	Vo	B10M-62	YV31MA61XXA050408	VH	33526	C48FT	
Poke {J & V Coaches}, Stromness	SN		WV 02 EUT	Vo	B12M	YV3R9H4141A000188	Pn	0212.8TZT4208	C49FLT	(ex A 17 EBD, WV 02 EUT)
Poke {J & V Coaches}, Stromness	SN		YN 57 AAK	Ibs	397E.12.43A	ZGA7B2S100E002702	Bs	06.019	C49FT	(YN57AAK/SAM 11B/FIL 725)
Portsoy Taxis, Portsoy	SN		SP 57 ENR	Rt	Mtr	VF1PDM1L638348166	?		M16	
Premier Coaches, Kintore	SN		BX 04 VKL	MB	413CDI	WDB9046632R505400	Cym/Excel		M16	
Premier Coaches, Kintore	SN		EY 58 UMD	Fd	Tt	WF0DXXTTFD8K47071	Fd		M16	
Premier Coaches, Kintore	SN		F904 YNV	Vo	B10M-60	YV31MGD12KA020172	Je	21173	C51FT	
Premier Coaches, Kintore	SN		PK 02 PUJ	Ds	R410	SFD112BR11GC10153	Pn	0212GWT4661	C70F	(ex UJL 270, PK 02 PUJ)
Premier Coaches, Kintore	SN		SF 03 AMV	MB	O814D	WDB6703732N106222	Essbee		C24F	(SM03AFV/S 445BN)
Premier Coaches, Kintore	SN		SF 04 WMY	Ba	FHD13-340	XL9AA38P431003339	Ba		C55F	(SF04WMY/NX03MCL)
Premier Coaches, Kintore	SN		SF 17 EDL	VDL	FHD2 129	XNL501E100D006167	VDL		C53F	
Premier Coaches, Kintore	SN		SN 13 DAU	MB	O816D	WDB6703742N147019	UNVI	-?-	C25F	
Premier Coaches, Kintore	SN		SN 13 DCF	MB	515CDI	WDB90665525727337	UNVI	-?-	M15	
Premier Coaches, Kintore	SN		SN 17 BKX	MB	1527L	WDB9670272L978567	UNVI	-?-	C37F	
Premier Coaches, Kintore	SN		SN 17 BKY	Io	70C18	ZCFC270D805136892	?		C24F	
Premier Coaches, Kintore	SN		SN 17 BKZ	MB	1024L	WDB96702420420117	UNVI	-?-	C29F	
Premier Coaches, Kintore	SN		SN 65 AAF	MB	516CDI	WDB90665725890803	?		C22F	
Premier Coaches, Kintore	SN		WX 54 PXC	MB	413CDI	WDB9046122R693782	UVM	10144	B16FL	
Premier Coaches, Kintore	SN		Y329 CFS	MB	413CDI	WDB9046632R149557	Onyx	442	M16	(Y329CFS/B 16DNY)
Premier Coaches, Kintore	SN		YG 17 SSV	Ytg	TC12	LZYTMTF63G1076674	Ytg		C51F	
Premier Coaches, Kintore	SN		YG 17 SUY	Ytg	TC9	LZYTCTE65G1031692	Ytg		C35F	
Premier Coaches, Kintore	SN		YN 08 OCJ	Sca	K340EB4	YS2K4X20001860532	Ir	104647	C49FT	

Premier Coaches, Kintore	SN		YN 13 AWC	MB	O816D	WDB6703742N147393	Pn	DC09/01	C29F	
Priest & Thomson {P&T Coaches}, Baltasound	SN		EO 66 DZY	Fd	Tt	WF0HXXTTGHGC67894	Fd		M16	
Priest & Thomson {P&T Coaches}, Baltasound	SN		LEZ 3362	Vo	B10M-60	YV31M3D17RA040646	Pn	9412VUS2266	C48FT	(L921NWW/3333WA/L188SUB)
Priest & Thomson {P&T Coaches}, Baltasound	SN		R190 SUT	Vo	B10M-62	YV31MA619VC060459	Je	24581	C49FT	(R190SUT/R555GSM)
Priest & Thomson {P&T Coaches}, Baltasound	SN		R924 DPS	Vo	B10M-48	YV31MA518WA048172	Pn	9710VMM7254	C45F	
Priest & Thomson {P&T Coaches}, Baltasound	SN		SF 05 BBE	MB	O814D	WDB6703742N117493	Pn	048.5MAE5768	C33F	
R										
Ratray {Woodlands Service Centre}, Grantown-on-Spey	SN		R 1 MNK	Fd	Tt	WF0EXXGBFE2Y05698	Fd		M14	(SD52GYU)
Ratray {Woodlands Service Centre}, Grantown-on-Spey	SN		SY 10 VPV	Fd	Tt	WF0BXXBDFBAY64190	Fd		M8	
Ratray {Woodlands Service Centre}, Grantown-on-Spey	SN		SY 12 THV	Fd	Tt	WF0DXXTTFD9C60623	Fd		M16	
Reid, Newmachar	SN		HF 04 GXK	MAN	18.350	WMAA51ZZ64S002054	Noge	N-5456	C53F	
Reid, Newmachar	SN		SF 11 DYC	MB	O816D	WDB6703742N140900	Pn	108.5MBJ8714	C??F	
Reid, Newmachar	SN		YG 07 WSM	Tmsa	Opalin	NLTHNJ45R01000011	Tmsa		C35F	(YG07WSM/M 77YEL/M 30YEL)
Reid, Newmachar	SN	(r)	YJ 57 BTO	Tmsa	Opalin	NLTHNJ45R01000002	Tmsa	MA03709	C35F	(ex RO 06 ART, YJ 57 BTO)
Reid, Rhynie	SN		EXZ 4294	Fd	Tt	WF0SXXBDFS8Y30068	Fd		M12	(DU09BFL)
Reid, Rhynie	SN		EXZ 4296	Fd	Tt	WF0DXXTTFD9C68023	Fd		M15	(FG59DPE)
Reid, Rhynie	SN		GX 63 DDV	Fd	Tt	WF0DXXTTFD9C68023	Fd		M16	
Reid, Rhynie	SN		LM 62 NLA	Fd	Tt	WF0DXXTTFD9C68023	Fd		M16	
Reid, Rhynie	SN		N??? ???	Vo	B10M-62	042470	Co	458039	C49FT	(N 83LSE/HSK816)
Reid, Rhynie	SN		RX 16 CRV	Rt	Mtr	VF1MEN4VE53046873	?		M16	
Reid, Rhynie	SN		YD 62 OLW	Fd	Tt	WF0DXXTTFD9C68023	Fd		M16	
Reid, Rhynie	SN		YT 13 BNV	Fd	Tt	WF0DXXTTFD9C68023	Fd		M16	
Robertson, Cuminstown	SN		FV 05 XWU	Fd	Tt	WF0EXXTTFF5B15910	Fd		M16	
Robertson, Cuminstown	SN		G109 GOG	MB	408D	WDB6110682P003556	DC	171M	M12	
Robertson, Ulsta	SN		B 10 HWH	Vo	B10M-62	YV31MA7131A053267	VH	33628	C53F	(Y617NYD/971CYB/Y617NYD)
Robertson, Ulsta	SN		B 12 HWH	Vo	B12M	YV3R9F8226A110171	VH	33994	C53FT	(SB06MSB)
Robertson, Ulsta	SN		M 17 SCR	MB	513CDI	WDB9061552N629865	IM	-?-	C19F	
Robertson, Ulsta	SN	(x)	M 19 SCR	VW	Tr	WV2ZZZ7HZAH23857	?		M8	(SK10ZPS)
Robertson, Ulsta	SN		M 66 SCR	MB	516CDI	WDB9066572S858229	EVM		C19F	
Robertson, Ulsta	SN		SF 65 CZR	MB	1021L	WDB9670242L927073	Ind	8600	C32F	
Robertson, Ulsta	SN		SF 66 NPC	MB	1021L	WDB9670242L060810	Ind	9042	C33F	
Robertson, Ulsta	SN		SJ 16 CRX	Vo	B8RLE	YV3T7U522GA173969	MCV	602	B46F	
Robertson, Ulsta	SN		SJ 16 CRZ	Vo	B8RLE	YV3T7U529GA173970	MCV	603	B46F	
Robertson, Ulsta	SN		T 13 SCR	MB	O816D	WDB6703732N123200	KVC		C24F	(YN57DVZ)
Robertson, Ulsta	SN		WX 08 AYG	MB	O813D	WDB6703742N128903	LCB	6512	B32FL	
Robertson, Ulsta	SN		YN 13 EHM	MB	O816D	WDB6703742N147993	IM	CCA469	C33F	
Robinson Transport, Weisdale	SN		R 20 TPT	MB	516CDI	WDB9066572P341212	?		C19F	
Robinson Transport, Weisdale	SN		R 30 TPT	MB	516CDI	WDB9066572S910607	EVM		C22F	
Robinson Transport, Weisdale	SN		SK 52 OCW	MB	O814D	WDB6703742N105578	Pn	028.5MXV4881	C33F	
Robinson Transport, Weisdale	SN		UKZ 8149	Vo	B10M-48	YV31M2F15TA045147	VH	32609	C53F	(P 9WAC/LDD488/P523EAB)
Robinson Transport, Weisdale	SN		VX 07 GYW	MB	O814D	WDB6703742N127411	Me	4468	C33F	
Robinson Transport, Weisdale	SN		WE 15 DLE	MB	921L	WDB9670232L975801	Erduman	-?-	C33F	
Roe {Vale Taxis}, Banff	SN		VT 03 ROE	Rt	Mtr	VF1NDD2L639787034	Rt		M??	(ex SH 08 CBF, SF 08 OJM)
Rosie {Causeway Cars}, St Margarets Hope	SN	(x)	SY 55 CPK	Fd	Tt	WF0TXXBDF5K74976	Fd		M8	
Ross {Lochcarron Garage}, Strathcarron	SN		FR 13 XBD	Fd	Tt	WF0DXXTTFD9C68023	Fd		M16	

Ross {Lochcarron Garage}, Strathcarron	SN		FY 62 ZTO	Fd	Tt	WF0DXXTTFDCCD21054	Fd		M16	
Ross {Lochcarron Garage}, Strathcarron	SN		SH 06 PVD	Fd	Tt	WF0EXXTTFE6Y20675	Fd		M14	
Ross {Lochcarron Garage}, Strathcarron	SN		SY 51 EBN	Rt	Mtr	VF1PDMCL524225606	Me	11211	M16	
Ross, Beaully	SN		BD 03 XZB	Fd	Tt	WF0EXXGBFE3E43800	Fd		M14	
Ross, Beaully	SN		BU 04 UTN	MB	413CDI	WDB9046632R603106	Koch		B16F	
Ross, Beaully	SN		L256 YOD	MB	709D	WDB6690032N013597	Pn	937.6MHV1717	B25F	
Ross, Beaully	SN	(r)	L899 LFS	MB	609D	WDB6680632N005476	Onyx		C24F	
Ross, Beaully	SN		MX 55 ZRF	Io	35C12	ZCFC408100D284195	?		M16	
Ross, Beaully	SN		PN 06 TVF	Io	65C17	ZCFC65C0005539967	Ind	5810	C22F	
Ross, Beaully	SN		SF 06 ODU	MB	O814D	WDB6703742N117954	Pn	058.5MXV6076	DP29FL	
Ross, Beaully	SN		X 42 SRM	MB	O814D	WDB6703742N090159	Pn	008.5MXV2824	B31F	
S										
Safedrive Taxis, Laurencekirk	SN		FJ 58 FLD	Io	45C15	ZCFC45A200D396893	Excel		M16L	
Safedrive Taxis, Laurencekirk	SN		YP 09 KXW	Fd	Tt	WF0DXXTTFD8Y33913	Fd		M16	
Safedrive Taxis, Laurencekirk	SN		YP 09 XTC	Fd	Tt	WF0DXXTTFD9J64267	Fd		M16	
Sanday Enterprises, Sanday	SN		SB 05 GJE	Fd	Tt	WF0EXXTTFE5M70572	Fd		M8	
Sanday Enterprises, Sanday	SN		YK 14 HGJ	Fd	Tt	WF0DXXTTFDDK77249	?		M16L	
Sands Hotel, Burray	SN		SH 56 RPX	Fd	Tt	WD0DXXTTFD6R77588	Fd		M13	(ex OO 03 JSG, SH 56 RPX)
Scalpay Minibus Committee, Scalpay	SN		RJ 60 UHN	MB	516CDI	WDB9066572S516425	EVM		M16	
Scalpay Minibus Committee, Scalpay	SN		SG 60 OTB	Fd	Tt	WF0DXXTTFDAB33052	Fd		M16	
Seaprobe Atlantis, Upper Breakish	SN		CV 60 FYR	Fd	Tt	WF0DXXTTFDAM79219	Fd		M16	
Shearer, Huntly	SN		CU 03 KDK	Fd	Tt	WF0EXXGBFE3L77652	Fd		M16	
Shearer, Huntly	SN		J100 SOH	MB	O814D	WDB6703742N113997	Pn	048.5MAE5450	C33F	(ex DEZ 6223, SN 04 HWF)
Shearer, Huntly	SN		J200 SOH	MB	O814D	WDB6703742N119828	LCB		B32FL	(ex GN 55 NVV)
Shearer, Huntly	SN		J300 SOH	VW	CrF	WV1ZZZ2EZ76016343	?		M16L	(ex YP 56 DPZ)
Shearer, Huntly	SN		J400 SOH	Fd	Tt	WF0DXXTTFDCC50449	Fd		M16	(ex YD 62 OLU)
Shearer, Huntly	SN		J500 SOH	Fd	Tt	WF0DXXTTFD7K81049	Fd		M16	(ex YH 07 OBC, 4294 CR, YH 07 OBC)
Shearer, Huntly	SN		J600 SOH	Fd	Tt	WF0DXXTTFD9E45034	Fd		M16	(ex SY 10 YPU)
Shearer, Huntly	SN		J700 SOH	VW	CrF	WV1ZZZ2EZ76033251	Verve		M15L	(ex SF 07 BNB)
Shearer, Huntly	SN		J800 SOH	VW	CrF	WV1ZZZ2EZ86004425	Verve		M15L	(ex SJ 57 BWM)
Shearer, Huntly	SN		KN 04 JBX	Fd	Tt	WF0EXXGBFE3M40623	Fd		M16	
Shearer, Huntly	SN		NA 06 BWH	Fd	Tt	WF0EXXTTFE6Y05501	Fd		M16	
Shearer, Huntly	SN	(x)	R245 JHS	Fd	Tt	WF0EXXBDVEWJ43769	Fd		M8	
Shearer, Huntly	SN	(r)	S 16 AMC	MB	O814D	WDB6703742N074288	Pn	988.5MXV9593	DP31F	
Shearer, Huntly	SN		SD 52 YRF	Fd	Tt	WF0EXXGBFE2R87888	?		M16	
Shearer, Huntly	SN		SJ 53 LTU	Fd	Tt	WF0EXXGBFE3Y11419	Fd		M16	
Shearer, Huntly	SN		WU 05 XDG	Fd	Tt	WF0EXXTTFE5U35178	Fd		M16	
Shearer, Huntly	SN		X224 USC	MB	O814D	WDB6703742N087935	Pn	008.5MXV2418	C33F	
Shetland Islands Council, Lerwick	SN		OE 51 YKD	Rt	Mtr	YS54RA45R11500168	Omninova		B13F	
Shetland Islands Council, Lerwick	SN		OY 02 YHB	Rt	Mtr	YS54RA45R11500169	Omninova		B13F	
Shetland Islands Council, Lerwick	SN		SP 57 JCY	Vo	B7RLE	YV3R6K6298A123121	Pn	0712TGA7339	B42F	(T 30JLS)
Shetland Islands Council, Lerwick	SN		SP 57 JCZ	Vo	B7RLE	YV3R6K6278A123151	Pn	0712TGA7340	B42F	(T 40JLS)
Shetland Islands Council, Lerwick	SN		X161 NPS	MB	O814D	WDB6703742N090161	Pn	008.5MXV3132	B29FL	

Shetland Islands Council, Lerwick	SN		YJ 59 NNE	Oe	M780SE	SABDN2AB09L193540	Oe		B??F	
Shetland Islands Council, Lerwick	SN		YJ 59 NNF	Oe	M880	SABEW3AF09L193566	Oe		B??F	
Shetland Islands Council, Lerwick	SN		YJ 60 KFY	Oe	M810SL	SABDN3AF0AL193708	Oe		B??F	
Shetland Islands Council, Lerwick	SN		YJ 60 KFZ	Oe	M810SL	SABDN3AF0AL193709	Oe		B??F	
Shetland Islands Council, Lerwick	SN		YJ 65 ERU	Oe	M960SR	SABNDD1A7FS291213	Oe		B27F	
Shetland Islands Council, Lerwick	SN		YN 10 AEA	MB	O816D	WDB6703742N138598	Pn	098.5MBJ8476	C33F	(ex J 50 JFJ, YN 10 AEA)
Shetland Islands Council, Lerwick	SN		YU 04 XHZ	MB	O814D	WDB6703742N113729	Pn	048.5MXW5471	DP29FL	
Shetland Islands Council, Lerwick	SN		SV 11 BYH	Io	50C15	ZCFC50A2005727078	Me	5091	M13L	
Shetland Islands Council, Lerwick	SN		SV 11 BYJ	Io	50C15	ZCFC50A2005751117	Me	5121	M11L	
Shiel Buses, Acharacle	SN		FNZ 2300	Vo	B10M-62	YV31M2B16TA044238	VH	32294	C49FT	(HSK644/N445PYS/M 4WMT/N445PYS)
Shiel Buses, Acharacle	SN		HSK 735	Vo	B10M-46	YV31MGC16LA024387	VH	30432	C42FT	(H251XDS)
Shiel Buses, Acharacle	SN		JIL 3961	MB	O816D	WDB6703742N134942	UNVI	-?-	C29F	(10-CN-335)
Shiel Buses, Acharacle	SN		K 10 SBL	MB	O816D	WDB6703742N125850	Pn	068.5MBE6921	C33F	(YN07KHB)
Shiel Buses, Acharacle	SN		K 20 SBL	Vo	B9R	YV3S5P723BA143484	Pn	1012.6SAA8667	C51F	(ex YN 60 BZE)
Shiel Buses, Acharacle	SN		K 22 SBL	Vo	B9R	YV3S5M1298A129086	Pn	0812.3TFR7959	C49FLT	(YN09AOK/NSU987/YN09AOK)
Shiel Buses, Acharacle	SN		K 30 SBL	Vo	B12B	YV3R8G12X7A116417	VH	38035	C51FT	(ex SR 07 SOU)
Shiel Buses, Acharacle	SN		K 33 SBL	VH	T915	YE2915SH249D53973	VH	53973	C49FT	(ex YJ 11 GGF)
Shiel Buses, Acharacle	SN		K 40 SBL	Vo	B9R	YV3S5P729DA162804	Pn	DE02/01	C51FT	(ex SG 13 RYD, KSK 981)
Shiel Buses, Acharacle	SN		K 55 SBL	MB	1524L	WDB9702782L359835	UNVI		C41F	(YN09HFF)
Shiel Buses, Acharacle	SN		K 60 SBL	Vo	B10M-62	YV31MA61XXC061316	Pn	9912VUP1234	C49FT	(Y 20BGS/VDO929/Y 20BGS)
Shiel Buses, Acharacle	SN		K 66 SBL	Vo	B12B	YV3R8G1236A110604	VH	33969	C49FT	(SP06EKA)
Shiel Buses, Acharacle	SN		K 70 SBL	MB	O813D	WDB6703742N132176	Pn	-?-	DP31FL	(ex YN 08 CWZ)
Shiel Buses, Acharacle	SN		K 77 SBL	Vo	B12B	YV3R8M92X8A124182	Pn	0712.3TMR7549	C53F	(EL57LON)
Shiel Buses, Acharacle	SN		K 80 SBL	MB	1523L	WDB9702782L099628	UNVI		C39FL	(SK07FMP)
Shiel Buses, Acharacle	SN		K 88 SBL	Vo	B11R	YV3T2U823EA165094	Pn	-?-	C53F	(ex BN 64 CNX)
Shiel Buses, Acharacle	SN		K 90 SBL	Vo	B12B	YV3R8M92X9A132400	Pn	0912.3TMR8269	C53FT	(YN60FMX)
Shiel Buses, Acharacle	SN		K 99 SBL	Ta	BB50R	TW1FG518605500619	Co	F053071009	C26F	(BX56AYF)
Shiel Buses, Acharacle	SN		K100 SBL	MB	O816D	WDB6703742N142396	UNVI	-?-	C33F	(SN12EAM)
Shiel Buses, Acharacle	SN		K200 SBL	MB	O816D	WDB6703742N145045	Pn	-?-	C29F	(ex SN 14 GNY)
Shiel Buses, Acharacle	SN		K400 SBL	Vo	B11R	YV3T2U823EA165612	Je	37217	C53FLT	(ex SD 14 YDG)
Shiel Buses, Acharacle	SN		K700 SBL	Vo	B9R	YV3S5P725EA167791	Pn	EE01/01	C49FT	(ex YY 14 NLN)
Shiel Buses, Acharacle	SN		K800 SBL	Vo	B11R	YV3T2U821EA165613	Je	37218	C53FLT	(ex SD 14 YDH)
Shiel Buses, Acharacle	SN		L 20 SBL	Vo	B7TL	YV3S2G5122A002165	Wt	F355	H43/??F	(ex LF 52 THN)
Shiel Buses, Acharacle	SN		L 30 SBL	Vo	B7TL	YV3S2G5162A002167	Wt	F357	H43/??F	(ex LF 52 THV)
Shiel Buses, Acharacle	SN		L 60 SBL	Vo	B7TL	YV3S2G5182A002168	Wt	F358	H43/??F	(ex LF 52 THX)
Shiel Buses, Acharacle	SN		L 80 SBL	Vo	B7TL	YV3S2G5285A106432	Wt	J589	H41/??F	(ex LX 05 FAO)
Shiel Buses, Acharacle	SN		L 90 SBL	Vo	B7TL	YV3S2G5205A105954	Wt	J591	H41/??F	(ex LX 05 FBA)
Shiel Buses, Acharacle	SN		RA 65 LYJ	MB	516CDI	WDB9066572P178677	EVM		M16	
Shiel Buses, Acharacle	SN		S 90 SBL	Vo	B9R	YV3S5P726CA156036	Pn	BP23/08	C53FT	(ex YN 12 CSV)
Shiel Buses, Acharacle	SN		SN 15 CDO	MB	516CDI	WDB9066572S889141	?		M16	
Shiel Buses, Acharacle	SN		T381 RFL	Fd	Tt	BDVEXE23979	?		M14	
Shiel Buses, Acharacle	SN		YG 09 YNY	MB	515CDI	WDB9066572S321116	Onyx	889	M16	
Shiel Buses, Acharacle	SN		YJ 14 BBK	Oe	M8900SR	SABSN3AF0ES290821	Oe		B31F	
Shiel Buses, Acharacle	SN		YJ 17 FVE	Oe	M9250SR	SABLD2A7HS291502	Oe		B30F	
Shiel Buses, Acharacle	SN		YN 03 LVL	MB	413CDI	WDB9046632R508576	Excel	0417	M16	
Shiel Buses, Acharacle	SN		YN 06 PCY	MB	O814D	WDB6703742N123571	Pn		C32FL	
Shiel Buses, Acharacle	SN		YN 07 NWD	MB	O814D	WDB6703732N123219	KVC		C24F	(YN07NWD/472HKE)
Shiel Buses, Acharacle	SN		YN 59 BLF	MB	O813D	WDB6703742N135214	Pn	-?-	B28FL	

Shiel Buses, Acharacle	SN		YX 14 SEO	Vo	B9R	YV3S5P726DA161027	Pn	CP56/01	C41FT	
Shiel Buses, Acharacle	SN		YY 17 GRF	AD	E20D	SFD7S1AR6HGY16036	AD	G258/05	B39F	
Shiel Buses, Acharacle	SN		YY 17 GRK	AD	E20D	SFD1RAAR6HGY16040	AD	G257/01	B29F	
Shirran, Lumsden	SN		VAV 552	Ba	FHD12-340	XL9AA18P632003580	Ba		C49FT	(ex WA 06 LZN)
Shirran, Lumsden	SN		SF 11 HVB	MB	1022L	WDB9702452L527621	Sitcar	2696	C35F	
Shirran, Lumsden	SN		SF 57 JSZ	MB	311CDI	WDB9036632R876448	Onyx	759D	M16	
Shirran, Lumsden	SN		SF 60 FRP	MB	O816D	WDB6703742N127011	?		C24F	
Shirran, Lumsden	SN		VKS 910V	Fd	R1014	BCRSUU255590	Du	921/4000	C45F	
Shirran, Lumsden	SN		Y178 KCS	Vo	B10M-62	YV31MA6191A053145	Je	25770	C49FT	(LSK555/Y178KCS/GIL1685/Y178KCS/T8DOF))
Shirran, Lumsden	SN		YX 05 AVT	MB	1223L	WDB9702582K966882	Fer	122 (OF305)	C39F	
Shirran, Lumsden	SN		YY 52 SSU	LDV	Cy	SEYZMVFGZDN087236	CSM		M16	
Simpson, Rosehearty	SN		597 KTU	Vo	B12M	YV3R9G1245A103351	Pn	0512TJL5809	C70F	(ex NH 05 FDH, MX 05 AKF)
Simpson, Rosehearty	SN		6280 RU	Vo	B12B	YV3R8G12X5A104541	VH	33949	C49FT	(ex YJ 05 XXB)
Simpson, Rosehearty	SN		FSU 335	Ba	FHD10-370	XL9AA16CGY8003121	Ba		C36FT	(ex W675 ANK, L111 KRK, W675 XNK, 9944 AT, W675 XNK, YAY 81, W675 XNK)
Simpson, Rosehearty	SN		HMU 118	Vo	B12M	YV3R9L2208A124807	Je	28566	C53F	(ex SF 08 VVE, 2767 WF, SF 08 VVE, LSK 497)
Simpson, Rosehearty	SN		YJL 693	MB	Tourino	WEB44430323000033	Co	F073051015	C28FT	(ex BN 08 OBV)
Simpson, Rosehearty	SN		GT 03 DDD	Vo	B12M	YV3R9F8133A000975	Je	26527	C53F	(ex L300 BAY, GT 03 DDD, XIL 636, GT 03 DDD)
Simpson, Rosehearty	SN		JK 15 DWO	Au	N2216SHD	-?-	Au	-?-	C49FT	
Simpson, Rosehearty	SN		JK 15 TWO	Au	N2216SHD	WAGP21Z24FT021456	Au	-?-	C49FT	
Simpson, Rosehearty	SN		PN 04 NMY	Ds	R410	SFD152BR24GC10184	Pn	0412GXT5250	C53F	
Simpson, Rosehearty	SN		SG 03 ZBM	Vo	B12M	YV3R9F81X3A001055	Je	26251	C53F	(ex L400 BAY, SG 03 ZBM, HSK 660)
Simpson, Rosehearty	SN		SM 12 SON	Au	N2216SHD	WAGP21Z21CT017537	Au	P21-1434	C49FT	
Simpson, Rosehearty	SN		SM 16 ONS	Au	N2216SHD	WAGP21Z27GT024157	Au	P21-1525	C49FT	
Simpson, Rosehearty	SN		SM 16 SON	Au	N2216SHD	WAGP21Z28FT021458	Au	P21-1597	C49FT	
Simpson, Rosehearty	SN		SM 16 SUN	Au	N2216SHD	WAGP21Z26GT024313	Au	-?-	C49FT	
Simpson, Rosehearty	SN		SM 55 SON	MB	311CDI	WDB9067332S347875	MB		M8	(ex YN 58 KVE, N 20 WAC, YN 58 KVE)
Simpson, Rosehearty	SN		YJ 03 GXL	Ba	FHD12-340	XL9AA18P230003675	Ba		C51FT	(ex SIL 9993, YJ 03 GXL)
Slater, Gott	SN		N589 JHS	LDV	400	CN965147	?		M16	
Spence {Arthur's Hire}, Birsay	SN		FA 04 FMF	LDV	Cy	SEYZMVSZGDN105412	LDV		M16	
Stables, Newmill	SN		BT 05 BJT	MB	O814D	WDB6703742N116710	Pn	058.5MAE5921	C33F	
Stables, Newmill	SN		HN 16 XNT	Fd	Tt	WF0HXTTTGHGR09389	Fd		M16	
Stables, Newmill	SN		K300 RES	Vo	B12M	YV3R9F8182A000579	Je	26244	C53F	(FJ03ABZ)
Stables, Newmill	SN		PO 60 DBU	MB	O816D	WDB6703742N140856	UNVI	1209	C33F	(PO60DBU/MCH456)
Stables, Newmill	SN		SN 13 GGK	MB	O816D	WDB6703742N148440	UNVI	-?-	C33F	
Stables, Newmill	SN		YN 56 NHK	Vo	B12M	YV3R9G1216A113496	Pn	0612TJT6619	C57F	
Stewart {RGS Motor Services}, Oldmeldrum	SN		GJ 06 BYR	Fd	Tt	WF0EXTTTFE5A59294	Fd		M16	
Stewart {RGS Motor Services}, Oldmeldrum	SN		RF 15 UKC	MB	516CDI	WDB9066572P144392	EVM		C22F	
Stewart {RGS Motor Services}, Oldmeldrum	SN		SG 12 KUJ	Fd	Tt	WF0DXTTTFDCB60435	Fd		M16	
Stewart {RGS Motor Services}, Oldmeldrum	SN		SH 13 XTB	Fd	Tt	WF0DXTTTFDDJ60789	Fd		M16	
Stewart {RGS Motor Services}, Oldmeldrum	SN		VK 06 LLZ	Fd	Tt	WF0EXTTTFE6Y15826	Fd		M16	
Sutherland {Great Glen Travel}, Invergarry	SN	(x)	K 44 GGT	VW	Tr	WV2ZZZ7HZ4X042015	VW		M8	(ex X 44 GGT, SY 04 FOC)
Sutherland {Great Glen Travel}, Invergarry	SN		SN 08 HUV	MB	515CDI	WDB9066572S280238	KVC		M16	
Sutherland {Great Glen Travel}, Invergarry	SN	(x)	X 44 GGT	VW	Tr	WV2ZZZ7HZCH042886	VW		M8	(ex SB 61 MJU)

Sutherland {Great Glen Travel}, Invergarry	SN		X444 GGT	VW	Tr	WV2ZZZ7HZ6X022081	VW		M8	(ET55BLF)
T										
Taxi 24/7, Nairn	SN		SJ 03 HMZ	MB	413CDI	WDB9046632R480754	?		M16	(SJ03HMZ/F 7BUS)
The Durness Bus, Lairg	SN		J 50 TDB	Fd	Tt	WF0DXXTTFDCS07247	Fd		M16	(ex YK 13 KXD)
The Durness Bus, Lairg	SN		J 66 TDB	Fd	Tt	WF0HXXTTGHFM14340	Fd		M16	
The Durness Bus, Lairg	SN	(x)	J 99 TDB	Fd	Tt	WF03XXTTG3FE56927	Fd		M8	
The Durness Bus, Lairg	SN		J200 TDB	Fd	Tt	WF0HXXTTGHGG48846	Fd		M16	
The Durness Bus, Lairg	SN		N 99 TDB	Fd	Tt	WF0DXXTTFD8S46941	Fd		M16	(YH09VPJ)
Tipper, Rousay	SN		GV 15 JKX	Fd	Tt	WF0HXXTTGHFL64929	Excel	-?-	M8	
Tipper, Rousay	SN		GV 15 JVN	Fd	Tt	WF0HXXTTGHFL75621	?		M14	
Tour Skye, Portree	SN		RX 16 XFH	MB	516CDI	WDB9066572S961537	EVM		M16	
U										
Urquart, Inverness	SN		SN 04 HHL	Sca	K114IB4	YS2K4X20001847444	Ir	96195	C49FT	
Urquart, Inverness	SN		SN 05 HTZ	MB	616CDI	WDB9056132R694619	UNVI		C22F	
Urquart, Inverness	SN		SY 10 BCK	Vo	B12B	YV3R8L22381128580	Vo	P083241	C49FT	
V										
Voluntary Action Training {The Red Bus / Third Sector Hebrides / Staran}, Stornoway	SN		YR 13 VBD	Fd	Tt	WF0DXXTTFDDJ61626	Fd		M16	
Voluntary Action Training {The Red Bus / Third Sector Hebrides / Staran}, Stornoway	SN		YR 13 VBG	Fd	Tt	WF0DXXTTFDDJ61699	Fd		M16	
Voluntary Action Training {The Red Bus / Third Sector Hebrides / Staran}, Stornoway	SN		DK 04 MWZ	Rt	Mtr	WDB9046632R601200	?		M12L	
Voluntary Action Training {The Red Bus / Third Sector Hebrides / Staran}, Stornoway	SN		KE 04 MWZ	MB	411CDI	WDB9046632R633159	?		M12L	
Voluntary Action Training {The Red Bus / Third Sector Hebrides / Staran}, Stornoway	SN	(x)	PN 02 LZW	VW	LT46	WV1ZZZ2DZ1H034663	?		M14	
Voluntary Action Training {The Red Bus / Third Sector Hebrides / Staran}, Stornoway	SN	(x)	PN 02 ZKJ	Fd	Tt	WF0EXXGBFE1G66721	Fd		M16	
Voluntary Action Training {The Red Bus / Third Sector Hebrides / Staran}, Stornoway	SN		SF 06 BFE	Io	50C14	ZCFC50A1005552549	Allied, Glasgow		M15L	
Voluntary Action Training {The Red Bus / Third Sector Hebrides / Staran}, Stornoway	SN		SO 55 LXB	Fd	Tt	WF0EXXTTFESK22393	Fd		M16	
Voluntary Action Training {The Red Bus / Third Sector Hebrides / Staran}, Stornoway	SN		SY 05 CKP	MB	313CDI	WDB9036632R768199	?		M16	(SY05CKP/C 10SCL)
Voluntary Action Training {The Red Bus / Third Sector Hebrides / Staran}, Stornoway	SN	(x)	SY 54 BZC	VW	LT46	WV1ZZZ2DZ5H008780	?		M14L	
Voluntary Action Training {The Red Bus / Third Sector Hebrides / Staran}, Stornoway	SN		SY 58 CMO	MB	515CDI	WDB9066552S366950	Cpt		M16	(JSK275/SY58CMO/C 1SCL)

Voluntary Action Training {The Red Bus / Third Sector Hebrides / Staran}, Stornoway	SN	(x)	VK 14 RXD	Ctn	Rly	VF7YDTMFC12595568	?		M8L	
Voluntary Action Training {The Red Bus / Third Sector Hebrides / Staran}, Stornoway	SN	(x)	W531 OJS	Rt	Mtr	VF1FDCEL522442927	?		M14	
Voluntary Action Training {The Red Bus / Third Sector Hebrides / Staran}, Stornoway	SN		SF 64 CJX	MB	513CDI	WDB9066552S927967	?		M16L	
W										
Wastbus, Bixter	SN		AD 56 LSV	Fd	Tt	WF0DXXTTFD6A26533	Fd		M16	
Wastbus, Bixter	SN		RX 14 AFU	MB	516CDI	WDB9066572S914367	EVM		C22F	
Wastbus, Bixter	SN		SV 56 KKJ	MB	O814D	WDB6703742N124462	Pn	-?-	C33F	(ex J 50 JFJ)
Watermill Coaches, Fraserburgh	SN		BS 8362	MB	O814D	WDB6703742N110051	Pn	038.5MAE5262	C33F	(ex YN 53 EJC)
Watermill Coaches, Fraserburgh	SN		FXZ 8492	VDL	FHD2-129	XNL501E100D002803	VDL		C??F	
Watermill Coaches, Fraserburgh	SN		H 11 ARB	MB	O815D	WDB6703742N106254	Sitcar	1829	C33F	(ex SN 03 TOA)
Watermill Coaches, Fraserburgh	SN		IB 9996	Ba	FHD127.365	XL9AA38R834003244	Ba		C55F	(ex YJ 09 FJA)
Watermill Coaches, Fraserburgh	SN		UOO 809	DAF	SB4000	XMGDE40XS0H010994	VH	37081	C49FT	(ex YJ 04 BYB)
Watermill Coaches, Fraserburgh	SN		BS 4279	MB	O815D	WDB6703742N112948	Sitcar	2014	C33F	(SV54EPJ)
Watermill Coaches, Fraserburgh	SN		BX 64 AEO	KL	XMQ6900	LA6R1DSE2DB105353	KL		C33FT	
Watermill Coaches, Fraserburgh	SN		FJ 05 XYS	MB	O814D	WDB6703742N116852	Pn	058.5MXW5985	B32FL	
Watermill Coaches, Fraserburgh	SN		HN 64 SWK	Rt	Mtr	VF1MEN4VE51942147	?		M16	
Watermill Coaches, Fraserburgh	SN		HSV 725	Vo	B12M	YV3R9F8275A103716	Pn	0512JT5867	C53F	(GO05WMS/NT05MXL)
Watermill Coaches, Fraserburgh	SN		J999 BER	MB	O816D	WDB6703742N134775	Pn	088.5MBJ7936	C33F	(ex KX 08 UXG, JIG 2100, KX 08 UXG)
Watermill Coaches, Fraserburgh	SN		JR 13 AAA	VDL	FHD2-129.365	XNL501E100D001613	VDL		C57F	
Watermill Coaches, Fraserburgh	SN		LAZ 9205	Ba	FHD13-340	XL9AA38P431003283	Ba		C55F	(SF04WMX/NX04MCL/SF04WMX)
Watermill Coaches, Fraserburgh	SN		M 8 SKY	Ds	Jv	SFD213BR3TGJ11825	WS	5448/96	C57F	(?/P492LSR)
Watermill Coaches, Fraserburgh	SN		M304 YWE	Ds	Jv	12SDA2152/1262	WS	4957/95	DP70F	(ex J999 BER, M304 YWE, EC 51 AA)
Watermill Coaches, Fraserburgh	SN		M783 ASL	Ds	Jv	12SDA2152/1254	WS	4954/95	DP70F	(EC48AA)
Watermill Coaches, Fraserburgh	SN		M808 ASL	Ds	Jv	12SDA2152/1230	WS	4946/95	DP70F	(00RN45/M808ASL/FSU393)
Watermill Coaches, Fraserburgh	SN		M823 ASL	Ds	Jv	12SDA2152/1229	WS	4945/95	DP70F	(00RN44/M823ASL/FSU395)
Watermill Coaches, Fraserburgh	SN		MX 06 GVG	MB	614D	WDB6683222N121134	Me	4258	B15FL	
Watermill Coaches, Fraserburgh	SN		MX 55 HXP	MB	O814D	WDB6703742N118672	Onyx	730	C24F	
Watermill Coaches, Fraserburgh	SN		N 5 BUS	Ba	FHD10-340	XL9AA16P330003762	Ba		C36FT	(WA03HRK/WSV478/WA03HRK)

Watermill Coaches, Fraserburgh	SN		N 30 BUS	Vo	B10M-48	YV31M2F19TA045149	VH	32611	C38FT	(97-KY-1022/P133FTA/MJI6060/P133FTA)
Watermill Coaches, Fraserburgh	SN		N 87 FHL	Ds	Jv	10SDA2156/1469	WS	5150/95	C49F	(?)
Watermill Coaches, Fraserburgh	SN	(w)	OSN 866Y	Vo	B55-10	82246	EL	A3706	H48/36F	
Watermill Coaches, Fraserburgh	SN		P971 HWF	Ds	Jv	SFD531BR3TGJ61553	Au	5001600	C49FT	(ex RIB 3929, P971 HWF)
Watermill Coaches, Fraserburgh	SN	(x)	R 43 ALS	Fd	Tt	WF0EXXBVDEWL18912	Fd		M8	
Watermill Coaches, Fraserburgh	SN		R888 WCS	Vo	B10M-62	YV31MA612VA047449	Pn	9712VUM6755	C70F	(R651RSE)
Watermill Coaches, Fraserburgh	SN	(p)	RRS 46R	Ld	PSU3E/4R	7606373	Du	734/5350	C49F	
Watermill Coaches, Fraserburgh	SN	(w)	SA 52 CTF	Ba	FHD12-340	XL9AA18P230003198	Ba		C49FT	(SA52CTF/MIL7795/SA52CTF/LAZ9205)
Watermill Coaches, Fraserburgh	SN		SC 03 CXE	Pt	Bxr	VF7ZCRMNC17235407	?		M8L	
Watermill Coaches, Fraserburgh	SN		SC 62 WGC	MB	516CDI	WDB9066572S695883	UNVI	-?-	C22F	
Watermill Coaches, Fraserburgh	SN		SF 04 EKU	MB	O814D	WDB6703742N114322	Pn	048.5MXW5455	B32FL	
Watermill Coaches, Fraserburgh	SN		SF 07 NLZ	Ba	FLD120.365	XL9AA12R733003310	Ba		C70F	(ex X 13 OVA, SF 07 NLZ)
Watermill Coaches, Fraserburgh	SN		SF 54 CHO	MB	O814D	WDB6703742N115342	Pn		DP33F	
Watermill Coaches, Fraserburgh	SN		SK 52 OGU	Ds	Tt	SFD54EBR22GX32412	Pn	7971	H51/32F	
Watermill Coaches, Fraserburgh	SN		SN 03 OAE	MB	O814D	WDB6703732N106522	KVC		C24F	(SN03OAE/C 9WGC)
Watermill Coaches, Fraserburgh	SN		SN 12 DWA	Ba	FHD127.365	XL9AA38RC35003135	Ba		C53DLT	(ex P 8 OVA, SN 12 DWA)
Watermill Coaches, Fraserburgh	SN		SN 13 DDA	MB	O816D	WDB6703742N146877	UNVI	-?-	C33F	
Watermill Coaches, Fraserburgh	SN		SN 13 GGJ	MB	O816D	WDB6703742N148442	UNVI	-?-	C33F	
Watermill Coaches, Fraserburgh	SN		SN 51 AYG	Ds	Tt	SFD344BR216GX21524	Pn	7470	H47/25D	
Watermill Coaches, Fraserburgh	SN		SN 51 AYM	Ds	Tt	SFD344BR216GX21529	Pn	7475	H47/25D	
Watermill Coaches, Fraserburgh	SN		SN 60 AOX	Ba	FHD120.365	XL9AA18RA34003781	Ba		C49FT	
Watermill Coaches, Fraserburgh	SN		SN 60 AOY	Ba	FHD120.365	XL9AA18RA34003778	Ba		C49FT	
Watermill Coaches, Fraserburgh	SN	(x)	SV 05 ZKT	Fd	Tt	WF0EXXTTFE5R25954	Fd		M8	
Watermill Coaches, Fraserburgh	SN	(x)	SV 05 ZPP	Fd	Tt	WF0EXXTTFE5R25958	Fd		M8	
Watermill Coaches, Fraserburgh	SN		T111 WCS	Vo	B12M	YV3R9F8112A000391	Pn	0112VUT4544	C51FT	(SD03SOU)
Watermill Coaches, Fraserburgh	SN		TIB 5004	Vo	B10M-62	YV31MA615VA046490	Co	658101	C70F	(R550MSS/HSK815/R550MSS/R 9WGC/R550MSS)
Watermill Coaches, Fraserburgh	SN		VU 06 XKX	MB	O814D	WDB6703742N122524	Pn	058.8MXC6460	C33F	
Watermill Coaches, Fraserburgh	SN		VX 57 GYT	MB	O814D	WDB6703742N124528	Pn	078.5MXC6937	C33F	

